

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

VEHICLE NO : SHC 2800J

DATE 5/12/2017 10:42

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X repair</i>			\$ 578.40
	Rear Bumper Reinforcement <i>X</i>			\$ 483.30
	Rear Bumper Clip <i>X</i>			\$ 22.00
	Rear Bumper Sponge <i>X</i>			\$ 137.40
	Rear Bumper Under Cover <i>X</i>			\$ 185.80
	<b>SUB TOTAL</b>			<b>\$ 1,406.90</b>
	<b>LESS 20%</b>			<b>\$ 281.38</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,125.52</b>
	<b>Labour Charge</b>			<i>100</i>
	Panel Beating			\$ <del>350.00</del>
	Spray Painting Charge			\$ <del>200.00</del>
				<i>180</i>
	<b>TOTAL LABOUR</b>			<b>\$ 550.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 1,675.52</b>

*Kalua 16/1/14*  
*5/12/17 1445hrs*  
*2017*  
*43*  
*After Repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Pans prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company.

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.