

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKN 357S

TP - AXA

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department \ THE MOTOR

Estimate No: ES1791462/WS

Date: 02 Jan 2018

Policy No: 5080622694-01

Veh Reg No: SKN357S

Make/Model: NISSAN ALMERA 1.5
5MT AIRBAG 2WD 4DR

Chassis No: MNTBBAN17Z0005592

Engine No: HR15929323D

Reg. Date: 30/05/2016

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 30/11/2017

TP Veh Reg No: SJT91M

Estimate Repair Cost to Vehicle No :SKN357S

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 FRONT BUMPER CLIPS	2.60	6 PC	15.60	15.60
		Less 10%	1.56	14.04
Special Net				
2 FRONT BUMPER	256.90	1 PC	256.90	256.90
3 FRONT BUMPER RH SIDE RETAINER	35.20	1 PC	35.20	35.20
4 RH HEAD LAMP	298.00	1 PCS	298.00	298.00
			590.10	590.10
Labour				
5 REMOVE AND REFIX FRONT BUMPER ASSY, HEAD LAMP. TO KNOCK AND REPAIR FRONT RH FENDER AND REALIGN THE SAME	380.00	1 LA	380.00	380.00
6 PUTTY AND RESPRAY ON FRONT RH FENDER, FRONT BUMPER AND AFFECTED AREA	450.00	1 LA	450.00	450.00
			830.00	830.00
			Total	S\$ 1,434.14
			Add GST @ 7%	100.39
			Total Amount Payable	S\$ 1,534.53

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE