

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
SOM	SOMPO INSURANCE SINGAPORE PL			CS3/SMO17023176	/Wbe2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623				05-04-2018		
			Code:	SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	FBF 6977D	Veh. Inspected		PC 4232R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD1704281/NSW	Excess (\$)		0.00	
	Assign From	SHERY WONG	Assign Date		06/12/2017	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HIACE	c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	JTFST22PX00022715	Colour		SILVER	
	Odometer	56473 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
	Size Make			Balance		
	R/H Front Tyre	195 R15C	JK TYRE		3 mm	
	L/H Front Tyre	195 R15C	JK TYRE		3 mm	
	R/H Rear Tyre	195 R15C	JK TYRE		4 mm	
	L/H Rear Tyre	195 R15C	JK TYRE		4 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S			PORTION.		
5.	. General Information					
	Accident Date	06/12/2017	Inspec	t Date / Time	15/12/2017 ( 12:00 PM )	
	Survey held at	Survey held at SHENG LI LAI				
	2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,600-\$5,600					
5b. Estimate Days of Repair						
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/SMO17023176/Wbe2

Inspected By

WILSON TEO CHENG MING

**Automotive Assessor** 

K.K.LAU CPT(RET)

**REGD Auto Consultant-SAE, Licensed Appraiser** 

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.