

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 20014

Date : 06.12.2017

Vehicle Num : SKN6886S

Make/Model : BMW 320i

Chassis/Engine no :

Accident Date : 05.12.2017

Claim No : 1217-20014

Not Admitted
LKR
d/s 4300
5/12/17
3 day

Qty	Particular	Amount S\$
-----	------------	------------

List Item :

1 pc Front Bumper	958.80	Deep cut	\$	1,315.00 ✓
1 pc Front Bumper side retainer	ALS	Scr	\$	62.00 ✓
1 set Front Bumper clip		ner	\$	50.00 ✓
1 pc Front Bumper fog lamp	ALS	11	\$	295.00 X
1 pc Front fender	ALS	body	\$	525.00 ✓
1 pc Front fender inner shield	ALS	horn	\$	126.00 ✓
1 set Front fender inner shield clip	ALS	ner	\$	50.00 ✓
1 pc headlamp	ALS	holder cro	\$	2,400.00 ✓
1 pc Front shock absorber	ALS	11	\$	695.00 X
1 pc Front knuckle arm	ALS	11	\$	922.00 X
1 pc Front knuckle arm bearing	ALS	11	\$	328.00 X
1 pc Front lower arm	ALS	11	\$	450.00 X
1 pc Front sport rim 19 inch	ALS	cut	\$	1,200.00 ✓
List item total :			\$	8,418.00

Labour Charge :

To check wiring	\$ 20	50.00
To spray rust proofing	\$ 30	50.00
To conduct wheel alignment	\$ 80	100.00
To dismantle & replacing front undercarriage	\$ 11	180.00 X
To spray painting and etc	\$ 400	800.00
To remove and replace spare part and panel beating	\$ 300	500.00
Labour Charge Total:	\$	1,680.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5392.77