

RONG SHENG AUTO ENGINEERING TRADING

NO 42 TOH GUAN ROAD EAST

01-79 ENTERPRISE HUB

SINGAPORE 608583

TEL : 9239 9009

REG NO : 53181821K

Tang Jiah 97495749
7/12/17 @ 1020

Compsum

Resurvey after repair

3 days

See @ Market.com

QUOTATION/ESTIMATE

VEHICLE NO : SKQ1440L

RE: REPAIR VEHICLE ON MITSUBISHI ASX

DATE : 06/12/2017

TO: Direct Asia Insurance

REFER NO : RSA/2017/12/ 0010

PARTS DESCRIPTI

NETT ITEMS

	QTY	UNTIL PRICE	AMOUNT
1 REAR BUMPER	1	\$830.00	\$830.00 de
2 REAR BUMPERB REINFORCEMENT	1	\$230.00	\$230.00 - photo?
3 REAR BUMPER BRACKET LH	1	\$54.00	\$54.00 ?
4 REAR BUMPER SIDE RETAINER LH	1	\$44.00	\$44.00 per ✓
5 REAR BUMPER CLIPS	4	\$3.90	\$15.60 aer -

TOTAL :	\$1,161.90	\$1,173.60
LESS 10 %	\$116.19	\$117.36
TOTAL :	\$1,045.71	\$1,056.24

TOTAL SPARE PARTS :	\$1,045.71	\$1,056.24
---------------------	------------	------------

LABOUR DESCRIPTION

AMOUNT

1 LABOUR FOR PANEL BEATING - photo end panel & reinforcement	\$600.00 \$300
2 LABOUR FOR SPRAYPAINTING	\$500.00 300
3 TO RUST PROOF ON FRONT RH ACCIDENT AREAS	\$200.00 400
4 WIRING	\$80.00 30

TOTAL LABOUR :

\$1,380.00

TOTAL PARTS AND LABOUR :

\$2,436.24



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices must be given for confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal TOTAL PARTS AND LABOUR :
- Supplementary work must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date: