

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : SJV6921T Case Owner : ANIKKA

Make & Model : TOYOTA VIOS E AUTO Year Manufacture : 2009

Chassis No : MR053HY9305153079 Engine No : 1NZY045268

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposit Surveyo
1	RHR DOOR <i>Painted</i>	1		\$856.60	✓		
2	RHR DOOR MOULDING <i>Painted</i>	1		\$120.92	✓		
4	RHR DOOR LOCK <i>New</i>	1		\$487.65	X		
5	RHR QUATER PANEL <i>Painted</i>	2		\$987.90	X		
6	RH ROCKER PANEL (OUTER) <i>New</i>	1		\$587.70	+		
7	RHR FENDER INNER SHIELD <i>New</i>	1		\$85.50	✓		
8	RHR DOOR MOTOR <i>New</i>	1		\$30.00	X		
9	RHR DOOR REGULATER <i>New</i>	1		\$679.80	X		
10	RHR DOOR TRIM BOARD <i>New</i>	1		\$127.90	X		
11	RHR DOOR HANDLE <i>New</i>	1		\$514.70	+		
12	RHR DOOR WEATHER STRIP <i>cut</i>	1		\$109.80	✓		
13	RHR DOOR GLASS <i>New</i>	1		\$255.14	+		
14	RHR RIM <i>cut</i>	1		\$218.70	✓	600	
15	RHR KNUCKLE ARM <i>?</i>	1		TBA	+		
16	RHR LOWER ARM <i>?</i>	1		TBA	+		
17	RHR KNUCKLE BEARING <i>?</i>	1		TBA	+		
18	RHR DRIVE SHAFT <i>?</i>	1			+		
19		1					
20		1					
21		1					
22		1					
23		1		2160.72		SN: 600	
24		1		879.61			
25		0					
26		0					
27		0					
28		0					
29		0					
30		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

