

22/07/2002

ASS. REC. BY:

REF:

CS/EGIA023231/Wqo⁰⁷

Special Instruction:

Surveyor: Wilson

ASSIGNMENT (Office)

Date/Time: 8:24am @ 7/12/17

From (Person): Yee Pei Li

of

CGI

Bill to:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD7436K

Insured:

XB7509J

at Workshop m/s

Motoricarz Garage

Tel:

9769 9299

of 53 Ubi Ave 1 # 01-19 408934

Policy No:

Claim No:

XB7509J / SA / PL

Sum Insured:

Excess:

D.O.A. 4/12/17

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS ^{1 up}

H.O.D. Endorsement:

Date/Time: 9:33am @ 7/12/17

Person Contacted:

Kamen Koh

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	
	GBD7436K - NA/EGII7023010/h4	D.O.A: 4/12/17
	XB7509J - NA/EGII7023010/h4	D.O.A: 4/12/17
08/12/17 @ 2:20pm	informed Kamen list parts discount 25% instead of 10%.	
08/12/17 @ 3:24pm	revised to Pei Li by email,	
	US \$1600 (Per \$2702.65, 58%)	

REF:

ASSIGNMENT

From G3D7436K Date

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No G3D7436K
at Workshop no Motorcars Garage
of 53, W. Ave. 1 #01-9

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value

IDAC Accident Report

Consistent? : Yes or No

GIA PR Seen

Consistent? : Yes or No

Est. Repairs

days Res Yes or No

Lump Sum

% 3 Val Yes or No

CA / REV / REP / 24 HRS

Date

Person Contacted

Vehicle IN / OUT

Date / Time

Action / Instruction

Repair Estimate Given.

Veh No G3D7436K yr Regn Apr 15

Type: M.Car / M.Cycle / Bus / Van / Carry / Taxi / Prime Mover /

Truck / Trailer or

Make Toyota Dyna cc 2982Colour White A.C. Insured / Std / Nil / NASp. Reading 87033 T Radio Insured / Std / Nil / NA

Eng No

C.No JTFAT35Y60K204129

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size F: 195/75R15R: 155/R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Yokohama (R)

Front

R.Bal 4 mm R.Bal 2 mmL.Bal 4 mm L.Bal 2 mm

D.O.A

Survey held at At AboveDes. of Damages Fr Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 12 DEC 2017

Only Time File Pass to:

☐

Preli. Report

☐

Final Report

Date Time File Return to:

Days Of Repair: 1

Resurvey No. of Trip:

Survey Fee

Transportation

3 x RS

Photos

Other

Report Format:

Lump Sum / I.B.T. / S

7P
1600

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech Insp \$

☐

Weekend \$

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI17023231/Wqb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 07-12-2017



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XB 7509J	Veh. Inspected	GBD 7436K
Policy No.		Coverage (\$)	0.00
Claim No.	XB7509J/SA/pL	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	07/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	04/12/2017	Inspection Date	07/12/2017
Survey held at	MOTORICARZ GARAGE 53 UBI AVE 1 #01-25 PAYA UBI IND. PARK SINGAPORE 408934		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Survey Department Check List (Case Handler)

Reference No.: CS/KG/17023231/W96
 Policy Type: OD/TP/RES/TL/EVA

GDP 74362

Case Handler

Typist

Admin (Cather): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA/REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Wilson): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Chen 21/9/17
 Case Handler Date

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 7 December, 2017 8:24 AM
To: 'admin-d@lkkauto.com'
Subject: OI : XB7509J / TP : GBD7436K/LKK / DOA : 04/12/2017
Attachments: XB7509J - SAS.pdf; GBD7436K - SAS.pdf; GBD7436K - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **MOTORICARZ GARAGE**,

ADDRESS : 53 UBI AVE 1
#01-19 PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934

PERSON TO CONTACT : KAMAN KOH @ 9769 9299 / 6841 5383

ERGO OFFICER-IN-CHARGE : SITI

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel : 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 06.12.2017
Our Reference: XB 7509J/SA/pl
Your Reference: GBD 7436K

Sent via Fax:

6841 5383

or

Email:

To: MOTORICARZ GARAGE PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBD 7436K
Insured's Vehicle: XB 7509J
Date Of Accident: 04.12.2017

We acknowledge receipt of your request for PRS on: 06.12.2017

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LDS	L.D.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's complete GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐ Our Insured's driver has not reported the accident to us to date.
☒ Others: OFFICER-IN-CHARGE - SITI

Prepared by: [Signature] Pei Li 6829 9194 claims@ergo.com.sg
Signature: [Signature] FAX: 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 8 December, 2017 3:24 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.); assignments
Cc: SUR
Subject: RE: XB7509J / TP : GBD7436K/LKK / DOA : 04/12/2017
Attachments: CSEGI17023231Wqb.pdf

Dear Pei Li,

Enclosed herewith preliminary advice of GBD 7436K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 7 December, 2017 9:40 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments
<assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: XB7509J / TP : GBD7436K/LKK / DOA : 04/12/2017

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Thursday, 7 December, 2017 8:24 AM
To: 'admin-d@lkkauto.com'
Subject: OI : XB7509J / TP : GBD7436K/LKK / DOA : 04/12/2017

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **MOTORICARZ GARAGE**.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: XB7509J/SA/pl

Date: 08th December 2017

Our Ref: CS/EG117023231/Wqb

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. GBD 7436K


We thank you for the instruction on 07/12/2017.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 07/12/2017 at the premises of M/s MOTORICARZ GARAGE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,802.65</u>
Revised Estimate Amount	: S\$ <u>2,797.07</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 1 day.

We have NOT authorise repair.

Yours faithfully

Wilson
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Business
Owner ID	0701J
Vehicle Details	
Vehicle No.	GBD7436K
Vehicle to be Exported	No
Intended De-registration Date	08 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	TOYOTA DYNA 150 MANUAL
Primary Colour	White
Manufacturing Year	2014
Engine No.	1KD2472448
Chassis No.	JTFAT35Y60K204129
Maximum Power Output	-
Open Market Value	\$27,856.00
Original Registration Date	14 Apr 2015
First Registration Date	14 Apr 2015
Transfer Count	0
Actual ARF Paid	\$1,393.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	13 Apr 2025
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
PQP Paid	\$41,061.00
COE Rebate Amount	\$30,168.00
Total Rebate Amount	\$30,168.00

The information contained herein is correct as at 08 Dec 2017

OK

Enquire Transfer Fee

Vehicle Details

Vehicle No.	GBD7436K
Vehicle Type	B31 - Goods (Open) Lorry (Metal Body)/Pickup
Vehicle Attachment 1	No Attachment
Vehicle Scheme	Normal
Vehicle Make	TOYOTA
Vehicle Model	TOYOTA DYNA 150 MANUAL
Chassis No.	JTFAT35Y60K204129
Propellant	Diesel
Engine No.	1KD2472448
Engine Capacity	2982 cc
Maximum Power Output	-
Maximum Laden Weight	3500 kg
Unladen Weight	1680 kg
Year Of Manufacture	2014
Original Registration Date	14 Apr 2015
Lifespan Expiry Date	13 Apr 2035
COE Category	C - Goods Vehicle & Bus
PQP Paid	\$41,061.00
COE Expiry Date	13 Apr 2025
Road Tax Expiry Date	13 Apr 2018
Inspection Due Date	13 Apr 2018
Intended Transfer Date	08 Dec 2017
CO2 Emission	257.00 (g/km)
CEVS Rebate Utilised Amount	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee (s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee	11.00	-	11.00

REPUBLIC OF SINGAPORE DRIVING LICENCE


 Licence Number **S7584709B**
 Name: **GAN NGIN ENG**
 Birth Date: **05 May 1975**
 Issue Date: **05 Feb 2016**

002535416F



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7584709B




 Name: **GAN NGIN ENG**
顏錦榮
 Race: **CHINESE**
 Date of birth: **05-05-1975** Sex: **M**
 Country of Place of birth: **MALAYSIA**

S7584709B

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)

	EFFECTIVE DATE
Class 2B Motorcycles <= 200 cc	18 Feb 2002
Class 3 Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles with unladen weight <= 2500kg	18 Feb 2002

NP425A7



Licence No: S7584709B

9362705



IDENTITY CARD NO. S7584709B



Nationality: **MALAYSIAN**
 Date of issue: **10-03-2015**

Address:
APT BLK 142 TECK WHYE LANE
#06-277
SINGAPORE 660142

1,447,57

eq

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

COMMERCIAL VEHICLE PRIVATE (SCH I) Comprehensive

Certificate No.: DMCPHQ17-001522

Form: LCVP1

Excess:

Section 1

SGD\$00.00

VEID-AC

Additional SGD\$2,000.00

1. Index Mark and Registration Number of Vehicles
G8D7436X

2. Name of Policyholder
G HOME

3. Effective Date of the Commencement of Insurance for the purpose of the Act
27/04/2017

4. Date of Expiry of Insurance
26/04/2018

5. Person or Classes of Persons entitled to drive*

Goods carrying - (M1300) Authorised Driver. Any of the following :-

1. The Policyholder
2. Any person on the order or with the permission of the Policyholder

*Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

6. Limitations as to use*

- 1) Use in connection with the Insured's business.
- 2) Use for the carriage of passengers (other than for hire or reward) in connection with the Insured's business.
- 3) Use for social domestic and pleasure purposes.

THE POLICY DOES NOT COVER

- 1) Use for hire or reward or for racing pace-making reliability trial or speed testing.
- 2) Use whilst drawing a greater number of trailers in all than is permitted by Law.
- 3) Use for the carriage of passengers for hire or reward.
- 4) Liability arising from or in connection with the carriage of hazardous materials, high explosives, inflammable liquid or gases including LPG in cylinders.

*Limitations rendered inoperative by section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.



Authorized Signatory
EQ Insurance Company Limited

misjo/HO/A000311/Neo & Company Ins-ns

14 March 2017

Motoricarz Garage

53 Ubi Avenue 1#01-19 Paya Ubi Industrial Park Singapore 408934
 Tel: 6844 4290 Fax: 6841 6043 Email: carzingarage@gmail.com
 Kaman Koh: 9769 9299
 ROC No: 201404988D

Estimate

Vehicle: GBD 7436K

Make & Model: TOYOTA DYNA

No	Particular	Qty	Amount (\$)
<u>PARTS REPLACEMENT-LIST ITEMS</u>			
1	Front windscreen <i>BR</i>	1pc	1,271.20 ✓
2	Front wiper panel <i>X NN</i>	1pc	262.50 X
3	Front wiper arm <i>DD</i>	2 pcs	179.30 ✓
4	Front wiper arm cover <i>X NN</i>	2 pcs	25.20 X
5	Front wiper blade <i>TORN</i>	2 pcs	80.00 ✓
6	Front windscreen rubber <i>NFC</i>	1pc	291.65 ✓
7	Front wiper noster <i>SCR</i>	1pc	95.00 ✓
8	Front side mirror stay LH <i>BT</i>	1pc	799.60 <i>330</i>
9	Front side mirror LH <i>X NN</i>	1pc	318.50 X
10	Front side mirror round LH <i>SCRA</i>	1pc	141.10 ✓
			3,464.05
	Less 10% <i>85%</i>		346.41
	Sub-Total cost for parts (A)		3,117.65
<u>Part Replacement - Special</u>			
<u>Nett Item</u>			
1	ERP sticker <i>NEC</i>	2pcs	15.00 ✓
2	Windscreen adhesive <i>X NN</i>	1pc	60.00 X
3	Towing <i>✓</i>		120.00 <i>70</i>
	Sub-Total cost for parts (B)		195.00
<u>Labour & MISC Charges</u>			
1	Labour to clear broken glass inside		60.00 <i>40</i>
2	To remove,refix front windscreen		150.00 <i>100</i>
3	To remove,refix dashboard to assit repair		280.00 X <i>NN</i>
	Sub-Total Labour (C)		490.00
	Grand Total		3,802.65

*Without Prejudice**01 Days Repairs**Parts / Disassemble / After Repair**7/12/2017**W. Lam**Temp Sun Repair*

LKK Auto Consultants hence notify
 the Repairer of the following:

- ✓ To resurvey before/after spray painting
- ✓ To display damaged part(s) during resurvey
- ✓ Parts prices are subject to confirmation
- ✓ Third party survey is on a "Without Prejudice" basis
- ✓ No illegal modification(s) is allowed
- ✓ Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI17023231/Wqbn2

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 21-12-2017



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XB 7509J	Veh. Inspected	GBD 7436K
Policy No.		Coverage (\$)	0.00
Claim No.	XB7509J/SA/pL	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	07/12/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTFAT35Y60K204129	Colour	WHITE
Odometer	87033	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/75 R15	YOKOHAMA	4 mm
L/H Front Tyre	195/75 R15	YOKOHAMA	4 mm
R/H Rear Tyre	155 R12	BRIDGESTONE	2 mm
L/H Rear Tyre	155 R12	BRIDGESTONE	2 mm

4. Description of DamagesTHE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.**5. General Information**

Accident Date	04/12/2017	Inspection Date	07/12/2017
Survey held at	MOTORICARZ GARAGE 53 UBI AVE 1 #01-25 PAYA UBI IND. PARK SINGAPORE 408934		

5a. RemarksA)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 7436K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT WINDSCREEN	BROKEN	1,271.20	1,271.20
1	FRONT WIPER PANEL	NOT NECESSARY	262.50	-
2	FRONT WIPER ARM	DENTED	179.30	179.30
2	FRONT WIPER ARM COVER	NOT NECESSARY	25.20	-
2	FRONT WIPER BLAKE	TORN	80.00	80.00
1	FRONT WINDSCREEN RUBBER	NECESSARY	291.65	291.65
1	FRONT WIPER NOSTER	SCRATCHED	95.00	95.00
1	FRONT SIDE MIRROR STAY LH	BENT	799.60	330.00
1	FRONT SIDE MIRROR LH	NOT NECESSARY	318.50	-
1	FRONT SIDE MIRROR ROUND LH	CRACKED	141.09	141.10
	LESS 10% DISCOUNT		-346.39	-
	LESS 25% DISCOUNT		-	-597.06
			3,117.65	1,791.19
<u>SPECIAL NETT ITEMS</u>				
2	ERP STICKER (SN)	NECESSARY	15.00	15.00
1	WINDSCREEN ADHESIVE (SN)	NOT NECESSARY	60.00	-
			75.00	15.00
<u>LABOUR</u>				
	TOWING.		120.00	70.00
	LABOUR TO CLEAR BROKEN GLASS INSIDE.		60.00	40.00
	TO REMOVE,REFIX FRONT WINDSCREEN.		150.00	100.00
	TO REMOVE,REFIX DASHBOARD TO ASSIST REPAIR.	NOT NECESSARY	280.00	-
			610.00	210.00
GRAND TOTAL			3,802.65	2,016.19
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00

Report Ref No. CS/EG117023231/Wqbn2

WILSON TEO CHENG MING

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE

SINGAPORE 038985

INV No. AC1714515
INV Date 21/12/2017
Reference CS/EG117023231/Wqbn2
Code EGI



PROFESSIONAL SERVICE FEE

Vehicle No. GBD 7436K
Insured Veh. XB 7509J
Claim No. XB7509J/SA/pL
Policy No.
Accident Date 04/12/2017
Inspection Date 07/12/2017

Description	Total
Survey Inspection	250.00
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN