



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Thatcham **escribe**

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: NS/INC17023242/Stbe2
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSE SINGAPORE 189556		 Date: 19-04-2018 Code: INC4
1. Policy Particulars :- THIRD PARTY CLAIM		
Insured Veh.	GBE 7752S	Veh. Inspected SHC 4121Y
Policy No.	5078397711-01	Coverage (\$) 0.00
Claim No.	MT/0972556-002	Excess (\$) 0.00
Assign From		Assign Date 06/12/2017
2. Vehicle Particulars & Condition		
Make & Model	TOYOTA PRIUS	c.c 1798
Engine No.	HIDDEN	Year of Reg. 2013
Chassis No.	JTDKN36U205702605	Colour MAROON
Odometer	458201	Steering IN ORDER
Brakes	IN ORDER	Modification NIL
General	FAIR	
3. Conditions of Tyres		
	Size	Make Balance
R/H Front Tyre	195/65 R15	FALKEN 6 mm
L/H Front Tyre	195/65 R15	FALKEN 6 mm
R/H Rear Tyre	195/65 R15	FALKEN 6 mm
L/H Rear Tyre	195/65 R15	FALKEN 6 mm
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.		
5. General Information		
Accident Date	05/12/2017	Inspection Date 06/12/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	
5a. Remarks		
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days