

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: AEMD/105/009/2017/160

Date: 15st December 2017

Our Ref: CS1/SPF17023277/T1vbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section
(Singapore Police Force)

1 Mount Pleasant Road
Blk 8 Old Police Academy
Singapore 298333
(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO.: SFK 6119Z INSURED VEHICLE NO: QX 329A ACCIDENT ON 19/09/2017

We thank you for your instruction on 06/12/2017.

We acknowledge receipt of the following documents:-

- Automobile Inspection Report of SFK 6119Z from M/s Automobile Inspection Services Pte Ltd.
- b) Singapore Accident Statement of Vehicles SFK 6119Z.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: SFK 6119Z

Make & Mode

: Volkswagen Sharan 2.0 (A)

Year of Registration

: 2013

Chassis Number

: WVWZZZ7NZCV039098

Engine Capacity

: 1984cc



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

	Our finding is that the repair cost of \$5,694.33	(before GST) quoted by M/s	Volkswagen Group
	Singapore Pte Ltd is fair & reasonable.		

3. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.

Vehicle Inspection By:

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING B. Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI Licensed Appraiser