

ALG

POA: 05.12.17

QTY	PARTS DESCRIPTION	TYPE	UNIT PRICE	AMOUNT
	REAR BUMPER ✓			\$ 458.60
	REAR BUMPER RE-INFORCEMENT ?			\$ 318.80
	REAR BUMPER UNDER COVER ✓			\$ 552.60
	REAR BUMPER TOWING COVER ✓			\$ 82.70
	REAR BUMPER CLIPS ✓			\$ 22.00
	SUB TOTAL			\$ 1,434.70
	LESS 20% 25%			\$ 286.94
	DISCOUNTED TOTAL			\$ 1,147.76
	Labour Charge			200
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 770.00
	ESTIMATE TOTAL			\$ 1,917.76

Kalvin LKK

✓ 6/12/17 1810Lm

2 Days

PP

Before Paint photo

Larry Ng

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Larry Ng

Kalvin Rucker
6/2/17 1410 Lm
2 Days
P/P
Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date:

Page 1 of 1