

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: AIG	DATE	: 07/12/2017
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SKL6310Y		
MODEL	: VOLKSWAGEN GOLF		Vic.
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 30-11-2017
		TIME	: 18:30 HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rebond</i>	1	\$ 1,124.00	\$ 1,124.00
2	FRONT BUMPER LOWER LID <i>Rebond</i>	1	\$ 566.30	\$ 566.30
3	FRONT BUMPER LOWER GRILLE <i>cracked</i>	1	\$ 311.20	\$ 311.20
4	FRONT BUMPER SIDE RETAINER <i>new motor</i>	2	\$ 72.30	\$ 144.60
5	FRONT BUMPER REINFORCEMENT SPONGE <i>new</i>	1	\$ 197.90	\$ 197.90
6	FRONT GRILLE <i>cut</i>	1	\$ 544.20	\$ 544.20
7	FRONT GRILLE LOGO <i>new</i>	1	\$ 93.20	\$ 93.20
8	HEADLAMP RH <i>cracked</i>	1	\$ 1,188.20	\$ 1,188.20

3971.7

TOTAL PRICE \$ 4,169.60

3773.11

LESS 0% \$ -

SUB TOTAL PRICE \$ 4,169.60

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Rebond</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
3	FRONT GRILLE CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00

TOTAL \$ 110.00

110

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,000.00	250	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	350	
3	WIRING CHECK	\$ 250.00	30	
4	TUFF COAT	\$ 250.00	X	
5	REFOCUS HEADLAMP BEAM	\$ 150.00	X	
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X	

TOTAL

\$2,830.00

630

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,279.60
TOTAL LABOUR COST : \$ 2,830.00
TOTAL REPAIR COST : \$ 7,109.60

Adrian King.
r/s 07/12/17

03 Days

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Label 4403.11

r/s: 3.31C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3.31C