



FALCON-AIR

SALLIM B HASSIM
BLK509 #02-391 TAMPINES CENTRAL 1
SINGAPORE 520509
MS SHARIFAH

Attention : Motor Claim Department

Contact : 91002955

Estimate : ES003070

Date : 01/12/2017
Vehicle Num. : SJJ5927Y
Make/Model : SUZUKI SWIFT-2008
Chassis/Eng# : ZC71S425310
Accident Date : 27/11/2017
Claim No. :
Reference : TP v. INDIA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	BONNET		463.25
2.	2 PCS	BONNET HINGE	26.00	52.00
3.	2 PCS	HEADLAMP	335.15	670.30
4.	1 PC	BONNET LOCK		51.80
5.	1 PC	FRONT GRILLE		69.55
6.	1 PC	FRONT GRILLE LOGO		19.68
7.	1 PC	RADIATOR AUTO		732.25
8.	1 PC	RADIATOR SUPPORT PANEL (COMPLETE)		500.15
9.	1 PC	RADIATOR FAN ASSY		558.15
10.	1 PC	AIRCON CONDENSER		1,465.05
11.	1 PC	RADIATOR FAN COWLING		69.75
12.	1 PC	FRONT BUMPER		628.15
13.	1 PC	FRONT BUMPER TOP REINFORCEMENT		172.75
14.	1 PC	FRONT BUMPER LOWER GRILLE		60.75
15.	1 PC	FRONT BUMPER FOG GARNISH		18.05
16.	2 PC	FRONT BUMPER RETAINER	25.05	50.10
17.	2 PC	FRONT FENDER	235.65	471.30
18.	2 PC	FRONT FENDER UNDERSHIELD	63.95	127.90
19.	1 PC	FRONT SHOCK ABSORBER		282.70
20.	2 PC	FRONT KNUCKLE ARM	248.15	496.30
21.	1 PC	TOP REINFORCEMENT GARNISH		92.65
22.	1 PC	LOWER REINFORCEMENT		148.70

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ■ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg **E-mail:** email@falconair.com.sg



FALCON-AIR

SALLIM B HASSIM
BLK509 #02-391 TAMPINES CENTRAL 1
SINGAPORE 520509
MS SHARIFAH

Attention : Motor Claim Department

Contact : 91002955

Page 2 / 3
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003070

Date : 01/12/2017
Vehicle Num. : SJJ5927Y
Make/Model : SUZUKI SWIFT-2008
Chassis/Eng# : ZC71S425310
Accident Date : 27/11/2017
Claim No. :
Reference : TP v. INDIA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	LOWER REINFORCEMENT GARNISH		92.65
24.	1 PC	FRONT LOWER ARM		180.10
25.	1 PC	DRIVESHAFT LH		968.40
26.	1 PC	GEARBOX MOUNTING		105.55
27.	1 PC	RADIATOR TOP HOSE		20.00
28.	1 PC	RADIATOR LOWER HOSE		18.15
29.	1 PC	STABILIZER BAR LINK		48.75
30.	2 PC	SPORTS RIM	633.45	1,266.90
31.	2 PC	FRONT WHEEL BEARING	146.05	292.10
32.	1 PC	ENGINE UNDERCOVER SIDE		38.10
List TotalS\$:				10,231.98
20.00% Discount S\$:				2,046.40
				8,185.58
SPECIAL NETT ITEMS :				
1.	1 PC	BATTERY		120.00
2.	1PC	GEARBOX (AUTO)		5,000.00
3.	2 PC	TYRE	180.00	360.00
4.	1	GEARBOX AUTO OIL		100.00
Special Nett Total S\$:				5,580.00
LABOUR :				
TO FOCUS HEADLAMP / CHECK LIGHT SYSTEM				30.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S[528840] Tel: 6789-7997 Fax: 6788-7997 ▪ No. 8 Pandan Loop (Blk I / Blk K) S[128226] Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

SALLIM B HASSIM
BLK509 #02-391 TAMPINES CENTRAL 1
SINGAPORE 520509
MS SHARIFAH

Attention : Motor Claim Department

Contact : 91002955

Page 3 / 3
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003070

Date : 01/12/2017
Vehicle Num. : SJJ5927Y
Make/Model : SUZUKI SWIFT-2008
Chassis/Eng# : ZC71S425310
Accident Date : 27/11/2017
Claim No. :
Reference : TP v. INDIA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TOWING CHARGES (4 WHEELS)		120.00
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS		1,400.00
		COMPUTERISED WHEEL ALIGNMENT		100.00
		TO REMOVE/REPLACE AIRCON CONDENSER VACUUM & REGAS		120.00
		PANEL BEATING, MECHANICAL WORKS		1,200.00
		TO REMOVE/ REWELD/RESEAL WEEK END PLATE		120.00
		Labour Total S\$:		3,090.00

E. & O.E.

Total S\$: 16,855.58

=====

for FALCON AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ▪ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg