

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Bazlin Ahmad

Date: 13 Dec 2017

Preliminary Advice

Vehicle No	: SKQ6919R	Accident Date	: 25/11/2017
Make	: LAND ROVER RANGE ROVER EVOQUE	Policy No.	: DMPPHQ17-003107
Assignment Date	: 07/12/2017	Excess	: S\$550.00
Date of Inspection	: 12/12/2017	Est. Duration of Repair	: 6.00
Inspection At	: AUTO N CARS SERVICES PTE LTD (HQ) BLK 1 KAKI BUKIT AVE 6 #01-04, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,570.64
Revised Amount	:S\$	14,525.89
Check Items (Estimated)	:S\$	4,099.75
Total	:S\$	18,625.64

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	98,000.00
COE / PARF Rebate	:S\$	78,419.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,581.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :