

Company **India International Insurance**
Address 64 Cecil Street
#04/#05/#06-02, IOB Building
Singapore 049711
Tel: 6347 6100
Fax: 6224 4174

Quotation

Quotation No. : MIC2017008/01
Date : 21/11/2017
Page: 1 of 1

Dear Sir/Madam,

We are pleased to submit our quotation for the repair of the vehicle below. Should there be any additional parts and labour required, will inform you and bill accordingly.

Vehicle: **Ferrari California**
Reg. No: **SCY 17 K**

Chassis No: **ZFFEZ59C000160679**
Engine No: **F136E133325**

Item	Description	Qty	Unit Price (SGD)	Amount (SGD)
1	<u>MATERIAL</u> R.H.S FRONT FENDER ASSEMBLY	1	5,864.00	5,864.00
				5,864.00
1	<u>LABOUR RENDERED</u> TO REMOVE AND REFIT WHEEL WELL LINER, SCUDERIA BADGE, SIGNAL LAMP, GRILL AND FRONT BUMPER TO FACILITATE RENEWAL OF FRONT FENDER	30	120.00	3,600.00
2	RESPRAY AND REPAIR FRONT BUMPER LHS	1	1,000.00	1,000.00
3	SPRAY NEW RHS FRONT FENDER TO BODY COLOUR	1	1,000.00	1,000.00
				5,600.00
			TOTAL	11,464.00
			GST	802.48
			GRAND TOTAL	12,266.48

.....
Authorized Signatory