

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216
Officer in Charge : BRYCE TAM YIK MAN
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960
Attn :
Tel :
Fax :
req: Lkk Marcus.
08-12-2017 @ 0930hrs.

Quotation No : QO17/12-1084	Quotation Date : 07/12/2017	Terms : 30 DAYS
Vehicle No : SLJ1206Y	Chassis No : JM6BN22A8H0120727	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: AIG, INSURED'S VEHICLE NO: SBP1213M, DATE OF ACCIDENT: 07.12.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID MAZDA 3 BADGE	1	130.0000	130.00
2	BOOTLID SKYACTIV BADGE	1	64.0000	64.00
3	BOOTLID REFLECTOR O/S	1	265.0000	265.00
4	REAR LAMP O/S	1	509.0000	509.00
5	REAR LAMP CLIP HOLDER	3	8.0000	24.00
6	REAR LAMP PANEL O/S	1	98.0000	98.00
7	REAR FENDER LOWER PANEL O/S	1	129.0000	129.00
8	REAR FENDER AIR VENT	1	35.0000	35.00
9	REAR BUMPER	1	1,075.0000	1,075.00
10	REAR BUMPER REFLECTOR O/S	1	51.0000	51.00
11	REAR BUMPER SIDE RETAINER	2	37.0000	74.00
12	REAR BUMPER SIDE HOLDER	2	74.0000	148.00
13	REAR BUMPER SIDE HOLDER RIVETS	4	6.0000	24.00
14	REAR BUMPER TOW COVER O/S	1	18.0000	18.00
15	REAR BUMPER END SPLASHIELD COVER O/S	1	80.0000	80.00
16	REAR BUMPER CLIPS	10	5.0000	50.00
17	REAR BUMPER REINFORCEMENT	1	558.0000	558.00
18	REAR END PANEL	1	506.0000	506.00
19	REAR END PANEL INNER TRIM	1	86.0000	86.00
20	REAR END PANEL INNER TRIM CLIPS	4	20.0000	80.00
21	REAR EXHAUST BOX	1	426.0000	426.00
22	REAR EXHAUST BOX HEAT SHIELD	1	80.0000	80.00
23	REAR EXHAUST BOX MOUNT	2	15.0000	30.00

C/F 0.00

Page 1 of 2

3164
2031.2

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216
Officer in Charge : BRYCE TAM YIK MAN Tel : Email :

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax :

Quotation No : QO17/12-1084	Quotation Date : 07/12/2017	Terms : 30 DAYS
Vehicle No : SLJ1206Y	Chassis No : JM6BN22A8H0120727	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: AIG, INSURED'S VEHICLE NO: SBP1213M, DATE OF ACCIDENT: 07.12.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	LESS 20% ITEMS (1-23)	1	-908.0000	-908.00
25	REAR BUMPER PARKING SENSOR	1 set	450.0000	450.00 200
26	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	80.0000	80.00 50
27	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	120.0000	120.00 50
28	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	880.0000	880.00 800
29	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	780.0000	780.00 700
30	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	120.0000	120.00 60
31	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	160.0000	160.00 20

446.2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub Total	6,222.00
GST(7.00%)	435.54
Total (SGD)	6,657.54

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216