

INS. CASE OWNER:

Ray Eng

CC 6 / LCR170 234151

LKK:

IDAC:

ASSIGNMENT

Surveyor:

MAGLUS

DOI:

19/12/17

Date / Time:

11/12/17

Registered in Merimen:

11/12/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLN 827R

Claim No.:

6256801803SG

Name of Insured:

LCR

Policy No.:

Insured Tel No.:

HP:

Make / Model:

MAZDA 3-1.5 SEDAN EV6 (A)

Excess Sec II : \$

D.O.A.:

02/12/17

Place of Accident:

ALONG AVE TOWARDS CTE

Is driver the owner?

(YES ☒ NO)

Nature of Accident:

If NO, Driver Name / Age: CHEONG YEW KEE

OI GIA REPORT ☒ YES / NO ; TP GIA REPORT ☒ YES / NO

Driver Tel No.:

(V/L ☒ YES / NO)

Insured Liability:

%

Final ? Yes / No

SB 2154Y



INSRS:

WSP: Hock Wah (Bedde)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

13/12/17 (29/12)

SB 2154Y - X ; SLN 827R - X

File review, OI removed TP.

Email to LCR.

Email to WSP. Liability clear.

- to submit total loss report. NO repair.

TP CLIENT DIDNT PURSUE
FOR REPAIR & DIDNT SEND
HIS VEH TO WSP.

RECEIVED 26 JUL 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

Let

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 250

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

Starline Mercury

REF:

AIC/ Ref: 17023415/0293

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJB21544
 at Workshop m/s: hucknuck 1pu.
 of _____
 Insured: SLN 827R
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJB21544 Yr Reg: 3/1/ of
 Type: CA / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA /
 Make: Honda Stream cc 1799
 Colour: Silver A.C. Insured / Std / NI / NA
 Sp. Reading: 14042 T. Radio: Insured / Std / NI / NA
 Eng. No: _____
 C/No: RN 61048055
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: _____ R: 205/65-15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 mm Rear: 6 mm
 R/Bal: 6 mm L/Bal: 6 mm
 D.O.A: 2/11/17 D.O.I: 19/12/17
 Survey held at: _____
 Des. of Damages: Rear / Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 9774
500? before 2 day after survey TOTAL LOSS?
25/7/18 vehicle hasn't send in for rep - (closed)

MV - \$10,000
 LR - \$9500.XX
 NETTV \$500.XX

\$(\$2,464.61/53%)

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Date/Time, File Return to?

Resurvey No. of Trip: _____

Survey Fee: _____

1) _____ Transportation: _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

☐ : Weekend (\$ _____)

Photos: _____

Notes: _____

TOTAL: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC6/LCR17023415/Uza3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120			Date : 11-12-2017	
			Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLN 827R	Veh. Inspected	SJB 2154Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/12/2017	Inspection Date	19/12/2017	
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

HOCK WAH MOTOR WORKSHOP PTE LTD

*BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S2688302D
BASIL ALI OMER UQBA
BLK 183 BEDOK NORTH ROAD
20-52
SINGAPORE 460183
TEL : FAX :
PH : 97824745
ATTN :

ESTIMATE BILL

Number : EB00004686
Date : 11/12/2017
Case No : AD00009440
Vehicle No : SJB2154Y
Chassis : RN61048055
Year of Mfr : 2007
Policy No : 5081364342
Model : HONDA STREAM
1.8A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAILGATE	1.0	903.20	20	722.56
2	TAILGATE INNER LOCK	1.0	189.20	20	151.36
3	TAILGATE EMBLEM	1.0	24.90	20	19.92
4	TAILGATE LOGO (STREAM)	1.0	31.60	20	25.28
5	REAR BUMPER	1.0	588.90	20	471.12
6	REAR BUMPER CLIP	2.0	3.70	20	5.92
7	REAR BUMPER SIDE RETAINER LH	1.0	24.10	20	19.28
8	REAR BUMPER SIDE RETAINER RH	1.0	24.10	20	19.28
List Price - Parts Sub Total					1,434.72
9	REAR NUMBER PLATE	1.0	30.00	0	30.00
10	REAR NUMBER PLATE HOLDER	1.0	30.00	0	30.00
11	REAR BUMPER REVERSE SENSOR LH	1.0	280.00	0	280.00
12	REAR BUMPER REVERSE SENSOR RH	1.0	280.00	0	280.00
13	REAR REVERSE CAMERA	1.0	580.00	0	580.00
14	WINDSCREEN SEALANT	2.0	24.00	0	48.00
15	REAR END PANEL - REPAIR	1.0			
Special Nett Price - Parts Sub Total					1,248.00
Parts Total					2,682.72
16	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	600.00	0	600.00
17	SPRAY PAINT ON THE AFFECTED AREAS	1.0	600.00	0	600.00
18	ANTI-RUST COATING	1.0	100.00	0	100.00
19	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
20	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					1,630.00
					2704.16
SINGAPORE DOLLARS : FOUR THOUSAND SIX HUNDRED FOURTEEN AND CENTS SIXTY-ONE ONLY			Less Excess		0.00
			SUBTOTAL		4,312.72
			GST 7.00%		301.89
			TOTAL		4,614.61

Date of accident : 02/12/2017 01:40 PM Place : AVE 10 MCE NEAR WEST COAST

E. & O. E.

LKK Auto Consultants hence notify the Repairer of the following:

- * To display damaged part(s) during resurvey
- * Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- * Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

CUSTOMER SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

AUTHORISED SIGNATURE



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8302D
Vehicle Details	
Vehicle No.:	SJB2154Y
Vehicle to be Exported:	No
Intended De-registration Date:	19 Dec 2017
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8 A
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	R18A1753702
Chassis No.:	RN61048055
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$18,340.00
Original Registration Date:	03 Jan 2008
First Registration Date:	03 Jan 2008
Transfer Count:	1
Actual ARF Paid:	\$19,430.00
Intended PARF Rebate Details	

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Jan 2018
PARF Rebate Amount:	\$9,715.00
Intended COE Rebate Details	
COE Expiry Date:	02 Jan 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$5,985.00
COE Rebate Amount:	\$59.00
Total Rebate Amount:	\$9,774.00

The information contained herein is correct as at 19 Dec 2017

OK

- Hyundai Accent 2014
- Singapore Reckless Driver Part V
- Beautiful Quotes - for people to find inspiration

Username / Email Add
password Submit Qu
Connect Sign Up New Account
Forgot Password

Honda Stream Price Range: Depreciation 2008 Vehicle Type Submit Advanced Search

Home » Used Cars » Hong Heng Co. Pte Ltd » Honda Stream 1.8A X

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle



UP TO 70% OFF

Luxury Watches

Compare

Honda Stream 1.8A X

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$10,800	
Depreciation	-	
Reg Date	23-Jan-2008 (1mth 3days COE left)	
Manufactured	2007	
Mileage	-	
Transmission	Auto	
Engine Cap	1,799 cc	
Road Tax	\$978 /yr	
Power	103.0 kW (138 bhp) View specs of the Honda Stream (2007-2014)	
Curb Weight	1,350 kg	
Features	1.8L I-VTEC 16 Valves DOHC Engine, 5 Speed Automatic Transmission, SRS Airbags.	
Accessories	-	
COE	\$15,501	
OMV	\$17,381	
ARF	\$19,120	
Dereg Value	\$9,704 as of today (change)	
No. of Owners	2	
Type of Veh	MPV	
Category	PARF Car	
Availability	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 16-Dec-2017 | Last Updated on: 19-Dec-2017
Tags: Honda Stream, Honda Stream, 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Stream, Used Honda

Upfront Payment		more Financial info
Transfer Fee	\$11	
Down Payment	\$3,240 (change)	Maximum 70% Loan
1st Instalment	\$7,579	
Total Upfront Payment	\$10,830 (excluding insurance)	

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.



Seller Information	
Company	Hong Heng Co. Pte Ltd • dealer's pricelist • 2 vhs sold 17 vhs available
Address	33 Sembawang Road #01-01 Search cars nearby this location
Location	Hong Heng Gardens
Office No	64521112
Contact Person(s)	Mr Ho 96563239 David Ang 92376357

Useful Services

STA Make sure of this car condition with STA Evaluation. Vehicle Evaluation

Find out the market value for your car. Get a Free Car Valuation. Free Valuation

SGCARMART.COM

THE ONLY PLACE FOR SMART CAR BUYERS

SGCARMART APP DOWNLOAD

Apple

Android

All

Car Make or Model

Search

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS & TIPS

Username / Email Add

password

Submit Qu

Connect

Sign Up New Account

Forgot Password

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2008 Toyota Camry 2.0

A Reliable Car In Very Good Condition, Serviced Only At Borneo Motors. Direct Owner StarAd

PRIME MOTOR & LEASING

ICHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Back (1 2 3 4) Next >

Sort by Date Posted

20 results/page

61 vehicles

Honda Stream

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Stream		Any	Any	2008	Any	Any	Any	Available
Honda Stream 1.8A (New 5-yr COE) \$42,800 \$8,560 /yr 17-Jan-2008 1,799 cc 93,462 km MPV Available Posted: 19-Dec-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda Details									
Honda Stream 1.8A (New 5-yr COE) \$38,500 \$7,700 /yr 18-Jan-2008 1,799 cc 200,000 km MPV Available Reliable And Proven 7 Seater MPV With A Great Price. Well Kept And Maintained By Owner. Monthly Below \$600 Only. Call Now For More Information. Get It Before COE Hikes Up.Loan/Insurance Available. Str... Prem Roy Motoring Posted: 19-Dec-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda Details									
Honda Stream 1.8A X (New 5-yr COE) \$46,800 \$9,350 /yr 06-Feb-2008 1,799 cc 97,000 km MPV Available "One Year Warranty!" With Official Warranty Certificate For A Peace Of Mind, 10% Down Payment, Bank/In House Loan Available, Lowest Down Payment, Flexible Loan Upto End Of Coe Fully Refurbished, New P... Carway Posted: 19-Dec-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda Details									
Honda Stream 1.8A (New 5-yr COE) \$43,800 \$8,760 /yr 16-May-2008 1,799 cc - MPV Available Posted: 18-Dec-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda Details									
Car Buying Car Selling Car Aftermarket Car Ownership On The Move Lifestyle									
Honda Stream 1.8A X (New 5-yr COE) \$43,800 \$8,760 /yr 19-Feb-2008 1,799 cc 101,000 km MPV Available One Owner, New Paintwork, Wear And Tear Parts Replaced, Excellent Condition, No Further Repairs Is Needed, Do Drop By For Viewing/Test Drive. Posted: 18-Dec-2017 Tags: 2008 Honda Stream, 2008 Honda Stream, Honda Stream, Honda Stream, Honda, Stream, Stream, Used Honda Details									
Honda Stream 1.8A X (New 5-yr COE) \$39,800 \$7,960 /yr 27-Mar-2008 1,799 cc - MPV Available \$0 Down Payment Available! Full Loan At Monthly \$900 Plus, We Are sgCarMart Premium Dealer! Buy With No Worries! No Hidden Costs! Car In Original Condition! Low Mileage! Accident Free! In House Loan O... 88 Motor Trading Compare Details									

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Thursday, 26 July 2018 11:10 AM
To: Khoo, Kay-Eng
Cc: Admin A
Subject: 6256801803SG (LCR SLN 827R ON 02.12.2017 / HOCK WAH SJB 2154Y) LKK: CC6/LCR17023415/Uja3

Dear Kay Eng,

We refer to the subject.

We were informed by TP repairer that their client didn't send in his vehicle for repair.

TP has 12 days balance after survey. COE Expiry on 02.01.2018 with est. nett value of \$500.00

In view of this, we will proceed to submit our report in Merimen.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Joy Irene (LKKAUTO)

From: Hock Wah Motor Pte Ltd <motor@hockwah.com.sg>
Sent: Monday, 2 July 2018 1:24 PM
To: Zayyer (LKKAUTO)
Subject: RE: TP CLAIM_SJB2154Y & SLN827R (AIG)_DOA:02/12/2017 *** LKK REF - CC6/LCR17023415/za3

Dear Zayer

This vehicle did not proceed repair at our workshop although the liability is clear.

Thank you.

Best Regards
Mavis Er
Customer Service Executive
Hock Wah Motor Workshop Pte Ltd
Blk 3011 Bedok North Avenue 4 | #01-2008/2010/2012/2014 | Singapore 489977
Tel: 6441 5655 | Fax: 6243 8121 | Website: www.hockwah.com.sg

From: Zayyer (LKKAUTO) <zayyer@lkkauto.com>
Sent: Friday, 15 December, 2017 1:47 PM
To: Hock Wah Motor Pte Ltd <motor@hockwah.com.sg>
Subject: RE: TP CLAIM_SJB2154Y & SLN827R (AIG)_DOA:02/12/2017 *** LKK REF - CC6/LCR17023415/za3

WITHOUT PREJUDICE

Dear Mavis,

Refer to the above matter.

Please be informed that the liability is clear for the above mentioned case (**Subject to the BOLA guideline Settlement**) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor. Please arrange for survey.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

Best Regards,
Zayer | Case Handler
LKK Auto Consultants Pte Ltd

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2017 Edit Reg		19 Dec 2017 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF PTE LTD , Co. Reg. No.: 201624597K		
Main Claimant:	BASIL ALI OMER UQBA , ID: S2688302D		
Vehicle Reg. No.:	SJB2154Y	Date of Loss:	02/12/2017 13:00 - :59 [118 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6256801803SG	Policy/Cover Note No.:	0999995083
Vehicle Reg. No. (Insured):	SLN827R	Policy No. (Claimant):	5081364342
		Excess:	
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E,, #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Khoo, Kay-Eng - 6419 1026] Kay-Eng.Khoo@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJB2154Y (6256801803SG)
[SLN827R]
TP
BASIL ALI OMER UQBA
Dec 2 2017 1:00PM
[LCRF PTE LTD]
Hock Wah Motor Workshop Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Photos/Images												3 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print			
1	19/12/17 17:26	General View										1	Load JPG				
2	19/12/17 17:26	General View										1	Load JPG				
3	19/12/17 17:26	General View										1	Load JPG				
4	19/12/17 17:26	General View										1	Load JPG				
5	19/12/17 17:26	General View										1	Load JPG				
6	19/12/17 17:26	General View										1	Load JPG				
7	19/12/17 17:26	General View										1	Load JPG				
8	19/12/17 17:26	General View										1	Load JPG				
9	19/12/17 17:26	General View										1	Load JPG				
10	19/12/17 17:26	General View										1	Load JPG				
11	19/12/17 17:26	General View										1	Load JPG				
12	19/12/17 17:26	General View										1	Load JPG				
13	19/12/17 17:26	General View										1	Load JPG				
14	19/12/17 17:26	General View										1	Load JPG				
15	19/12/17 17:26	General View										1	Load JPG				
16	19/12/17 17:26	General View										1	Load JPG				
17	19/12/17 17:26	General View										1	Load JPG				
18	19/12/17 17:26	General View										1	Load JPG				
19	19/12/17 17:26	General View										1	Load JPG				
20	19/12/17 17:26	General View										1	Load JPG				
21	19/12/17 17:26	Odometer Reading										1	Load JPG				
22	19/12/17 17:26	General View										1	Load JPG				
23	19/12/17 17:26	General View										1	Load JPG				
Documentation												1 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print			
1	11/12/17 09:48	TP GIA REPORT										1	Load PDF				
2	21/12/17 10:18	TP ESTIMATE- MARKED										1	Load PDF				
3	26/07/18 11:16	EMAIL TO AIG-WP										1	Load PDF				
4	26/07/18 11:18	EMAIL FROM WORKSHOP										1	Load PDF				
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail	Print			
1	12/12/17 16:18	OI GIA REPORT										1	Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR17023415/UJA3Q2

Date: 01/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995083
Claimant Vehicle No : SJB2154Y **Insured Vehicle No :** SLN827R
 Date of Loss: 02/12/2017 Nature of Claim: TP Claim No: 6256801803SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJB2154Y**
 Make & Model: HONDA STREAM, 1.8 (A) Engine No: R18A1753702
 Reg. Date: 03/01/2008 (Man. Year: 2007) Chassis No: RN61048055
 Colour: Silver Odometer: 121042 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R15 Rear Tyre Size: 205/65 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 19/12/2017
 Date Inspected: 19/12/2017 Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok)
 Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
 Singapore 489977
 Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$10,000.00

LTA REIMBURSEMENT VALUE (RV) : \$9,500.00

NETT VALUE : \$500.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >