



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : LOH JIN LOONG Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO17/12-1047	Quotation Date : 05/12/2017	Terms : 30 DAYS
Vehicle No : SLP1863T	Chassis No : MHFB29F3502009763	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: AIG, INSURED VEHICLE NO: GBF6534G, DATE OF ACCIDENT: 3.12.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	FRONT BUMPER	1	427.9000	427.90
2	FRONT BUMPER REINFORCEMENT	1	379.2000	379.20
3	FRONT BUMPER SIDE RETAINER N/S	1	65.7000	65.70
4	FRONT BUMPER AIR GUIDE TOP N/S	1	77.9000	77.90
5	FRONT BUMPER AIR GUIDE BOTTOM N/S	1	59.7000	59.70
6	FRONT BUMPER CLIPS	10	4.3000	43.00
7	HEAD LAMP N/S	1	588.1000	588.10
8	FRONT FENDER N/S- REPAIRS	1	612.7000	612.70
9	FRONT BUMPER CENTRE GRILLE	1	276.2000	276.20
10	LESS 25% ITEMS(1-9)	1	-632.6000	-632.60
11	FRONT LICENCE PLATE	1	100.0000	100.00
12	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	500.0000	500.00
13	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	480.0000	480.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000	60.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Date:

Sub Total 3,037.80
GST(7.00%) 212.65
Total (SGD) 3,250.45

P-1460.6
252
1095.45

P/7 1715.45