

15/5/2016

INS. CASE OWNER:

Tan Wilson

CC 6 / LER 170 23435, Uwa3

LKK:
IDAC:

ASSIGNMENT

DOI:

11-12-17

Date / Time:

11/12/17

Registered in Merimen:

11/12/17

Surveyor:

MARLUS

Pre-assign / CCU / FTE

SLR 1222H

LEPS PL

Claim No.:

0799995070

Policy No.:

Make / Model:

Honda Vezel.

Place of Accident:

Tampines St 82



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

D.O.A.:

8/12/17

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

Lee Kong WIE

If NO, Driver Name / Age:

Driver Tel No.:

6881063C

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Pytech
2868K

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

DATE / PIC

13/12

6881063C X; SLR 1222H X

13/12/17

email letter to CO.

O/S pms to cs mumsa

RECEIVED 22 DEC 2017

STAGE

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Email

Call

Repair Cost:

SS

(days) Reduction:

%

FINAL SETTLEMENT

Date/Time:

Confirm with Winston

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

Repair Cost:

SS

3263.50

Loss of Rental (LOR):

SS

642.00

(6 days) X 100 + 65

Loss of Use (LOU):

SS

-

(\$ x days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

535

Medical:

SS

Disbursement:

SS

Legal Cost

SS

Total:

SS

3910.85

Global Sum SS:

Email

Call

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

SS

3910.85

Payee 2: (Strike if N.A.)

SS

Payee 3: (Strike if N.A.)

SS

Name 1:

Name 2:

Name 3:

Stytech Auto Pte Ltd.

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Summary memo

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: G8B1063C
 at Workshop m/s: Stylech
 of _____
 Insured: SLR/222H
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 9k.
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 G/A / PR Seen: [Signature] Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction L7A 965

18/1/17 confirmed L/S @ 3050 with winston.

Veh No: G8B1063C /r Regn: 7.08
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or (m)
 Make: Nissan urvan C.C. 2953
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 392107 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: INIMG2E280750135
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: NI / S/Rim / STD A/Rim or
 Tyre Size: F: 195-R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front _____ Rear _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. _____ mm L/Bal. 7 mm
 D.O.A. 8/1/17 D.O.I. 11/1/17
 Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time. File Pass to?

1)

Date/Time. File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS \$ _____

Photos

Others

TOTAL

(ed. \$ 2799.65
 44.1.)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/LCR17023435/Uwa3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 11-12-2017



Code : LCR

Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	SLR 1222H	Veh. Inspected	GBB 1063C
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	11/12/2017

Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.		Colour
	Odometer		Steering
	Brakes		Modification
	General		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages

4.

General Information

5.	Accident Date	08/12/2017	Inspection Date	11/12/2017
	Survey held at	STYTECH AUTO PTE LTD 2 KAKI BUKIT AVENUE 2 #02-30 KAKI BUKIT AUTOHUB SINGAPORE 417921		

Remarks

5a.

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

not allowed
1/5
L-day.
11/11/17
1/5 + 3050

Make & Model: Nissan Urvan

Chassis No:

Year:	Chassis No:	Condition	Price	recommend
1st item	Parts / Labour			
Rear body panel nls	body	2010.30	/	
Rear body inner wheel house panel nls	n	442.60	X	
Rear body inner cardboard nls	n1	178.00	X	
Rear body inner cardboard clips nls	nu	30.00 S Netf	✓	
Rear bumper	Deepen	733.60	/	
Rear bumper side retainers @ 14.20	Nls net	28.40 S Netf	12 C	
Rear bumper clips	net	30.00 S Netf	✓	
Rear mudflap nls	To n	113.60 S Netf	✓	
Rear tyre cover nls	cu	80.00 S Netf	✓	
Rear axle shaft	n1	338.20 S Netf	X	
Rear axle shaft bearing	n1	82.00 S Netf	X	
Rear axle shaft cone	n1	14.00 S Netf	X	
Rear axle shaft oil seal	n1	18.00 S Netf	X	
Sliding door roller guide nls	n1	271.40 S Netf	X	
Sliding door roller guide stopper garnish nls	n1	30.20 S Netf	X	
tooltory nls	one	208.70 S Netf	✓	
(30%)				
To check wiring		80.00	30	
To spray anti rust proofing		100.00	50	
To smooth & refix upholstery	n1	150.00	X	
labour for panel beating & replacing parts		800.00	780	
To putty & spray painting		1000.00	600	
To Dismantle & refix axle shaft	n1	120.00	X	
LKK Auto Consultants hence notify the Repairer of the following:				P 2693.30
• To resurvey before/after spray painting				1885.31
• To display damaged partial tuning resurvey				
• Parts prices are subject to confirmation				S.N 476.50
• Third party survey is on a "Without Prejudice" basis				labour 1460
• No illegal modification(s) is allowed				3811.81
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
Acknowledged by Repairer				
Signature:				
Date:				

Alaskan URVAN C25 ABB 1063 C

- 1) Rear body outer panel (tu) — 1.1500 — \$2010.30
- 2) " " Inner sheet house lrc panel — 1 X \$442.60
- 3) " " Inner Cardboard — 11 X \$178.00
- 4) " " " " clip — 121 — \$30.00 SN
- 5) Rear Bumper — Deep cut — \$733.60
- 6) " " Retainer — 22 — 1/2 set lrc \$28.40 SN
- 7) " " clip — 221 — \$30.00 SN
- 8) Rear mudflap (tu) — 10.1 — \$113.60 SN
- 9) Rear Tyre Cover (tu) — cut — \$80.00 SN
- 10) Rear axle shaft — 11 X \$338.20 SN
- 11) " " " Beam (sk) — 11 X \$82.00 SN
- 12) " " " Cone — 11 X \$14.00 SN
- 13) " " " oil seal — 11 X \$18.50 SN
- 14) 14 Sidup Door roller guide — 11 X \$271.40 SN
- 15) 14 Sidup Door roller guide stopper garnish — 11 X \$30.20 SN
- 16) 14 Rear Taillamp — cut — \$208.70 SN
- Labour —
- 1) Check wiring — 80k — 30
- 2) Anti Rust Protection — 100k — 50
- 3) Interior Upholstery (Red) — 150k — 11 X
- 4) Panel Beating — 800k — 780
- 5) Paintwork — 1000k — 600
- 6) Remove & refit axle shaft — 150k 11 X
- Refill axle oil

Sdy. 11/12/17

Sent from Yahoo Mail on Android

----- Forwarded message -----

From: "LTA-VTL@lta.gov.sg" <LTA-VTL@lta.gov.sg>

To: "stytech_winston@yahoo.com.sg" <stytech_winston@yahoo.com.sg>

Sent: Sat, 9 Dec 2017 at 11:36

Subject: Notification of Successful Vehicle Insurance Search for Receipt No.: ITNET-00000-171209-000421



Notification of Successful Vehicle Insurance Search for Receipt No.: ITNET-00000-171209-000421

Dear Sir/Madam

We wish to inform you that your transaction on "Enquire Vehicle Insurance Particulars" performed on 09 Dec 2017 was successful and the Receipt No. is ITNET-00000-171209-000421.

2. The details of the search results are as follow:

Vehicle No.	Search Date	Search Time	Search Result
-------------	-------------	-------------	---------------

SLR1222H	08 Dec 2017	08:45:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.
----------	-------------	----------	--------------------------------------

3. Please contact our customer service officers at tel : 1800-CALL LTA (1800-2255 582) should you require further assistance.

4. Please do not reply to this auto-generated e-mail. If you have any feedback, please go to www.lta.gov.sg/feedback. You can also visit www.onemotoring.com.sg for more information.

5. Thank you.

If you are not the intended recipient of this communication, please delete it.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Business
Owner ID	2868K

Vehicle Details

Vehicle No.	GBB1063C
Vehicle to be Exported	No
Intended De-registration Date	11 Dec 2017
Vehicle Make	NISSAN
Vehicle Model	URVAN PANEL SWB 3.0 5DR 5MT AIRBAG 2WD
Primary Colour	Silver
Manufacturing Year	2008
Engine No.	ZD30157542K
Chassis No.	JN1MG2E25Z0750135
Maximum Power Output	-
Open Market Value	\$23,724.00
Original Registration Date	21 Jul 2008
First Registration Date	21 Jul 2008
Transfer Count	0
Actual ARF Paid	\$1,187.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	20 Jul 2018
COE Category	E - Open Category
COE Period(Years)	10
QP Paid	\$16,500.00
COE Rebate Amount	\$965.00
Total Rebate Amount	\$965.00

The information contained herein is correct as at 11 Dec 2017

OK



Nissan Urvan Price Range Depreciation 2008 Vehicle Type Submit Advanced Search

Home » Used Cars » ABWIN Bus Pte Ltd » Nissan Urvan

Nissan Urvan

Overview Financial Accessories Similar Research Photos Map

PREMIUM AD

ABWIN 諭輝 BUS PTE LTD

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle

Car Leasing



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$13,800	?
Depreciation	\$15,260 /yr View models with similar depreciation	?
Reg Date	07-Nov-2008 (10mths 26days COE left)	?
Manufactured	2008	?
Mileage	-	?
Transmission	Manual	?
Engine Cap	2,953 cc	?
Curb Weight	1,800 kg	?
Fuel type	Diesel	?
Features	-	?
Accessories	Glass Window Can Modify Close Panel.	?
Description	1 Owner Only. Low Miles, HDB Parking \$65, Can Renew More 10 Years COE, No Repair Needed, Regular Servicing Just Done, Price Negotiable, Provide High Loan With Low Interest Rate, High Trade In Value, Call Fast!	?
COE	\$14,890	?
OMV	\$29,097	?
ARF	\$1,455	?
Dereg Value	\$1,346 as of today (change)	?
No. of Owners	1	?
Type of Veh	Van	?
Category	Premium Ad Car	?
Availability	Available	?

Add to Shortlist

Add to Compare

Add a Note

Posted on: 30-Nov-2017 | Last Updated on: 11-Dec-2017

Tags: Nissan Urvan, Nissan Urvan, 2008 Nissan Urvan, 2008 Nissan Urvan, Nissan, Urvan, Urvan, Used Nissan



Seller Information

Company	ABWIN Bus Pte Ltd * dealer's pricelist * 68 vehs sold 226 vehs available
Address	172 Sin Ming Drive Search cars nearby this location
Office No	69339404
Contact Person(s)	Wei Lun Dan 83233989 83213033

Hock Thye Seng @ Bt Batok - Top Notch SG Car Workshop

 Car Repair (Air Con, Dent, Engine, Everything), Repaint, Servicing. Visit Now hockthyeseng.com

 Sign up & Get \$10 free
 Email Add
 Submit Qu
 Sign Up New Account
 Forgot Password

Nissan Urvan Price Range Depreciation 2008 Vehicle Type Submit Advanced Search

Home » Used Cars » E-Cube Auto Pte Ltd » Nissan Urvan

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle

Car Tyres



Nissan Urvan

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$12,888	
Depreciation	\$22,400 /yr	?
	View models with similar depreciation	
Reg Date	10-Jul-2008	
	(6mths 28days COE left)	
Manufactured	2008	?
Mileage	360,000 km (38.2k /yr)	
Transmission	Manual	
Engine Cap	2,953 cc	
Curb Weight	1,760 kg	?
Fuel type	Diesel	
Features	Long Wheel Based. 3.0L Engine With Auto Transmission. 5 Doors.	
Accessories	Sony Player With USB Port.	
Description	Fast Deal. Price As The Condition Of The Pictures. Spacious And Robust Design For Goodies Transportation! Flexible Loans And High Trade-In Packages Are Welcome! Call Our Friendly Sales Team Now For More Information Or To Make Appointment For Viewing Now.	
COE	\$14,756	?
OMV	\$24,411	?
ARF	\$1,221	?
Dereg Value	\$849 as of today (change)	?
No. of Owners	4	?
Type of Veh	Van	
Category	-	
Availability	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 02-Nov-2017 | Last Updated on: 27-Nov-2017

Tags: Nissan Urvan, Nissan Urvan, 2008 Nissan Urvan, 2008 Nissan Urvan, Nissan, Urvan, Urvan, Used Nissan

Upfront Payment

» more Financial info

Transfer Fee	\$11	?
Down Payment	\$1,289 (change)	Maximum 90% Loan ?



Location Map



Price Analysis

Seller Information

Company	E-Cube Auto Pte Ltd	
	» dealer's pricelist	
	» 25 vehs sold 22 vehs available	
Address	615 Lorong 4 Toa Payoh #07-04	
	Search cars nearby this location	
Office No	62575757	
Contact Person(s)	Tom Lim	91995679
	Benny Low	88686660
	Allen Lim	86686660

Useful Services



Make sure of this car condition with STA Evaluation.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Don't let
your TV
screen
go black.

Compare

Alisan URUJAN C25 ABB 1063 C

- 1) Rear body outer panel (tu) — 1.500 ✓
 - 2) " " Inner wheel House Arc panel — 11X
 - 3) " " Inner Cardboard — 11X
 - 4) " " " " clips — 11C ✓
 - 5) Rear Bumper — Deep cut —
 - 6) " " Retainer — 11 — 1/2 set 11C
 - 7) " " clips — 11 ✓
 - 8) Rear mudflap (tu) — 10.1 ✓
 - 9) Rear Tyre Cover (LH) — cut —
 - 10) Rear axle shaft — 11X
 - 11) " " " Beam (2x) — 11X
 - 12) " " " Cone — 11X
 - 13) " " " oil seal — 11X
 - 14) LH Sidep Door roller guide — 11X
 - 15) LH Sidep Door roller guide stopper garnish — 11X
 - 16) LH Rear Taillamp — cut —
- Labour —
- 1) Check wiring — 80/- — 30
 - 2) Anti Rust Protection — 100/- — 50
 - 3) Interior Upholstery (Ref) — 150/- — 11X
 - 4) Panel Beating — 800/- — 780
 - 5) Paintwork — 1000/- — 600
 - 6) Remove & refill axle shaft — 150/- 11X
 - & refill axle oil

LEAD 4.10 Contingents hence notify the following of the following:

- Notify insurer before/after survey painting
- Notify third party (neighbor/parties) during resurvey
- Contingents are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Third party modification is allowed
- Survey must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____



STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #02-30 SINGAPORE 417921 (Kaki Bukit Auto hub)
TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
GST REG. NO: 201601539K CO. REG. NO: 201601539K

Our Ref: SAPL/98052/12/17

Date : 20/12/2017

To : M/S AIG Asia Pacific Insurance Pte.Ltd.
AIG Bldg 78 Shenton Way #07-16
S'pore 079120
Attn: Motor Claim Dept



Dear Sir/Mdm,

Re : Claim of repair cost & loss of use for veh no.GBB 1063-C

<u>NO</u>	<u>PRICE</u>
1.Lump Sum Repair Cost For Veh No.GBB 1063-C.....	S\$ 3263.50
2.Loss Of Use For Rental Bill NR:B33818(150X6Days)... (Plus One Waiting Day)	S\$ 963.00
3.LTA Search Fee.....	S\$ 5.35

TOTAL : S\$ 4231.85

Vivian Lau' (LKKAUTO)

From: Vivian Lau (LKKAUTO)
Sent: Wednesday, 13 December, 2017 4:35 PM
To: 'eyap@lioncityrentals.com.sg'
Cc: Zayyer (LKKAUTO); Hsiao Tong (LKKAUTO)
Subject: ACCIDENT INVOLVING SLR 1222H AND GBB 1063C ON 08/12/2017

Our Ref: CC6/LCR17023435/Uwa3

13 December 2017

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLR 1222H AND GBB 1063C ON 08/12/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Soon Hwa Foodstuff Enterprise ("the third party claimant")
of Blk 3017 Bedok North Ave 4 / Street 5 #02-04 S(18611) (address),
owner of ABB1063C (vehicle no.) hereby authorize
Stytech Auto Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. ABB1063C that was
damaged pursuant to the accident which occurred on 08/12/17 (date) along
Tampines Ave 4 X Tampines St 82 (location)
involving vehicle no/s SLR 1222H ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 17 day of Dec (month) 20 17 (year)


顺华食品供应企业
SOON HWA FOODSTUFF ENTERPRISE
Blk 3017 Bedok North Avenue 4 Street 5
#02-04 Singapore 486121

Signed by "the third party claimant"





Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

"We/I, Stytech Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 3263.50 (repair costs), S\$ 642.00 (loss of use/rental) S\$ 5.35 (search fees) for vehicle no. G8B1063C that was damaged pursuant to the accident which occurred on 08/12/17 (date) along Tampines Ave 4 X Tampines St 82 (location) involving vehicle no/s SLR 1222 H.

This is pursuant to the inspection conducted on 11-12-17 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Seon Hwa Foodstuff Enterprise ("third party claimant") of vehicle no. G8B1063C to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to G8B1063C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 22 day of Dec (month) 20 17 (year)

cks.



Signed by AIG appointed surveyor

Winston



Chopped & Signed by "the workshop"



STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #02-30 SINGAPORE 417921 (Kaki Bukit Auto hub)
TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
GST REG. NO: 201601539K CO. REG. NO: 201601539K

Our Ref: SAPL/98052/12/17

Date : 20/12/2017

To : M/S AIG Asia Pacific Insurance Pte.Ltd.
AIG Bldg 78 Shenton Way #07-16
S'pore 079120
Attn: Motor Claim Dept

Dear Sir/Mdm,

Re : Accident on 8/12/2017 involving veh nos.Gbb 1063-C & SLR 1222H
Along Tampines Ave 4 & Tampines St 82.

FINAL BILL FOR VEH NO.GBB 1063-C

DESCRIPTION

PRICE

Lump Sum Repair Cost For Veh No.GBB 1063-C.....	S\$3050.00
7% GST	S\$ 213.50

TOTAL : S\$3263.50

Yours Faithfully
STYTECH AUTO PTE.LTD.

.....
Mr.Winston Teo
9685-8843



STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #02-30 SINGAPORE 417921 (Kaki Bukit Auto hub)
 TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
 GST REG. NO: 201601539K CO. REG. NO: 201601539K

NR No: 833818

ABB1063C

Vehicle No: <u>ABF2016L</u>	Make and Type: <u>TOYOTA HIACE (Auto)</u>
Date/Time Out: <u>09/12/17 3:00pm</u>	Date/Time In: <u>16/12/17 3:30pm</u>

Fuel Gauge

E	1/4	1/2	3/4	F

EXTENSION CHARGES IS \$12.00 PER HOUR (SINGAPORE USE)
 DEPOSIT WILL BE FORFEITED IN ANY ACCIDENT/DAMAGE/FIRE & THEFT
 *NO RETURNING OF VEHICLE AFTER 6 PM & EVE / PUBLIC HOLIDAY

Hirer's Name: Soon Hwa Foodstuff Enterprise

Hirer's Address: Blk 3017 Bedok North Ave 4 /
Street 5 #02-04 S(486121)

Tel: I/C:

H/P: Age:

Driver's Name: Lee Teow SoonDriver's Address: Blk 842E Tampines St 82 #08-124Tel: 98634296 I/C: 51277860JAge: 1957Driving Licence Date: 05/06/79 Class: 3

Additional Driver's Name:

Driver's Address:

Tel: I/C:

Age:

Driving Licence Date: Class:

Guarantor's Name:

Guarantor's Address:

Tel: I/C:

Occupation: Age:

KM OUT												KM IN								
--------	--	--	--	--	--	--	--	--	--	--	--	-------	--	--	--	--	--	--	--	--

RENTALS CHARGES	AMOUNT
6 Days at \$ <u>150/-</u> per day	\$ <u>900.00</u>

Week at \$ per week	
---------------------	--

Month at \$ per mth	
---------------------	--

Insurance fee to cover hired vehicle only	
---	--

Delivery/Collection fee	
-------------------------	--

Petrol/Diesel	
---------------	--

Others	
--------	--

Sub-Total	
-----------	--

Add GST <u>7%</u>	\$ <u>63.00</u>
-------------------	-----------------

Total Nett Charges	\$ <u>963.00</u>
--------------------	------------------

*Less Total Prepayment/Deposit Received	
---	--

Balance Amount Due/Refundable	
-------------------------------	--

Add : EXTENSION CHARGES	
-------------------------	--

IMPORTANT NOTES

- * This vehicle is restricted to SINGAPORE only.
- * No refund will be given for early return or fuel left in vehicle.
- * Hirer is liable to pay all parking fees, traffic summons & other claims.
- * Hirer who carries the number of passengers or load exceeding the MPC label will have to take their own responsibilities & LTA summons.
- * In the event of vehicle breakdown due to no fuel, hirer is liable to pay \$50 service charge plus cost of fuel/diesel.
- * No replacement of vehicle in any accident, damage or loss.
- * Hirer is responsible for the first \$ 2000 excess for collision/damage/ fire or theft to first party (i.e. STYTECH AUTO PTE LTD) vehicle (including windscreen) and also first \$ 1500 excess for collision/damage/fire & theft to third party's vehicle for each and every accident & damage.

METHOD OF PAYMENT

☐ Cash ☐ Cheque No: ☐ Visa ☒ Bill Co.

Refund Received \$ By Hirer x

* In the event of the rental vehicle is not return on the date due & no contact is made to inform our company of any changes & payment after one week due. Our Company will take action & repossess the vehicle & a service charge of \$120.00 are subject to the Hirer inclusive of the overdue charges with an additional interest of 3% per month.

I/We have read the terms and conditions of the rental agreement and agree thereto:-

Hirer's Signature

顺华食品供应企业
 SOON HWA FOODSTUFF ENTERPRISE
 Blk 3017 Bedok North Avenue 4 Street 5
 #02-04 Singapore 486121

Guarantor's Signature

STYTECH AUTO PTE LTD
 Signed By

From: choon kiatt winston teo <stytech_winston@yahoo.com.sg>
Sent: Saturday, December 9, 2017 11:42 AM
To: Winston Teo
Subject: Fw: Notification of Successful Vehicle Insurance Search for Receipt No.: ITNET-00000-171209-000421
Attachments: Untitled.gif

Sent from Yahoo Mail on Android

----- Forwarded message -----

From: "LTA-VTL@lta.gov.sg" <LTA-VTL@lta.gov.sg>
To: "stytech_winston@yahoo.com.sg" <stytech_winston@yahoo.com.sg>
Sent: Sat, 9 Dec 2017 at 11:36
Subject: Notification of Successful Vehicle Insurance Search for Receipt No.: ITNET-00000-171209-000421



Notification of Successful Vehicle Insurance Search for Receipt No.: ITNET-00000-171209-000421

Dear Sir/Madam

We wish to inform you that your transaction on "Enquire Vehicle Insurance Particulars" performed on 09 Dec 2017 was successful and the Receipt No. is ITNET-00000-171209-000421.

2. The details of the search results are as follow:

Vehicle No.	Search Date	Search Time	Search Result
SLR1222H	08 Dec 2017	08:45:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.

3. Please contact our customer service officers at tel : 1800-CALL LTA (1800-2255 582) should you require further assistance.
4. Please do not reply to this auto-generated e-mail. If you have any feedback, please go to www.lta.gov.sg/feedback. You can also visit www.onemotoring.com.sg for more information.
5. Thank you.

If you are not the intended recipient of this communication, please delete it.

As it may contain confidential or official information, do not retain it or disclose the contents to any person as it may be an offence under the Official Secrets Act.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2017 Edit Reg		11 Dec 2017 00:00 Edit Adj Rpt	S\$3,050.00 Edit Estimates	S\$3,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	SOON HWA FOODSTUFF ENTERPRISE, Co. Reg. No.: 52872868K		
Vehicle Reg. No.:	GBB1063C	Date of Loss:	08/12/2017 00:00 - :59
Claim Type:	TP / 9762237674SG	Policy/Cover Note No.:	0999995070
Vehicle Reg. No. (Insured):	SLR1222H	Policy No. (Claimant):	2100087387-09000
	Excess:		
Repairer:	Stytech Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub, 417921 Kaki Bukit - Tel: 64448125		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (12/12/2017): TP GIA REPORT

☐ **ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBB1063C (9762237674SG)
[SLR1222H]
TP
SOON HWA FOODSTUFF ENTERPRISE
Dec 8 2017 12:00AM
[LCRF PTE LTD]
Stytech Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		Use Viewer	
Letters/Correspondences										1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown										Edit	
Assessment Reports										1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)								Thumbnail		Print	
1	12/12/17 17:12	Accident Statement From: SC - Reg. No: SLR1222H, Claimant: LCRF PTE LTD										Load HTM	
Photos/Images										3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print	
1	11/12/17 14:21	Chassis Number										Load JPG <input checked="" type="checkbox"/>	
2	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
3	11/12/17 14:21	Odometer Reading										Load JPG <input checked="" type="checkbox"/>	
4	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
5	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
6	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
7	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
8	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
9	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
10	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
11	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
12	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
13	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
14	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
15	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
16	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
17	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
18	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
19	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
20	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
21	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
22	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
23	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
24	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
25	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
26	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
27	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
28	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
29	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
30	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
31	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	
32	11/12/17 14:21	General View										Load JPG <input checked="" type="checkbox"/>	

33	11/12/17 14:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	11/12/17 14:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	11/12/17 14:21	General View	1	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/12/17 09:13	TP GIA REPORT	1	Load PDF	
2	13/12/17 16:39	Email letter to OIACCIDENT INVOLVING SLR 1222H AND GBB 1063C ON 08.12.2017	1	Load PDF	
3	28/12/17 10:05	WORKSHOP INVOICE	1	Load PDF	
4	28/12/17 10:05	AUTHORISATION TO ACT FORM	1	Load PDF	
5	28/12/17 10:05	RELEASE VOUCHER	1	Load PDF	
6	28/12/17 10:05	RENTAL RECEIPT	1	Load PDF	
7	28/12/17 10:05	LTA SEARCH	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid #ccc; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLR1222H (Insd veh)	Model:	NISSAN URVAN 3.0 5DR
	GBB1063C (TP veh)		5MT ABS A/B 2WD (M)
Date of Accident:	08/12/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	7,339.13
Final Repair Cost	:	\$	3,263.50
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	642.00 6 days
LTA / GIA Search Fee	:	\$	5.35
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,910.85
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____100____(%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No:	
BOLA Liability: ____%(%)		Assessed Liability (*): ____%(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Stytech Auto Pte Ltd	:	\$ 3,910.85
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

28 Dec
2017

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR17023435/UWA3Q2

Date: 28/12/2017

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995070
 Claimant Vehicle No : GBB1063C Insured Vehicle No : SLR1222H
 Date of Loss: 08/12/2017 Nature of Claim: TP Claim No: 9762237674SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBB1063C
 Make & Model: NISSAN URVAN, 3.0 5DR 5MT ABS A/B 2WD (M) Engine No: ZD30157542K
 Reg. Date: 21/07/2008 (Man. Year: 2008) Chassis No: JN1MG2E25Z0750135
 Colour: Grey Odometer: 392107 km
 Engine Capacity: 2953 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm
 Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,609.00	2,361.81	2,247.19	48.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	1,460.00	790.00	35.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,859.00	3,821.81	3,037.19	44.28
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	6,859.00	3,050.00	3,809.00	55.53
+ GST 7.00/7.00% (S\$)	480.13	213.50	266.63	55.53
Nett Amount (S\$)	7,339.13	3,263.50	4,075.63	55.53
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		3,910.85		

INSPECTION

Date of Assignment: 11/12/2017
 Date Inspected: 11/12/2017 Inspected At: Stytech Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit
 Autohub
 Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BODY PANEL N/S	Badly Dented	2,010.30 F	*2,010.30 FL
2	1		*REAR BODY INNER WHEEL HOUSE PANEL N/S	Repair	442.60 F	*- FL
3	1		*REAR BODY INNER CARDBOARD N/S	Not Necessary	178.00 F	*- FL
4	1		*SET REAR BODY INNER CARDBOARD CLIPS N/S	Necessary	30.00 FS	*30.00 FS
5	1		*REAR BUMPER	Deep Cut	733.60 F	*683.00 FL
6	1		*REAR BUMPER SIDE RETAINERS	N/S Bent	28.40 FS	*14.20 FS
7	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
8	1		*REAR MUDFLAP N/S	Torn	113.60 FS	*113.60 FS
9	1		*REAR TYRE COVER N/S	Cut	80.00 FS	*80.00 FS
10	1		*REAR EXLE SHAFT	Not Necessary	338.20 FS	*- FS
11	1		*REAR AXLE SHAFT BEARING	Not Necessary	82.00 FS	*- FS
12	1		*REAR AXLE SHAFT CONE	Not Necessary	14.00 FS	*- FS
13	1		*REAR AXLE SHAFT OIL SEAL	Not Necessary	18.00 FS	*- FS
14	1		*SLIDING DOOR ROLLER GUIDE N/S	Not Necessary	271.40 FS	*- FS
15	1		*SLIDING DOOR ROLLER GUIDE STOPPER GARNISH N/S	Not Necessary	30.20 FS	*- FS
16	1		*TAILLAMP N/S	Cracked	208.70 FS	*208.70 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,609.00	3,169.80
- List Item Discount on L Items 0.00/30.00% (S\$)	0.00	807.99
Total Parts (S\$)	4,609.00	2,361.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO SPRAY ANTI RUST PROOFING	New	100.00	50.00
3	TO DISMANTLE & REFIX UPHOLSTERY	New	150.00	0.00
4	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	800.00	780.00
5	TO PUTTY & SPRAY PAINTING	New	1,000.00	600.00
6	TO DISMANTLE & REFIX AXLE SHAFT	New	120.00	0.00
Gross Labour Cost (S\$)			2,250.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >