

INS. CASE OWNER

Calistha

CC 6 / III170

23439, Uwa39

LKK:
IDAC:

Simulator

Marinus

DOI

ASSIGNMENT

11/12/17

Date / Time

11/12/17

Registered in Merimen

11/12/17

Pre-assign / CCU / FTE



Insured Vehicle No.

SJT39392

Name of Insured

Kok Yuen Fah

Insured Tel No.

HP:

Excess Sec II :SS

D.O.A:

8/12/17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Oh Jia Hao Elson

Driver Tel No.:

94363699

(V/L: YES / NO)

Claim No.:

merit/3172

Policy No.:

M489364

Make / Model:

Honda Civic

Place of Accident:

Jongy Pier Rd

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SK6 18539



INSRS:

WSP:

Tel:

Liability:

RMKS:

Choo motor

19376



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with Jagan.

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. 28c

Repair Cost:

SS

8500.00

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

660.00 (5.60 x 11 days)

Loss of Income (LOI):

SS

(5

x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

2.00

Medical

SS

Disbursement:

SS

Legal Cost

SS

Total:

SS

9162.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

9162.00

Name 1:

Choo Motor Spray Painter

Payee 2. (Strike if N.A.)

SS

Name 2:

Payee 3. (Strike if N.A.)

SS

Name 3:

If NO or B 28, Ass. Lia: 100%

O2D involved in 2.00

O2D is the loss

COPY SENT
15/1/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection

Bal. or Market Value:			
IDAC Accident Report:		Consistent? :	Yes or No
GIA / PR Seen:		Consistent? :	Yes or No
Est. Repairs:	9	days	Res.: Yes or No
Lum Sum:	20	%	3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Veh No: SKE 1235 Yr Regn: 2 12
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA1
Make: Hyundai Elantra 1591
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 74028 T/Radio: Insured / Std / NI / NA
Eng/No: KMHDDH41CMCU423423
Cr/No: Good / Fair / Poor / Burnt
Gen. Cond: In order / Jammed / Leaked / Burnt or
Steering: In order / Jammed / Leaked / Burnt or
Brake: NI / S/Rim / STD A/Rim or
Modi: 205/55R16
Tyre Size: F: 205/55R16
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 8/12/17	D.O.I. 11/12/17
Survey held at	

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear n/s & Ltr o/s
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	LTA 31913

net 1287

have G1A already

20/12/17 Confined L/S & SSW with Sh.

(20) - ~~4~~ 2531.48
77%)

DateTime: File Page 10?

☐: Prel. Report

11

☐ : Final Report

Date/Time: File Return to?

29

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Add Fee: : Site Insp (\$

☐ Site Insp (\$

☐ Interview (\$

Tech. Invs (\$)

Weekend (\$)	
--------------	--

28

Contd.

152



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC6/III17023439/Uwa3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 11-12-2017		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJT 3939Z	Veh. Inspected	SKE 1853S	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/12/2017	Inspection Date	11/12/2017	
Survey held at	CHOO MOTOR SPRAY PAINTER 1 KAKI BUKIT AVENUE 6 #01-39 AUTOBAY@KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SGCARMART.COM

THE ONLY PLACE FOR SMART CAR BUYERS

Vote for your favourite car!

Car of the Year

All

Car Make or Model

Search

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS & TIPS

Sign up & Email Add

Submit Qu

Sign up New Account

Forgot Password

Sign up & Email Add

Submit Qu

Sign up New Account

Forgot Password

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Well Maintained Civic With Ultra Low Depreciation.



Well Maintained Civic. Low Depreciation At \$7700. PARF Rebate \$8057. Spacious. Direct Owner StarAd.

Free VICOM evaluation

Free grooming and 6 months maintenance

In-house workshop ensures quality service

Member of SVTA and hire purchase association

100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

◀ Back (1 2) Next ▶

Sort by Date Posted

20 results/page

21 vehicles

Hyundai Elantra

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Hyundai Elantra		Any	Any	2012	Any	Any	Any	Available
	Hyundai Elantra	1.6A Elite Sunroof	\$50,666	\$9,810 /yr	18-May-2012	1,591 cc	-	Sedan	Available
Only 1 Owner! Highest Specs Elite Model With Sunroof. Very Well Maintained In Excellent Pristine Condition Assured! Guaranteed No Repair Needed. Warranty Will Be Provided. Various Flexible Loan Scheme...									
Posted: 10-Dec-2017 Tags: 2012 Hyundai Elantra, 2012 Hyundai Elantra, Hyundai Elantra, Hyundai Elantra, Hyundai, Elantra, Elantra, Used Hyundai Details									
	Hyundai Elantra	1.6A (OPC)	\$43,800	\$8,960 /yr	13-Mar-2012	1,591 cc	82,483 km	Sedan	Available
Cheapest In Market, 1 Owner, Well Maintained, Fully Maintained By KOMOCO, Low Mileage Done At 82483KM, Can Convert To Normal Plate, View To Believe, Price Negotiable.									
Posted: 10-Dec-2017 Tags: 2012 Hyundai Elantra, 2012 Hyundai Elantra, Hyundai Elantra, Hyundai Elantra, Hyundai, Elantra, Elantra, Used Hyundai Details									
	Hyundai Elantra	1.6A Elite	\$54,500	\$9,810 /yr	17-Oct-2012	1,591 cc	68,515 km	Sedan	Available
Agent Regular Maintained With Service Records, Genuine Low Mileage, New Tyres, Original Excellent Condition, Low Maintenance And Worth Value Affordable Sedan, Price And Down Payment Negotiable.									
Posted: 09-Dec-2017 Tags: 2012 Hyundai Elantra, 2012 Hyundai Elantra, Hyundai Elantra, Hyundai Elantra, Hyundai, Elantra, Elantra, Used Hyundai Details									
	Hyundai Elantra	1.6A Elite	\$46,800	\$9,670 /yr	12-Jan-2012	1,591 cc	55,000 km	Sedan	Available
1 Owner, Original Condition, Serviced/ Maintained By Agent (Komoco), Low Mileage Of 55K Km Done, Sleek And Futuristic Design, View And Judge The Condition For Yourself.									
Posted: 09-Dec-2017 Tags: 2012 Hyundai Elantra, 2012 Hyundai Elantra, Hyundai Elantra, Hyundai Elantra, Hyundai, Elantra, Elantra, Used Hyundai Details									
Car Buying Car Selling Car Aftermarket Buying a pre-owned car, but Unsure of its Condition? Get, STA Car Evaluation									
Car Ownership On The Move Lifestyle									
	Hyundai Elantra	1.6A	\$49,800	\$9,380 /yr	26-Jun-2012	1,591 cc	98,000 km	Sedan	Available
Fully Serviced By Komoco Motors, Road Tax Till June/2018, No Repair Needed. Excellent Condition. Bank Loan In-house Loan Available. Trade In Welcome.									
Posted: 06-Dec-2017 Tags: 2012 Hyundai Elantra, 2012 Hyundai Elantra, Hyundai Elantra, Hyundai Elantra, Hyundai, Elantra, Elantra, Used Hyundai Details									
	Hyundai Elantra	1.6A	\$48,800	\$9,610 /yr	09-Jun-2012	1,591 cc	73,000 km	Sedan	Available
1 Owner! Low Mileage! Powerful And Responsive, Best Known For It's Fuel Saving Capabilities! Classic White Color That Is Elegant And Popular Among Many! Huge Interior. Extremely Good Condition That Yo...									
Tan Wei Auto Pte Ltd Posted: 08-Dec-2017 Tags: 2012 Hyundai Elantra, 2012 Hyundai Elantra, Hyundai Elantra, Hyundai Elantra, Hyundai, Elantra, Elantra, Used Hyundai Details									
Compare	Hyundai Elantra	1.6A Elite Sunroof	\$51,300	\$9,520 /yr	28-Jul-2012	1,591 cc	65,391 km	Sedan	Available

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	1937G
Vehicle Details	
Vehicle No.	SKE18535
Vehicle to be Exported	No
Intended De-registration Date	11 Dec 2017
Vehicle Make	HYUNDAI
Vehicle Model	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour	Silver
Manufacturing Year	2012
Engine No.	G4FGCU467009
Chassis No.	KMHDH41CMCU423423
Maximum Power Output	95.6 kW (128 bhp)
Open Market Value	\$14,112.00
Original Registration Date	14 Feb 2012
First Registration Date	14 Feb 2012
Transfer Count	0
Actual ARF Paid	\$14,112.00 7058
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	13 Feb 2022
PARF Rebate Amount	\$9,878.00
Intended COE Rebate Details	
COE Expiry Date	13 Feb 2022
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$52,809.00
COE Rebate Amount	\$22,035.00
Total Rebate Amount	\$31,913.00

The information contained herein is correct as at 11 Dec 2017

OK

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Co. Reg No: 22736900M

Tel No: 67452063 / 67467158 Fax No: 67458520

Not Approved
Under
1/5 @ 8500/2
9 day.

Qty

Particular

SEI 8535

Amount S\$

List Item:

1PCS BOOTLID

Best/suc \$1048.00 ✓

1PCS BOOTLID 'H' LOGO

nr \$34.10 —

1PCS BOOTLID HYUNDAI EMBLEM

nr \$32.00 —

1PCS BOOTLID ELANTRA EMBLEM

nr \$32.00 ✓

1PCS BOOTLID ELITE

nr \$55.40 ✓

1PCS BOOTLID INNER LOCK

11 \$162.70 X

1PCS BOOTLID LOCK STRIKER

11 \$86.20 X

1PCS BOOTLID WEATHERSTRIP

nr / twi \$115.20 ✓

2PCS BOOTLID REFLECTORS @\$238.40

11 \$476.80 X

2PCS BOOTLID STOPPER @\$12.50

11 \$25.00 X

1PCS BOOTLID INNER TRIM

11 \$192.80 X

1SET BOOTLID INNER TRIM CLIPS

11 \$40.00 X

2PCS BOOTLID LICENCE LAMPS @\$62.00

11 \$124.00 X

2PCS BOOTLID HINGES @\$163.20

11 \$326.40 X

1PCS REAR BUMPER

Dis \$531.00 —

1PCS REAR BUMPER REINFORCEMENT

one \$341.50 —

2PCS REAR BUMPER REINFORCEMENT BRACKETS @\$55.80

11 \$111.60 X

2PCS REAR BUMPER SIDE RETAINERS @\$45.50

but \$91.00 —

1SET REAR BUMPER CLIPS

nr \$50.00 —

2PCS REAR BUMPER REFLECTORS @\$43.00

nr/sone \$86.00 1pc

2PCS REAR BUMPER SIDE ATTACHMENTS @\$25.00

11 \$50.00 X

2PCS TAILLAMPS @\$384.50

nr/sone \$769.00 1pc

2PCS TAILLAMP HOUSING PANELS @\$145.50

1 \$291.00 X

(20%)

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Co. Reg No: 22736900M

Tel No: 67452063 / 67467158 Fax No: 67458520

<u>Qty</u>	<u>Particular</u>	<u>Amount S\$</u>
<u>List Item:</u>		
1PCS	REAR END PANEL	5.04gms \$442.80 ✓
1PCS	REAR END PANEL TOP GARNISH	twi \$88.60 ✓
1PCS	REAR FLOOR PANEL	n \$803.00 x
1PCS	REAR FLOOR PANEL TOP BOARD	merged/ae \$272.00 ✓
2PCS	REAR FLOOR PANEL SIDE MEMBERS @\$245.00	17 \$490.00 x
1PCS	REAR FLOOR PANEL TOOLS SPONGE TRAY	17 \$266.50 x
1PCS	REAR WINDSCREEN MOULDING	17 \$66.50 x
2PCS	REAR FENDERS @\$781.30	n \$1562.60 x
2PCS	REAR FENDER INNER TRIMS @\$182.50	17 \$365.00 x
1SET	REAR FENDER INNER TRIMS CLIPS	17 \$50.00 x
2PCS	REAR FENDER SPLASH SHIELDS @\$42.80	17 \$85.60 x
2PCS	REAR WHEEL HOUSING PANELS @\$688.50	17 \$1377.00 x
2PCS	REAR FENDER AIR VENTS @\$32.50	17 \$65.00 x
1PCS	REAR EXHAUST SILENCER	17 \$489.50 x
1PCS	REAR EXHAUST HEAT SHIELD	17 \$115.00 x
2PCS	REAR EXHAUST MOUNTINGS @\$32.20	17 \$64.40 x
1PCS	REAR BUMPER LOCK SENSOR	17 \$103.00 x
1PCS	REAR BUMPER LOCK SENSOR WIREHARNESS	17 \$168.00 x
2PCS	REAR MUDFLAPS @\$66.80	17 \$133.60 x
2PCS	REAR CHASSIS MEMBERS @\$966.30	17 \$1932.60 x
1PCS	CENTRE EXHAUST PIPE	17 \$685.30 x
1PCS	FRONT BUMPER	Dis \$682.50 ✓
2PCS	FRONT BUMPER SIDE RETAINERS @\$45.50	sent \$91.00 ✓

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Co. Reg No: 22736900M

Tel No: 67452063 / 67467158 Fax No: 67458520

<u>Qty</u>	<u>Particular</u>	<u>Amount S\$</u>
<u>List Item:</u>		
1PCS	FRONT BUMPER REINFORCEMENT	End \$382.00 ✓
2PCS	FRONT BUMPER BRACKETS @\$32.50	o/s twi \$65.00 1PC
1PCS	FRONT BUMPER CENTRE GRILLE	Tw1 \$185.00 ✓
1PCS	FRONT BUMPER SPONGE	Cne \$129.60 ✓
1SET	FRONT BUMPER CLIPS	ner \$50.00 ✓
2PCS	FRONT BUMPER FOG LAMPS @\$193.00	o/s cne \$386.00 ✓
1PCS	FRONT GRILLE	Cne \$272.40 ✓
1PCS	FRONT GRILLE LOGO	ner \$34.10 ✓
1PCS	HEADLAMP o/s 1345.10	Cne \$1645.00 ✓
1PCS	BONNET	~ \$1001.80 X
2PCS	BONNET HINGES @\$66.50	11 \$133.00 X
1PCS	BONNET INNER LOCK	11 \$66.80 X
1PCS	BONNET LOCK CABLE	11 \$47.50 X
1PCS	BONNET INNER RUBBER BEADING	11 \$38.80 X
1PCS	FRONT SUPPORT PANEL	Surf/cne \$945.50 ✓
1PCS	AIR CON CONDENSER	11 \$986.00 X
2PCS	AIRCON CONDENSER TOP MOUNTINGS @\$18.00	11 \$36.00 X
1PCS	AIR CON SUCTION PIPE	11 \$250.80 X
1PCS	AIR CON DISCHARGE PIPE	11 \$298.60 X
1PCS	AIR CON LIQUID PIPE	11 \$198.20 X
1PCS	RADIATOR	11 \$768.00 X
2PCS	RADIATOR TOP MOUNTINGS @\$28.00	11 \$56.00 X
1PCS	RADIATOR FAN ASSY	11 \$589.00 X

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Co. Reg No: 22736900M

Tel No: 67452063 / 67467158 Fax No: 67458520

Qty	Particular	Amount S\$
-----	------------	------------

List Item:

1PCS WASHER : TANK

ee \$165.00 ✓

1PCS AIR DUCT ASSY

11 \$266.00 X

2PCS FRONT FENDERS @\$617.09

20% 0/530/12 \$1234.18/20

2PCS FRONT FENDER INNER SHIELDS @\$122.50

11 \$245.00 X

List Item Total:

\$25,946.48

887889
7103-11:

Special Nett Item:

1PCS FRONT LICENCE PLATE W/HOLDER

11 \$50.00 X

1BOL RADIATOR COOLANT

11 \$40.00 ✓

1BOL AIR CON OIL

11 \$40.00 X

1SET REAR BUMPER REVERSE SENSOR

shd \$280.00 200

1SET REAR REVERSE CAMERA

11 \$600.00 X

1SET REAR FLOOR PANEL INSULATOR

11 \$300.00 X

1PCS REAR WINDSCREEN SEALANT

11 \$50.00 X

1PCS REAR LICENCE PLATE W/HOLDER

11 \$50.00 X

1PCS REAR END PANEL SEALANT

11 \$50.00 ✓

Special Nett Total:

\$1460.00

290

Labour Charge:

TOWING CHARGE.

11 \$65.00 X

TO CHECK WIRING.

\$100.00 30

TO DISMANTLE & REPLACING REVERSE SENSOR.

\$100.00 10

TO REFILL AIR CON GAS.

\$150.00 100

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Co. Reg No: 22736900M

Tel No: 67452063 / 67467158 Fax No: 67458520

<u>Qty</u>	<u>Particular</u>	<u>Amount S\$</u>
<u>Labour Charge:</u>		
	TO SPRAY RUST PROOFING.	\$250.00 80
11	TO DISMANTLE & REFIX PETROL TANK.	\$100.00 X
11	TO MOUNT VEHICLE ON TO CAR 'O' LINER.	\$380.00 X
11	TO CONDUCT WHEEL ALIGNMENT.	\$100.00 X
11	TO DISMANTLE & REFIX REAR WINDSCREEN.	\$150.00 X
Repull	TO SPRAY RUST PROOFING.	\$250.00 X
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.	\$150.00 80
11	TO DISMANTLE & REPLACING REAR EXHAUST.	\$150.00 X
11	TO DISMANTLE & REIX REAR UNDERCARRIAGE.	\$380.00 X
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN	
	& REPLACING PARTS.	\$3800.00 / 400
	TO PUTTY & SPRAY PAINTING.	\$3500.00 / 500
Labour Charge Total:		

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$37,031.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair modification(s) is allowed
- Supplementary claim(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

View Received Message

This mail is associated with :

***SKE1853S (MC2017/3172)**
[SJT3939Z]

TP
ZHOU XINGE
Dec 8 2017 7:00AM
[KOK YUEN FAH]
Choo Motor Spray Painter

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 15/01/2018 09:25 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9162.00) - SKE1853S - Claim Handler: Lalitha Krishnan

Approved:9162.00.

DOCUMENTS SUMMARY

There are no documents.

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Tel No: 67465405 / 67465376 Fax No: 67458520

Tax Reg No: 22736900M

Date : 27.12.2017

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

Attn: Motor Claim Department

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES : SKE 1853S / SJT 3939Z AND OTHER ON 08.12.2017

We are the authorized repair workshop for the owner of motor vehicle no: **SKE 1853S**, which was involved in the captioned accident with your insured vehicle no: **SJT 3939Z**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$ 8,500.00
2) Loss of Use (9 days + 2 Sunday X S\$60)	\$ 660.00
3) GIA Search Fee	\$ 2.00
	<u>\$ 9,162.00</u>

We enclosed herewith the following documents to support the claims:

- | | |
|--------------------------|------------------------------------|
| a) Final Repair Invoice | b) Vehicle Registration Log Card |
| c) GIA Report | d) I/C & Driving Licence |
| e) Insurance Certificate | f) Letter of Authorisation, etc... |
| g) GIA Search Result | |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,

Jason Tang (jason@fastechauto.com.sg)

For Choo Motor Spray Painter

DATE : 27.12.2017

TO : India International Insurance Pte Ltd.

RE : ACCIDENT INVOLVING VEHICLE NO. 3KE 1853S / SJT 3939Z
And other
ALONG Jurong Pier Rd > Jurong Island.
ON 08.12.2017.

I/We, Zhou Xinge
of (NRIC No./ROC No.) S7061937G
of Blk 685B # 15-163 Jurong West Street 64 (S) 642685
owner of vehicle no. 3KE 1853S in consideration of M/s **CHOO MOTOR SPRAY PAINTER** repairing my/our vehicle 3KE 1853S at my/our instruction and hereby authorise M/s **CHOO MOTOR SPRAY PAINTER** to demand claim settle receive whatever amount settled/payable by the Insurance Company and/or third party or to commence legal proceedings, if necessary, under my name, for the cost of repairs, car rental and/or loss of use, etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and all claimed and/or settled shall belong to them absolutely.

I/We further agree and undertake to indemnify them against the abovementioned claim cost which may arisen therewith.

Signature of Owner : Zhi

Name of Owner : Zhou Xinge

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MC2017/3172
Claimant Ref: SKE18538

We/I, Choo Motor Spray Painter ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 8500.00 (repair cost), S\$ 660.00 (loss of use/rental), S\$ 2.00 (search fee), vehicle no. SKE18538 that was damaged pursuant to the accident which occurred on 08-12-2017 (date) at Jurong Pier Rd - Jurong Island (location) involving vehicle no. STL3131Z (insured vehicle). This is pursuant to the inspection conducted on 11/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Zhou Xinge ("the third party claimant") of vehicle no. SKE18538 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKE18538 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 9162.00 to Choo Motor Spray Painter.

Dated this 15 day of 1 20 18

CLAIMANT:

Signature: _____

Name: _____

NRIC: _____

Address: _____

Nationality: _____

Occupation: _____

Signed by "the workshop" (with chop)

CHOO MOTOR SPRAY PAINTER

22736900M

1 KAM BUKIT AVE 6 #01-29

AWOBBAY SINGAPORE 47883

WITNESS:

Signature: _____

Name: _____

NRIC: _____

Address: _____

Nationality: _____

Occupation: _____

CR3
Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE.
51 Ubi Ave 1, #01-23
Paya Ubi Industrial Park
Singapore 408933
Tel: 6256 3561

TAX INVOICE

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Tel No: 67465405 / 67465376 Fax No: 67458520

Tax Reg No: 22736900M

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

Attn : Motor Claim Department

Tax Invoice : 20023

Date : 27.12.2017

Vehicle No : SKE 1853S

Make/Model : HYUNDAI ELANTRA

Chassis/Eng# :

Accident Date : 08.12.2017

Claim No :

Reference : 1117 -20023

Policy No :

		Amount
To proceed on lump sum repair	S\$	8500.00

E. & O. E.

Total : S\$

8500.00


for CHOO MOTOR SPRAY PAINTER

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-17-183639
Date of Request: 08/12/2017

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 08/12/2017
Enquiry By KCA USER 1
TP Vehicle No. SJT3939Z
Accident Date 08/12/2017

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJT3939Z	India International Insurance Pte Ltd	18/01/2017-17/01/2018	63476100

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-17-183639
Date of Request: 08/12/2017

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 08/12/2017
Enquiry By: KCA USER 1
TP Vehicle No: SJT3939Z
Accident Date: 08/12/2017

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2017 Edit Reg		11 Dec 2017 00:00 Edit Adj Rpt	\$8,500.00 Edit Estimates	\$8,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:		KOK YUEN FAH, ID: S1280940I							
Main Claimant:		ZHOU XINGE, ID: S7061937G							
Vehicle Reg. No.:		SKE1853S	Date of Loss:	08/12/2017 07:00 - :59					
Claim Type:		TP / MC2017/3172	Policy/Cover Note No.:	M489364					
Vehicle Reg. No. (Insured):		SJT3939Z	Policy No. (Claimant):	S053123644-05					
		Excess:							
Repairer:		Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67453897							
Handling Insurer:		India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Lalitha Krishnan - 6347 6139]							
Claimant's Insurer:		NTUC Income Insurance Co-operative Ltd (HQ) - Tel:							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/12/2017]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (15/01/2018): Alert - Adj Mandate Approved (\$9162.00) - SKE1853S - Claim Handler: Lalitha Kri... - III_SG (14/12/2017): Alert - Adj Mandate Approved (\$0.00) - SKE1853S - Claim Handler: Lalitha Krishn...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKE1853S (MC2017/3172)**
[SJT3939Z]
TP
ZHOU XINGE
Dec 8 2017 7:00AM
[KOK YUEN FAH]
Choo Motor Spray Painter

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/12/17 09:11	TP GIA REPORT	 Load PDF	
2	12/01/18 14:55	WORKSHOP INVOICE	 Load PDF	
3	12/01/18 14:55	GIA SEARCH	 Load PDF	
4	12/01/18 14:55	LOD	 Load PDF	
5	17/01/18 12:41	DISCHARGE VOUCHER	 Load PDF	
6	17/01/18 12:41	AUTHORISATION TO ACT FORM	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	12/12/17 08:46	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III17023439/UWA3Q2

Date: 17/01/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: M489364

Claimant Vehicle No: SKE1853S

Insured Vehicle No: SJT3939Z

Date of Loss: 08/12/2017

Nature of Claim: TP

Claim No: MC2017/3172

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKE1853S

Make & Model: HYUNDAI ELANTRA, 1.6 D/AB 2WD 4DR (A)

Engine No: G4FGCU467009

Reg. Date: 14/02/2012 (Man. Year: 2012)

Chassis No: KMHDH41CMCU423423

Colour: Silver

Odometer: 74028 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,406.48	7,393.11	20,013.37	73.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,625.00	3,240.00	6,385.00	66.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,031.48	10,633.11	26,398.37	71.29
Approved Total (Overridden) (S\$)		8,500.00		
Nett Amount (S\$)	37,031.48	8,500.00	28,531.48	77.05
+ Loss of Use (11.0 x S\$60.00/day) (S\$)		660.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,162.00		

INSPECTION

Date of Assignment: 11/12/2017

Date Inspected: 11/12/2017 Inspected At:

Choo Motor Spray Painter (HQ)

1 Kaki Bukit Avenue 6, #01-39 AutoBay @

Kaki Bukit

Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: MARCUS CHUA**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jan 2018)
Parts:	143	HYUNDAI ELANTRA 1.6 D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE1853S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Buckled	1,048.00 F	*1,048.00 FL
2	1		*BOOTLID H LOGO	Necessary	34.10 F	*34.10 FL
3	1		*BOOTLID HYUNDAI EMBLEM	Necessary	32.00 F	*32.00 FL
4	1		*BOOTLID ELANTRA EMBLEM	Necessary	32.00 F	*32.00 FL
5	1		*BOOTLID ELITE	Necessary	55.40 F	*55.40 FL
6	1		*BOOTLID INNER LOCK	Not Necessary	162.70 F	*- FL
7	1		*BOOTLID LOCK STRIKER	Not Necessary	86.20 F	*- FL
8	1		*BOOTLID WEATHERSTRIP	Necessary / Twisted	115.20 F	*115.20 FL
9	2		*BOOTLID REFLECTORS	Not Necessary	476.80 F	*- FL
10	2		*BOOTLID STOPPER	Not Necessary	25.00 F	*- FL
11	1		*BOOTLID INNER TRIM	Not Necessary	192.80 F	*- FL
12	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	40.00 F	*- FL
13	2		*BOOTLID LICENCE LAMPS	Not Necessary	124.00 F	*- FL
14	2		*BOOTLID HINGES	Not Necessary	326.40 F	*- FL
15	1		*REAR BUMPER	Distorted	531.00 F	*531.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Cracked	341.50 F	*341.50 FL
17	2		*REAR BUMPER REINFORCEMENT BRACKETS	Not Necessary	111.60 F	*- FL
18	2		*REAR BUMPER SIDE RETAINERS	Bent	91.00 F	*91.00 FL
19	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
20	1		*REAR BUMPER REFLECTORS	N/S Cracked	86.00 F	*43.00 FL
21	2		*REAR BUMPER SIDE ATTACHMENTS	Not Necessary	50.00 F	*- FL
22	1		*TAILLAMPS	N/S Cracked	769.00 F	*384.50 FL
23	2		*TAILLAMP HOUSING PANELS	Repair	291.00 F	*- FL
24	1		*REAR END PANEL	Badly Dented	442.80 F	*442.80 FL
25	1		*REAR END PANEL TOP GARNISH	Twisted	88.60 F	*88.60 FL
26	1		*REAR FLOOR PANEL	Repair	803.00 F	*- FL
27	1		*REAR FLOOR PANEL TOP BOARD	Warped / Deformed	272.00 F	*272.00 FL
28	2		*REAR FLOOR PANEL SIDE MEMBERS	Not Necessary	490.00 F	*- FL
29	1		*REAR FLOOR PANEL TOOLS SPONGE TRAY	Not Necessary	266.50 F	*- FL
30	1		*REAR WINDSCREEN MOULDING	Not Necessary	66.50 F	*- FL
31	2		*REAR FENDERS	Repair	1,562.60 F	*- FL
32	2		*REAR FENDER INNER TRIMS	Not Necessary	365.00 F	*- FL
33	1		*SET REAR FENDER INNER TRIMS CLIPS	Not Necessary	50.00 F	*- FL
34	2		*REAR FENDER SPLASH SHIELDS	Not Necessary	85.60 F	*- FL
35	2		*REAR WHEEL HOUSING PANELS	Not Necessary	1,377.00 F	*- FL
36	2		*REAR FENDER AIR VENTS	Not Necessary	65.00 F	*- FL
37	1		*REAR EXHAUST SILENCER	Not Necessary	489.50 F	*- FL
38	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	115.00 F	*- FL
39	2		*REAR EXHAUST MOUNTINGS	Not Necessary	64.40 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR BUMPER LOCK SENSOR	Not Necessary	103.00 F	*- FL
41	1		*REAR BUMPER LOCK SENSOR WIREHARNES	Not Necessary	168.00 F	*- FL
42	2		*REAR MUDFLAPS	Not Necessary	133.60 F	*- FL
43	2		*REAR CHASSIS MEMBERS	Not Necessary	1,932.60 F	*- FL
44	1		*CENTRE EXHAUST PIPE	Not Necessary	685.30 F	*- FL
45	1		*FRONT BUMPER	Distorted	682.50 F	*682.50 FL
46	2		*FRONT BUMPER SIDE RETAINERS	Bent	91.00 F	*91.00 FL
47	1		*FRONT BUMPER REINFORCEMENT	Bent	382.00 F	*382.00 FL
48	1		*FRONT BUMPER BRACKETS	O/S Twisted	65.00 F	*32.50 FL
49	1		*FRONT BUMPER CENTRE GRILLE	Twisted	185.00 F	*185.00 FL
50	1		*FRONT BUMPER SPONGE	Cracked	129.60 F	*129.60 FL
51	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
52	2		*FRONT BUMPER FOG LAMPS	Cracked	386.00 F	*386.00 FL
53	1		*FRONT GRILLE	Cracked	272.40 F	*272.40 FL
54	1		*FRONT GRILLE LOGO	Necessary	34.10 F	*34.10 FL
55	1		*HEADLAMP O/S	Cracked	1,645.00 F	*1,345.10 FL
56	1		*BONNET	Repair	1,001.80 F	*- FL
57	1		*BONNET HINGES	Not Necessary	133.00 F	*- FL
58	1		*BONNET INNER LOCK	Not Necessary	66.80 F	*- FL
59	1		*BONNET LOCK CABLE	Not Necessary	47.50 F	*- FL
60	1		*BONNET INNER RUBBER BEADING	Not Necessary	38.80 F	*- FL
61	1		*FRONT SUPPORT PANEL	Bent / Cracked	945.50 F	*945.50 FL
62	1		*AIR CON CONDENSER	Not Necessary	986.00 F	*- FL
63	2		*AIR CON CONDENSER TOP MOUNTING	Not Necessary	36.00 F	*- FL
64	1		*AIR CON SUCTION PIPE	Not Necessary	250.80 F	*- FL
65	1		*AIR CON DISCHARGE PIPE	Not Necessary	298.60 F	*- FL
66	1		*AIR CON LIQUID PIPE	Not Necessary	198.20 F	*- FL
67	1		*RADIATOR	Not Necessary	768.00 F	*- FL
68	1		*RADIATOR TOP MOUNTINGS	Not Necessary	56.00 F	*- FL
69	1		*RADIATOR FAN ASSY	Not Necessary	589.00 F	*- FL
70	1		*WASHER TANK	Deformed	165.00 F	*165.00 FL
71	1		*AIR DUCT ASSY	Not Necessary	266.00 F	*- FL
72	1		*FRONT FENDERS	O/S Bent / Buckled	1,234.18 F	*617.09 FL
73	2		*FRONT FENDER INNER SHIELDS	Not Necessary	245.00 F	*- FL
74	1		*FRONT LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
75	1		*RADIATOR COOLANT	Necessary	40.00 FS	*40.00 FS
76	1		*BOL AIR CON OIL	Not Necessary	40.00 FS	*- FS
77	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
78	1		*SET REAR REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
79	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	300.00 FS	*- FS
80	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
81	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
82	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 27,406.48 9,168.89
 - List Item Discount on L Items 0.00/20.00% (S\$) 0.00 1,775.78

Total Parts (S\$) 27,406.48 7,393.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE	New	65.00	0.00
2	TO CHECK WIRING	New	100.00	30.00
3	TO DISMANTLE & REPLACING REVERSE SENSOR	New	100.00	50.00
4	TO REFILL AIR CON GAS	New	150.00	100.00
5	TO SPRAY RUST PROOFING	New	250.00	80.00
6	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
7	TO MOUNT VEHICLE ON TO CAR O LINER	New	380.00	-
8	TO CONDUCT WHEEL ALIGNMENT	New	100.00	0.00
9	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
10	TO SPRAY RUST PROOFING	New	250.00	0.00
11	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
12	TO DISMANTLE & REPLACING REAR EXHAUST	New	150.00	0.00
13	TO DISMANTLE & REFIX REAR UNDERCARRIAGE	New	380.00	0.00
14	LABOUR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS	New	3,800.00	1,400.00
15	TO PUTTY & SPRAY PAINTING	New	3,500.00	1,500.00
Gross Labour Cost (S\$)			9,625.00	3,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >