

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE.

速良摩哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒杆噴漆
代理保險：車禍
賠償及買賣汽車

MR NEO KWEE CHONG

DATE: 07/12/2017

DOA : 04/12/2017

ESTIMATE REPAIR FOR VEHICLE NO. SKS 3063 T (HONDA CIVIC)

	Description	List Price
1 pc	Bootlid <i>3up/3uc</i>	\$ 481.50 ✓
1 pc	Bootid lock <i>twi</i>	\$ 100.00 ✓
1 pc	Weatherstrip <i>twi</i>	\$ 98.00 ✓
1 pc	emblem <i>rec</i>	\$ 38.00 ✓
1 pc	Civic emblem <i>rec</i>	\$ 38.00 ✓
1 pc	1.6 emblem <i>rec</i>	\$ 40.00 ✓
1 pc	i-Vtec <i>rec</i>	\$ 40.00 ✓
1 pc	Reflector (rh) <i>11</i>	\$ 128.00 X
1 pc	Rear bumper <i>80/25</i>	\$ 700.70 ✓
2 pcs	Bumper side retainer @S\$30.00 <i>3up</i>	\$ 60.00 ✓
10 pcs	Bumper clips @S\$8.00 <i>rec</i>	\$ 80.00 ✓
1 pc	Lower lip <i>25</i>	\$ 430.00 ✓
1 pc	Rear end panel <i>2</i>	\$ 380.00 X
1 pc	Top garnish <i>twi</i>	\$ 98.00 ✓
		\$ 2,712.20
	Less : 20%	\$ (542.44)
		\$ 2,169.76

	Special Nett Items	
4 pcs	Reverse sensor <i>shad</i>	\$ 350.00 <i>2005.2</i>
	To remove & fix reverse sensor	\$ 80.00 <i>50</i>
	To spray anti-rust	\$ 100.00 <i>60</i>
1 set	No. plate & housing <i>11</i>	\$ 60.00 X
	Labour charges for knocking & replacing parts.	\$ 700.00 <i>600</i>
	Spraypainting	\$ 800.00 <i>700</i>
	TOTAL	\$ 4,259.76

not added
2650
1/3
Honey
2650
11/12/17

Insurance Company to be notified of this survey.

- To resurvey all work done by spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- This survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____