

REPAIR DETAILS

SGD1111C (Supp 1)

Reference**Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 04 Jan 2018)**Parts:** 143 MERCEDES-BENZ C250 2.0 SALOON (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Hoe Motor Pte Ltd/SGD1111C/04/01/2018 18:43**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC RH HEADLAMP CONTROL UNIT	CM 0.00	0.00	*685.00 F ✓
						Sub Total (S\$) 685.00
						+ Margin on L,N Items 5.00% (S\$) 34.25
						Total Parts (S\$) 719.25

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SGD1111C/04/01/2018 18:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Cheng Hoe Motor Pte Ltd/SGD1111C/04/01/2018 18:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >