



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475 Fax : 6844 2474

E-mail : claims@teamworkgarage.com

ROC: 201015366H

3RD PARTY CLAIM ESTIMATION

Vehicle number	: SKH225X
Make / Model	: MERCEDES/C180
Chassis number	: WDD2040452A720455
Accident date	: 03 December 2017
Reference	: 1712-03

AIG Aisa Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way #07-16

Singapore 079120

Qty Particulars

Unit Price - SGD \$

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER <i>CRASH</i>	1610.40 ✓
2	REAR BUMPER SIDE BRACKET <i>SR</i>	163.20 X
2	REAR BUMPER RETAINER <i>SR</i>	91.20 X
1	REAR BUMPER REINFORCEMENT <i>SR</i>	798.00 X
1	REAR BUMPER INNER BRACKET <i>damaged</i>	162.00 ✓
1	REAR RH LOWER BRACKET <i>SR</i>	23.40 X
1	REAR RH TAILLAMP <i>MM</i>	929.50 X
1	REAR RH EXHAUST ASSY <i>SR</i>	2118.00 ✓
1	REAR RH EXHAUST TIP <i>SR</i>	279.50 ✓
4	REAR PDC SENSOR <i>Dem</i>	729.60 ✓
1	END PANEL <i>mm</i>	1488.00 X
1	END PAENL TOP GARNISH <i>MM</i>	141.60 X
		8534.40
Less 10 %		853.44
Subtotal		7680.96
Balance C/F		7680.96
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
Balance B/F		7680.96
1	REAR BUMPER CLIP <i>mm</i>	60.00 30/-
1	JOINT SELANT <i>Dem MM</i>	150.00 X
Subtotal		210.00
Balance C/F		7890.96
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
Balance B/F		7890.96
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 80/-
3	DIAGNOIS CHECK AND CLEAR FAULT CODE	400.00 MM
4	PANEL BEATING ON AFFECTED AREAS	1200.00 600/-
5	SPRAY PAINTING ON AFFECTED AREAS	1000.00 500/-
6	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30/-
Subtotal		3010.00
Grand total		10900.96

Acknowledged by Repairer

Signature:

Date:

18/12/2017 2:15pm

Hot Antenna

2/5mm

1kk Auto 3 day 1.

Check part prices.