

Class

CC 4/TWD17023494

Uca3

LKK:

IDAC:

Surveyor:

MARCUS

DOI:

11/12/17

Date / Time:

11/12/17

Registered in Merimen:

11/12/17

Pre-assign / CCU / FTE



Insured Vehicle No. : SKC 4916K
 Name of Insured : TAN NGOH PHENG
 Insured Tel No. : 9174 6188 HP: 9174 6188
 Excess Sec II : S\$ 11/10/17 D.O.A : 11/10/17
 Is driver the owner? (YES ☒ NO) Nature of Accident :

Claim No. : 120170000 8769
 Policy No. : PNPV2017 - 0000 4756
 Make / Model : CHERY TII 1.6MT ABS
 Place of Accident : ALONG GAMBARAS AVENUE

If NO, Driver Name / Age : KOO AH SIMDriver Tel No. : 9174 6188(V/L ☒ NO)OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Insured Liability : % Final ? Yes / No

FS 8074M



INSRS:
WSP: Eola (Liability)
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time

02/01/18 (Asst)

FS 8074M - X ; SKC 4916K - X

Inventory, UNCLE, Pending TP EVIDENCE

12/3/18 FWD PROVIDED FINAL PR, DID WPS (JAMES)

12/3/18 FAE PASS TO TPST TO PREPARE REPORT

RECEIVED 13 MAR 2018

X DIS INVT AS MAXIMUM

RECEIVED 25 APR 2018

STAGE DATE / PIC

Non-Reporting ltr (1st):
 Non-Reporting ltr (2nd):
 Non-Reporting ltr (Final):
 Notification ltr (if non-pickup):
 Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)	<input type="checkbox"/>	<input type="checkbox"/>
After call ltr to OI:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Release Voucher:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Car Rental Invoice:	<input type="checkbox"/>	<input type="checkbox"/>
Towing Invoice:	<input type="checkbox"/>	<input type="checkbox"/>
LTA / GIA:	<input type="checkbox"/>	<input type="checkbox"/>
Medical Bill:	<input type="checkbox"/>	<input type="checkbox"/>
PIR:	<input type="checkbox"/>	<input type="checkbox"/>
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
LOD	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Payment Breakdown Form:	<input type="checkbox"/>	<input type="checkbox"/>
Post-Repair Photos:	<input type="checkbox"/>	<input type="checkbox"/>
Others:	<input type="checkbox"/>	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 02/01/18 Sent By: Shirley Hwee

FINALIZATION Date/Time: Confirm with: LEE LEE Confirm by: LKS

Repair Cost: 45 S\$ 2,100 (6 days) Reduction: 38 % Email ☐ Call ☐FINAL SETTLEMENT Date/Time: 12/4/18 Confirm with: LEE LEE Email ☒ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 15

Repair Cost: S\$ 2,100.00 DID (Agreed) LATE CHARGE TP SKID.

Loss of Rental (LOR): S\$ - (days)

Loss of Use (LOU): S\$ 160.00 (\$ 20 x 8 days)

Loss of Income (LOI): S\$ - (\$ x days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search S\$ -

Medical: S\$ -

Disbursement: S\$ - (e.g. Tow/ Independent)

Legal Cost S\$ -

Total: S\$ 2,260.00 Global Sum S\$:

FINAL PAYMENT Date/Time: 12/4/18 Confirm with: LEE LEE Email ☒ Call ☐

Payee 1: S\$ 2,260.00 Name 1: GEORGE MOORE TRADING PTE LTD

Payee 2: (Strike if N.A.) S\$ - Name 2:

Payee 3: (Strike if N.A.) S\$ - Name 3:

COPY SENT 25/04/18

1) Claim status: Normal/Reject/Private Settle
 2) Report Format: TP
 3) Survey fee: +500



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD			Ref : CC4/FWD17023494/Uea3	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4 SINGAPORE 038986			Date : 11-12-2017	
Code : FWD				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKC 4916K	Veh. Inspected	FS 8074M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/10/2017	Inspection Date	11/12/2017	
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	6536Z

Vehicle Details

Vehicle No.	F58074M
Vehicle to be Exported	No
Intended De-registration Date	11 Dec 2017
Vehicle Make	PIAGGIO
Vehicle Model	PX 200E
Primary Colour	Green
Manufacturing Year	2000
Engine No.	VSE1M409511
Chassis No.	VSX1T6008400
Maximum Power Output	-
Open Market Value	\$2,395.00
Original Registration Date	22 Nov 2000
First Registration Date	22 Nov 2000
Transfer Count	3
Actual ARF Paid	\$360.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	31 Oct 2020
COE Category	D - Motorcycle
COE Period(Years)	10
PQP Paid	\$1,353.00
COE Rebate Amount	\$444.00
Total Rebate Amount	\$444.00

The information contained herein is correct as at 11 Dec 2017

OK

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Aiman Hafiz
Bin Nor Anuar

Accident Date : 11-Oct-17

Vehicle No : FS 8074 M

Vehicle Model : Piaggio PX200

Estimated Repair Costs

Qty	Description <u>List Items</u>	Amount S(\$)
1	Front fender	\$ 3uc 85.00 ✓
1	Front fork assy	\$ 1 580.00 x
1	Front shock absorber	\$ 5u 320.00 x
1	Front fork cover	\$ 5u 42.00 ✓
1	Front rim	\$ 11 80.00 x
1	Front brake disc	\$ 17 150.00 x
1	Top cowling	\$ 1 120.00 x
1	Front centre cowling	\$ 1 85.00 x
1	Front panel moulding	\$ 70.1 110.00 ✓
1	Headlamp	\$ 1u 120.00 ✓
1	Front signal -R/H	\$ 1u 65.00 ✓
1	Side mirror -R/H	\$ 50u 60.00 ✓
1	Handle bar	\$ 151 185.00 ✓
1	Hand grip (1 set)	\$ 70.1 38.00 ✓
1	Brake lever	\$ 50u 26.00 ✓
1	Step board panel	\$ 1 180.00 x
1	Step board panel moulding	\$ 70.1 55.00 ✓
1	Engine cover -R/H	\$ 15 155.00 ✓
1	Engine cover moulding -R/H	\$ 1u 50.00 ✓
1	Kick starter	\$ 1u 90.00 ✓
1	Gear selector	\$ 11 98.00 x
1	Exhaust pipe	\$ 15 295.00 ✓
1	Rear signal -R/H	\$ 1u 55.00 ✓
1	Rear taillamp	\$ 11 85.00 x
1	Rear spoiler	\$ 12u 55.00 ✓
		\$ 3,184.00
		\$ 318.40
		\$ 2,865.60

Less 10%

LiK Auto Consultants hence notify
the Repairer of the following:

- To resurvey / be foreaster spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Aiman Hafiz
Bin Nor Anuar

Accident Date : 11-Oct-17

Vehicle No : FS 8074 M

Vehicle Model : Piaggio PX200

Estimated Repair Costs

<u>Special Nett Items</u>		
1	Number plate (1 set)	\$ 28.00 20
1	Steering cone (1 set)	\$ 85.00 X
1	ERP IU	\$ 170.00 165
		<u>\$ 283.00</u>

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service.	\$ 50.00 30
2	To provide labour.	\$ 380.00 300
3	To respray painting.	\$ 1,000.00 580
4	To repair body frame.	\$ 450.00 250
		<u>\$ 1,880.00</u>

Grand Total \$ 5,028.60

Dollars: Five Thousand Twenty-Eight And Sixty Cents Only.


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com, assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 02 Jan 2018

Preliminary Advice

Insured Vehicle No	: SKC4916K	Accident Date	: 11/10/2017
TP Vehicle No	: FS8074M	Assignment Date	: 11/12/2017
Make	: PIAGGIO PX200E	Est. Duration of Repair	: 6 days
Date of Inspection	: 11/12/2017		
Inspection At	: Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesO/S body.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,028.60
Revised Amount	:S\$	2,682.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,682.40

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

Catherine Chong (LKK Auto)

From: clara.li@fwd.com
Sent: Friday, 8 December, 2017 2:09 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: PRI request for accident involving SKC4916K and FS8074M on 11 October 2017
Attachments: FS8074M - DOC.pdf

Hi LKK team,

Please refer to the email below and liaise with TP repairer for survey arrangement.

Attached is the repair estimate, TP GIA report. Our insured has yet to lodge accident report and we will forward you a copy upon receipt.

Please create the case in Merimen.

Thank you.

Kind Regards

Clara Li
Senior Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722
E clara.li@fwd.com
W fwd.com.sg



*08-12-2017 @ 2:15pm
Mr. Teo veh in
merimen.*

	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!	2.02% p.a. fwd.com.sg save now
--	--	---

From: Erofia Motor - LeeLee Tan [mailto:erofia@singnet.com.sg]
Sent: Friday, 8 December, 2017 11:50 AM
To: Motor Claims SG - SG Common
Subject: PRI request for accident involving SKC4916K and FS8074M on 11 October 2017

Dear Sir

Attached necessary documents for your arrangement of pre-repair inspection for

Motorcycle no: FS8074M at

Erofia Motor Trading Pte Ltd
1 Kaki Bukit Avenue 6 #02-62
Auto Bay @ kaki Bukit
Singapore 417883

Contact : 90696165 Mr Teo

Thank you

Regards
LeeLee Tan
Erofia Motor Trading Pte Ltd
Tel: 67527740
Fax: 67528669

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Erofia Motor Trading Pte Ltd

1 Kaki Bukit Avenue 6 #02-62
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67527740 Fax: 67528669
E-Mail: erofia@singnet.com.sg
Co Registration No: 201202259N

Our Ref: EMT1257/18/lt/FS8074M

WITHOUT PREJUDICE

Your reference: To Be Advised

BY HAND TO FWD

FWD Singapore Pte Ltd
6 Temasek Boulevard #18-01
Suntec Tower Four
Singapore 038986

Attn: Officer-In-Charge (Motor Claims Department)

Dear Sir

Re: Accident Involving SKC4916K And FS8074M On 11 October 2017

We are instructed by our client Alman Hafiz Bin Nor Anuar to claim damages against your insured SKC4916K in connection with a road traffic accident on 11 October 2017 at about 17.45hrs Along Gambas Avenue with our client's motorcycle registration number FS8074M

As a result of the accident, our client's motorcycle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1.	Final Repair Bill as per surveyor's recommendation	S\$2,100.00
2.	Loss of Use (8 days x S\$20.00/day) Repair + PRI	S\$ 160.00
	Total to Claim	<u>S\$2,260.00</u>

Attached final repair bill for your early process of our claim

Thank you

Yours faithfully
Erofia Motor Trading Pte Ltd

Teo Hwa Heng



Erofia Motor Trading Pte Ltd

1 Kaki Bukit Avenue 6 #02-62

AutoBay @ Kaki Bukit

Singapore 417883

Tel: 67527740 Fax: 67528669

Co Registration No: 201202259N

AUTHORISATION TO ACT

I/We, Aiman Hafiz Bin Nor Anwar ("the third party claimant") of
BLK 28 Marsiling Drive #03-271 S 730028 (address), owner of
FS 8074M (vehicle no.) hereby authorize Erofia Motor Trading Pte Ltd ("the
workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of
use ("claim") for my vehicle no. FS 8074M. That was damaged pursuant to the
accident which occurred on 11/10/2017 (date)
along gambas avenue (location) involving vehicle no/s
SKC 4916 K ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they
deemed fit and the workshop is further authorized to receive payment further to settlement of my
claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the
other vehicle/s is concerned.

Dated this 05 (day) of 12 (month) 20 17 (year)

Aiman Hafiz Bin Nor Anwar

Signed by "the third party claimant"

(With company stamp if applicable)



[Signature]
Signed by "the workshop"

(With company stamp)

Provide always that this discharge of my
claim for damages relating to the damage to
my vehicle shall not prejudice or affect or
preclude me from making a further claim for
general and special damages for my personal
injuries sustained in the same accident.

RELEASE

Claim Reference:	1201700008769
Surveyor's Reference:	CC4/FWD17023494/Uea3
TP Reference:	FS 8074M

We, **EROFIA MOTOR TRADING PTE LTD** ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle **FS 8074M** ("Vehicle") to accept the sum of **\$2,260.00**, being the amount claimed for **\$2,100.00** (repair costs), **\$160.00** (loss of ~~rental~~ use), **\$ -** (loss of income), **\$ -** (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on **11/10/2017** (date of accident) at / along **GAMBAS AVENUE** (location) involving vehicle no/s. **FS 8074M** and **SKC 4916K**.

This is pursuant to the inspection conducted on **11/12/2017** (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of **SKC 4916K** be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 23 day of 4 2018

CLAIMANT



[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"



CKS

[FWD's appointed surveyor with Co. Stamp]

For and on behalf of FWD Singapore Pte. Ltd.

Provide always that this discharge or my claim for damages relating to the damage to my vehicle shall not prejudice or affect or preclude me from making a further claim for general and special damages for my personal injuries sustained in the same accident.

EROFIA MOTOR TRADING PTE LTD (201202259N)

1 Kaki Bukit Ave 6 #02-62
Singapore 417883
Tel: 67527740 Fax: 67528669
H/P: 90696165 (Mr Teo)

INVOICE

Number	Date	Page
FS8074M	09-Mar-18	1

VEHICLE NO: FS8074M
MAKE/MODEL: PIAGGIO PX200
NAME: FWD SINGAPORE PTE LTD
ADDRESS: 6 TEMASEK BOULEVARD #18-01
SUNTEC TOWER FOUR
SINGAPORE 038986

ACCIDENT INVOLVING SKC4916K AND FS8074M ON 11 OCTOBER 2017

FINAL REPAIR COST AS PER SURVEYOR'S RECOMMENDATION	S\$	2,100.00
LOSS OF USE (8 DAYS X \$20.0/DAY) REPAIR DAY+PRI	S\$	160.00

SUB-TOTAL: S\$ 2,260.00

SINGAPORE DOLLARS: TWO THOUSAND TWO HUNDRED AND SIXTY ONLY

TOTAL : S\$ 2,260.00

EROFIA MOTOR TRADING PTE LTD

.....



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2017 Edit Reg		11 Dec 2017 00:00 Edit Adj Rpt	S\$2,100.00 Edit Estimates	S\$2,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Tan Ngoh Pheng, ID: S1218216C								
Main Claimant:	AIMAN HAFIZ BIN NOR ANUAR, ID: S9326536Z								
Vehicle Reg. No.:	FS8074M	Date of Loss:	11/10/2017 17:00 - :59 [202 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201700008769	Policy/Cover Note No.:	PNPV2017-00004756 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKC4916K	Policy No. (Claimant):	5088564340						
		Excess:							
Repairer:	Erofla Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62, 417883 Kaki Bukit - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/12/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> FWD_SG (27/03/2018): Alert - Adj Mandate Approved (S\$2260.00) - FS8074M - Claim Handler: Clara Li Zi ... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FS8074M (1201700008769)
[SKC4916K]

TP

















































AIMAN HAFIZ BIN NOR ANUAR

Oct 11 2017 5:00PM

[Tan Ngoh Pheng]

Erofia Motor Trading Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Letters/Correspondences									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown							1		Edit	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	02/01/18 09:37	Adjuster Immediate Advice							1		Load HTM	
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
2	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
3	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
4	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
5	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
6	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
7	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
8	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
9	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
10	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
11	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
12	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
13	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
14	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
15	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
16	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
17	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
18	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
19	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
20	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
21	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
22	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
23	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
24	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
25	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
26	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
27	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
28	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
29	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	
30	13/03/18 16:42	General View							1		Load JPG <input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
32	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
33	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
34	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
35	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
36	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
37	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
38	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
39	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
40	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
41	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
42	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
43	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
44	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
45	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
46	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
47	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
48	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
49	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
50	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
51	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
52	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
53	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
54	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
55	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
56	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
57	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
58	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
59	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
60	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
61	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
62	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
63	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
64	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
65	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
66	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
67	13/03/18 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
68	13/03/18 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	13/03/18 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	13/03/18 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	13/03/18 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	13/03/18 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	13/03/18 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/12/17 17:47	ACKNOWLEDGEMENT EMAIL TO FWD DD 08.12.2017	 Load PDF	
2	11/12/17 17:47	NOTIFICATION FROM WORKSHOP + TP ESTIMATE + TP GIA REPORT	 Load PDF	
3	13/12/17 09:29	TP ESTIMATE- MARKED	 Load PDF	
4	14/12/17 19:15	EMAIL FROM FWD TO OI DD 08.12.2017	 Load PDF	
5	20/03/18 16:00	WORKSHOP INVOICE	 Load PDF	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
6	20/03/18 16:00	LOD		Load PDF
7	27/04/18 08:24	AUTHORISATION TO ACT FORM		Load PDF
8	27/04/18 08:24	Release Voucher		Load PDF
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail Print
1	29/12/17 11:51	OI GIA Report		Load PDF
2	03/01/18 15:11	Police Report & Charge from Traffic Police		Load PDF
3	06/03/18 17:54	Final PIR		Load PDF
4	13/03/18 16:26	Letter of Demand from Third Party		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKC4916K (Insd veh)	Model:	PIAGGIO PX200E 198CC
	FS8074M (TP veh)		
Date of Accident:	11/10/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	5,028.60
Final Repair Cost	:	\$	2,100.00
Loss of Use	:	\$	160.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	2,260.00

8.00 days at \$20.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Erofia Motor Trading Pte Ltd	:	\$ 2,260.00
2)		:	\$

JOANNE LEE KHANG MIN

27 Apr
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD17023494/UEA3Q2

Date: 27/04/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00004756

Claimant Vehicle No : FS8074M **Insured Vehicle No :** SKC4916K

Date of Loss: 11/10/2017 Nature of Claim: TP Claim No: 1201700008769

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FS8074M**
 Make & Model: PIAGGIO PX200E, 198cc Engine No: VSE1M409511
 Reg. Date: 22/11/2000 (Man. Year: 2000) Chassis No: VSX1T6008400
 Colour: Green Odometer: 10378 km
 Engine Capacity: 198 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 3.50-10 Rear Tyre Size: 3.50-10
 Front Left Side: INQUE 6 mm Rear Left Side: INQUE 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,148.60	1,522.40	1,626.20	51.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,160.00	720.00	38.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,028.60	2,682.40	2,346.20	46.66
Approved Total (Overridden) (S\$)		2,100.00		
Nett Amount (S\$)	5,028.60	2,100.00	2,928.60	58.24
+ Loss of Use (8.0 x S\$20.00/day) (S\$)		160.00		
Nett Liability (S\$)		2,260.00		

INSPECTION

Date of Assignment: 11/12/2017

Date Inspected: 11/12/2017 Inspected At:

 Erofia Motor Trading Pte Ltd (KAKI BUKIT)
 1 KAKI BUKIT AVE 6 #02-62
 Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Mar 2018)	
Parts:	N/A	PIAGGIO PX200E 198cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FS8074M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Buckled	85.00 FL	*85.00 FL
2	1		*FRONT FORK ASSY	Repair	580.00 FL	*- FL
3	1		*FRONT SHOCK ABSORBER	Serviceable	320.00 FL	*- FL
4	1		*FRONT FORK COVER	Scratched	42.00 FL	*42.00 FL
5	1		*FRONT RIM	Not Necessary	80.00 FL	*- FL
6	1		*FRONT BRAKE DISC	Not Necessary	150.00 FL	*- FL
7	1		*TOP COWLING	Repair	120.00 FL	*- FL
8	1		*FRONT CENTRE COWLING	Repair	85.00 FL	*- FL
9	1		*FRONT PANEL MOULDING	Torn	110.00 FL	*110.00 FL
10	1		*HEADLAMP	Cracked	120.00 FL	*120.00 FL
11	1		*FRONT SIGNAL -R/H	Cracked	65.00 FL	*65.00 FL
12	1		*SIDE MIRROR -R/H	Scratched	60.00 FL	*60.00 FL
13	1		*HANDLE BAR	Bent	185.00 FL	*185.00 FL
14	1		*SET HAND GRIP	Torn	38.00 FL	*38.00 FL
15	1		*BRAKE LEVER	Scratched	26.00 FL	*26.00 FL
16	1		*STEP BOARD PANEL	Repair	180.00 FL	*- FL
17	1		*STEP BOARD PANEL MOULDING	Torn	55.00 FL	*55.00 FL
18	1		*ENGINE COVER -R/H	Dented	155.00 FL	*155.00 FL
19	1		*ENGINE COVER MOULDING-R/H	Necessary	50.00 FL	*50.00 FL
20	1		*KICK STARTER	Cut	90.00 FL	*90.00 FL
21	1		*GEAR SELECTOR	Not Necessary	98.00 FL	*- FL
22	1		*EXHAUST PIPE	Dented	295.00 FL	*295.00 FL
23	1		*REAR SIGNAL -R/H	Cracked	55.00 FL	*55.00 FL
24	1		*REAR TAILLAMP	Not Necessary	85.00 FL	*- FL
25	1		*REAR SPOILER	Damaged	55.00 FL	*55.00 FL
26	1		*SET NUMBER PLATE	Necessary	28.00 FS	*20.00 FS
27	1		*SET STEERING CONE	Not Necessary	85.00 FS	*- FS
28	1		*ERP IU	Cut	170.00 FS	*165.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,467.00	1,671.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	318.40	148.60
Total Parts (\$\$)	3,148.60	1,522.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	50.00	30.00
2	TO PROVIDE LABOUR	New	380.00	300.00
3	TO RESPRAY PAINTING	New	1,000.00	580.00
4	TO REPAIR BODY FRAME	New	450.00	250.00
Gross Labour Cost (S\$)			1,880.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >