Date: 06th March 2018



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: AEMD/105/009/2017/143

Our Ref: CS1/SPF17023521/R1vbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section (Singapore Police Force) 1 Mount Pleasant Road Blk 8 Old Police Academy Singapore 298333 (The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO.: SY 69X INSURED VEHICLE NO: QX 376M ACCIDENT ON 04/07/2017

We thank you for your instruction on 11/12/2017.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SY 69X from M/s Borneo Motors (Singapore) Pte Ltd.
- b) Singapore Accident Statement of Vehicles SY 69X.
- c) Colour damaged vehicle photographs of SY 69X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SY 69X

Make & Mode : Toyota Lexus CT200H, 1.8 (A)

Year of Registration : 2011

Chassis Number : JTHKD5BH902046989

Engine Capacity : 1798 cc

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

- Our finding is that the repair cost of \$14,917.19 (before GST) quoted by M/s Borneo Motors (Singapore) Pte Ltd is fair & reasonable.
- We recommend that the repairs of the entire damage require about <u>9 (Nine)</u> working days to complete.

Vehicle Inspection By:

MRB

MOHD. RASUL BIN MOHD YUNUS AMSOE, AMIRTE, AMSAE-A, M. MATAI Automotive Assessor

ADRIAN LING WAI PING

B. Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser