

ASS. I.E.C. BY:

REF: CS/CTI17023529/R/vb

Special Instruction:

SURVEYOR
MENJEN

Rasul

ASSIGNMENT (Office)

From (Person):

Joel Goh

of

CTI

Date/Time:

12/12/17 09:06am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FW 3499H

Insured:

GBF 9245X

at Workshop m/s

SG98 Motor

Tel:

6452 4898

of

BLK 4001 AMK Ind Prk / # 01-21, 569622

Policy No:

DMCVSN1728561700

Claim No:

SNMI7D07010C02/5

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

8/12/2017

CA / REV / REP. / REV 24 HRS

(wp)

13/12/2017

H.O.D. Endorsement:

Date/Time:

9:21am 01/12/17

Person Contacted:

Rose

Vehicle IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	FW 3499H-X
	GBF 9245X-X
18/4/18	@ 11:02am LS \$ 1600 confirmed with Rose (Red 1421.50, 4720)
	✓ 18/4

RECEIVED 19 APR 2018

CaseTime File Pass 001 ☐ : Prel. Report

Days Of Repair: 3☐ : Final ReportResurvey No. of Trip: 1

Copyright © 2003

Case Time-For-Return Is?

Add Fee: Site Insp. \$

19/4 - typist

Interviews 5

Report Format : merimen

[illegible]

Lump Sum / I.B.I.: \$ 160012

100 李 强



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17023529/R1vb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 12-12-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 9245X	Veh. Inspected	FW 3499H
Policy No.	DMCVSN1728561700	Coverage (\$)	0.00
Claim No.	SNM17D010C02/5	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	12/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	08/12/2017	Inspection Date
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 589622	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Authored	Status
Main	12 Dec 2017		12 Dec 2017 09:06 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S SANTINO COFFEE SPECIALISTS PTE LTD, Co. Reg. No.: 200005167G		
Main Claimant:	MUHAMMAD UBHAIDULLAH BIN HASHIM, ID: S8507843G		
Vehicle Reg. No.:	FW3499H	Date of Loss:	08/12/2017 10:00 - :59
Claim Type:	TP / SNM17D07010C02/5	Policy/Cover Note No.:	DMCVSN1728561700 (Comprehensive)
Vehicle Reg. No. (Insured):	GBF9245X	Policy No. (Claimant):	5082307323-01
		Excess:	S\$0.00
Repairer:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/12/2017]		
Driver/Custodian (Insured):	NG ZU ZHENG (27 / Male), NRIC: G2375354K, Tel: +6591464866		
Adj Asp. Remarks:	NO ESTIMATES. KENNETH KONG SELECTED AS SJE FOR WP PRS		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	7843G
Vehicle Details	
Vehicle No.	FW3499H
Vehicle to be Exported	No
Intended De-registration Date	15 Dec 2017
Vehicle Make	HONDA
Vehicle Model	CB400SF2J
Primary Colour	Black
Secondary Colour	White
Manufacturing Year	2002
Engine No.	NC23E2036289
Chassis No.	NC391036235
Maximum Power Output	-
Open Market Value	\$8,026.00
Original Registration Date	04 Mar 2003
First Registration Date	04 Mar 2003
Transfer Count	8
Actual ARF Paid	\$1,204.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	28 Feb 2023
COE Category	D - Motorcycle
COE Period(Years)	10
PQP Paid	\$1,780.00
COE Rebate Amount	\$955.00
Total Rebate Amount	\$955.00

The information contained herein is correct as at 15 Dec 2017

OK



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/12/2017 12:05
Date Of Accident	08/12/2017 10:30
Exact Location Of Accident	NO 3 CHANGI BUSINESS PARK CRESCENT(CARPARK)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FW3499H
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD UBHAIDULLAH BIN HASHIM
NRIC No	S8507843G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-86961232
Alternative Phone No	OTHERS-86961232

Vehicle Particulars

Manufacturer	HONDA
Model	SUPER 4 SPEC 2
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5082307323-01
Cover Note Number	

Driver

Name of Driver	MUHAMMAD UBHAIDULLAH BIN HASHIM
NRIC No	S8507843G
Date Of Birth	25/02/1985
Occupation	INDOOR
Date Of Driving Pass	08/08/2006
Driving Experience	11 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86961232
Fax Number	
Contact Number	OTHERS-86961232
Email Address	NOEMAIL

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if needed.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purposes) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me in writing about delivery of the same as well as on the internal cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centro Person's Signature
Name:
NIC/PN No.:

Hi Rose, the bike is parked bike, so
replace or remove front fork is not necessary

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 13 December 2017

To : LKK

By Fax: 6256-4315

Attn: Rasul

Tel : 90010068

VEHICLE NO : FW 3499H

CB 400 VTEC

ACCIDENT DATE: 8 December 2017

Description	Qty	Quotation \$
1 Handle Bar	1	205.00 X <i>sm</i>
2 Radiator Assy	1	880.00 <i>PA</i>
3 RH Side Shroud - Guard	1	220.00 <i>CR</i>
4 Radiator Fan Motor	1	480.00 <i>PA</i> X <i>sm</i>
5 Side Stand	1	150.00 <i>PA</i>
6 Water Pump	1	350.00 <i>PA</i> <i>9.10.10</i>
7 Crash Bar	1 set 1 pc	175 350.00 <i>SC</i>
	Sub-Total	2,635.00 1775
	Less 10%	263.50 10%
	Sub-Total	2,371.50 1597.50
<u>Nett items</u>		
1 Towing fee		40.00
2 Remove & replace necessary parts, align & etc		180.00 100
3 To remove & replace water pump assy, check oil leakage		350.00 250
4 Supply engine oil x 4 litres		80.00 <i>sm</i>
5 <i>Remove & replace fork tube. fork oil seal & fork oil. 150.00</i>		
	Sub-Total	650.00
	Nett Total	3,021.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion, thank you

SG 98 MOTOR PTE LTD

Rasul
Hp 90010068
3 days
4/5
13/12/17 @ 1210

1597.50
470.00
2067.50
20%
1654
45-1600
3 days

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4888

Email: sg_motor_enterprise@yahoo.com.sg

Date: 15 December 2017

To : LKK

By Fax: 6256-4315

Attn : Rasul

Tel : 90010068

VEHICLE NO : FW 3499H

CB 400 VTEC

ACCIDENT DATE: 8 December 2017

Supplementary Items

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Under Bracket	1	380.00
2 Fork Tube	1 set	680.00
	Sub-Total	1,060.00
	Less 10%	106.00
	Sub-Total	954.00

Nett items

1	Remove & replace fork tube, fork oil seal & fork oil	150.00
	Sub-Total	150.00
	Nett Total	1.104.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion, thank you

SG 98 MOTOR PTE LTD

forward 12/17

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2017		12 Dec 2017 09:06 Edit Adj Rpt	S\$1,600.00 Edit Estimates	S\$1,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	M/S SANTINO COFFEE SPECIALISTS PTE LTD , Co. Reg. No.: 200005167G								
Main Claimant:	MUHAMMAD UBHAIDULLAH BIN HASHIM , ID: S8507843G								
Vehicle Reg. No.:	FW3499H	Date of Loss:	08/12/2017 10:00 - :59 [177 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM17D07010C02/5	Policy/Cover Note No.:	DMCVSN1728561700 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBF9245X	Policy No. (Claimant):	5082307323-01						
		Excess:	S\$0.00						
Repairer:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/12/2017]								
Driver/Custodian (Insured):	NG ZU ZHENG (27 / Male), NRIC: G2375354K, Tel: +6591464866								
Adj Asg. Remarks:	NO ESTIMATES. KENNETH KONG SELECTED AS SJE FOR WP PRS								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FW3499H (SNM17D07010C02/5)
[GBF9245X]
TP
MUHAMMAD UBHAIDULLAH BIN HASHIM
Dec 8 2017 10:00AM
[M/S SANTINO COFFEE SPECIALISTS PTE LTD]
Sg 98 Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		☒	
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)					Thumbnail	Print	
1	11/12/17 12:17	Accident Statement					Load HTML		
Photos/Images						3 per page		☒	
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)					Thumbnail	Print	
1	11/12/17 12:11	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
2	11/12/17 12:11	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
3	11/12/17 12:11	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
4	11/12/17 12:11	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
5	11/12/17 12:11	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
6	11/12/17 12:11	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
7	11/12/17 12:11	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
8	11/12/17 12:11	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
9	11/12/17 12:11	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
10	11/12/17 12:11	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	15/12/17 10:04	General View					Load JPG	☒	
2	15/12/17 10:04	General View					Load JPG	☒	
3	15/12/17 10:04	General View					Load JPG	☒	
4	15/12/17 10:04	General View					Load JPG	☒	
5	15/12/17 10:04	General View					Load JPG	☒	
6	15/12/17 10:04	General View					Load JPG	☒	
7	15/12/17 10:04	General View					Load JPG	☒	
8	15/12/17 10:04	General View					Load JPG	☒	
9	15/12/17 10:04	General View					Load JPG	☒	
10	15/12/17 10:04	General View					Load JPG	☒	
11	15/12/17 10:04	General View					Load JPG	☒	
12	15/12/17 10:04	General View					Load JPG	☒	
13	15/12/17 10:04	General View					Load JPG	☒	
14	15/12/17 10:04	General View					Load JPG	☒	
15	15/12/17 10:04	General View					Load JPG	☒	
16	15/12/17 10:04	General View					Load JPG	☒	
17	15/12/17 10:04	General View					Load JPG	☒	
18	15/12/17 10:04	General View					Load JPG	☒	
19	15/12/17 10:04	General View					Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
20	15/12/17 10:04	General View	 Load JPG	☒
21	15/12/17 10:04	General View	 Load JPG	☒
22	15/12/17 10:04	General View	 Load JPG	☒
23	15/12/17 10:04	General View	 Load JPG	☒
24	15/12/17 10:04	General View	 Load JPG	☒
25	15/12/17 10:04	General View	 Load JPG	☒
26	15/12/17 10:04	General View	 Load JPG	☒
27	15/12/17 10:04	General View	 Load JPG	☒
28	15/12/17 10:04	General View	 Load JPG	☒
29	15/12/17 10:04	General View	 Load JPG	☒
30	15/12/17 10:04	General View	 Load JPG	☒
31	15/12/17 10:04	General View	 Load JPG	☒
32	15/12/17 10:04	General View	 Load JPG	☒
33	15/12/17 10:04	General View	 Load JPG	☒
34	15/12/17 10:04	General View	 Load JPG	☒
35	15/12/17 10:04	General View	 Load JPG	☒
36	15/12/17 10:04	General View	 Load JPG	☒
37	15/12/17 10:04	General View	 Load JPG	☒
38	15/12/17 10:04	General View	 Load JPG	☒
39	15/12/17 10:04	General View	 Load JPG	☒
40	15/12/17 10:04	General View	 Load JPG	☒
41	15/12/17 10:04	General View	 Load JPG	☒
42	15/12/17 10:04	General View	 Load JPG	☒
43	15/12/17 10:04	General View	 Load JPG	☒
44	15/12/17 10:04	General View	 Load JPG	☒
45	15/12/17 10:04	General View	 Load JPG	☒
46	15/12/17 10:04	General View	 Load JPG	☒
47	15/12/17 10:04	General View	 Load JPG	☒
48	15/12/17 10:04	General View	 Load JPG	☒
49	15/12/17 10:04	General View	 Load JPG	☒
50	15/12/17 10:04	General View	 Load JPG	☒
51	15/12/17 10:04	General View	 Load JPG	☒
52	18/04/18 14:34	Reinspection Photo	 Load JPG	☒
53	18/04/18 14:34	Reinspection Photo	 Load JPG	☒
54	18/04/18 14:34	Reinspection Photo	 Load JPG	☒
55	18/04/18 14:34	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/12/17 09:07	OI GIA REPORT	 Load PDF	
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	11/12/17 12:17	Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	11/12/17 12:17	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	11/12/17 12:17	Accident Statement	 Load HTM	

Assessment Reports			1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
2	24/01/18 12:59	Addendum Sheet	 Load TIF	☐
3	24/01/18 13:09	Accident Statement Addm. #1	 Load HTM	☐
Photos/Images			3 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	11/12/17 12:11	Accident Photo	 Load JPG	☒
2	11/12/17 12:11	Accident Photo	 Load JPG	☒
3	11/12/17 12:11	Accident Photo	 Load JPG	☒
4	11/12/17 12:11	Accident Photo	 Load JPG	☒
5	11/12/17 12:11	Accident Photo	 Load JPG	☒
6	11/12/17 12:11	Accident Photo	 Load JPG	☒
7	11/12/17 12:11	Accident Photo	 Load JPG	☒
8	11/12/17 12:11	Accident Photo	 Load JPG	☒
9	11/12/17 12:11	Accident Photo	 Load JPG	☒
10	11/12/17 12:11	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	11/12/17 12:17	Sketch Plan	 Load JPG	☒
2	11/12/17 12:17	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117023529/R1VBQ2

Date: 25/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1728561700

Claimant Vehicle
No: FW3499HInsured Vehicle
No: GBF9245X

Date of Loss: 08/12/2017

Nature of Claim: TP

Claim
No: SNM17D07010C02/5

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FW3499H

Make & Model: HONDA CB400SF2J, 399cc

Engine No: NC23E2036289

Reg. Date: 04/03/2003 (Man. Year: 2002)

Chassis No: NC391036235

Colour: Black

Odometer: 0 km

Engine Capacity: 399 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60 R17

Rear Tyre Size: 120/60 R17

Front Left Side: Dunlop 4 mm

Rear Left Side: Dunlop 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,451.50	1,677.50	774.00	31.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	570.00	390.00	180.00	31.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,021.50	2,067.50	954.00	31.57
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	3,021.50	1,600.00	1,421.50	47.05

INSPECTION

Date of Assignment: 12/12/2017

Date Inspected: 13/12/2017 Inspected At:

Sg 98 Motor Pte Ltd (HQ)
BLK 4001 ANG MO KIO INDUSTRIAL
PARK 1 #01-21
Singapore 569622

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Apr 2018)	
Parts:	N/A	HONDA CB400SF2J 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FW3499H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Serviceable	205.00 FL	*- FL
2	1		*RADIATOR ASSY	Bent	880.00 FL	*880.00 FL
3	1		*RH SIDE SHROUD-GUARD	Cracked	220.00 FL	*220.00 FL
4	1		*RADIATOR FAN MOTOR	Serviceable	480.00 FL	*- FL
5	1		*SIDE STAND	Bent	150.00 FL	*150.00 FL
6	1		*WATER PUMP	Necessary	350.00 FL	*350.00 FL
7	1		*CRASH BAR	Scratched	350.00 FL	*175.00 FL
8	4		*LITRES ENGINE OIL	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	2,715.00	1,855.00
- List Item Discount on L Items 10.00/10.00% (S\$)	263.50	177.50
Total Parts (S\$)	2,451.50	1,677.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	40.00	40.00
2	REMOVE & REPLACE NECESSARY PARTS ,ALIGN & ETC	New	180.00	100.00
3	TO REMOVE & REPLACE WATER PUMP ASSY ,CHECK OIL LEAKAGE	New	350.00	250.00
Gross Labour Cost (S\$)			570.00	390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >