

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

AIG/LKK
 DATE 8/12/2017 15:20
REAR RIGHT

Fz

VEHICLE NO : SHC 2715Y
 MAKE :
 MODEL : HYUNDAI SONATA

Fauzy

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 578.40
	Rear Bumper Reinforcement ✕			\$ 483.30
	Rear Bumper Clip ✓			\$ 22.00
	Rear Bumper Sponge ✕			\$ 137.40
	Rear Bumper Under Cover ✕			\$ 185.80
	Rear Bumper Protector (LH/RH) ✕ repair		\$ 38.00	\$ 76.00
	SUB TOTAL			\$ 1,482.90
	LESS 20%			\$ 296.58
	DISCOUNTED TOTAL			\$ 1,186.32
	Rear Bumper Reverse Sensor ✓			\$ 135.70 Nett
				\$ 135.70
	Labour Charge			<i>200</i>
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 200.00 <i>180</i>
	Wiring Charge			\$ 50.00 ✕
	Remove/Refix Reverse Sensor			\$ 120.00 <i>20</i>
	TOTAL LABOUR			\$ 720.00
	ESTIMATE TOTAL			\$ 2,042.02
	<p><i>Kalvin LKK</i> <i>11/12/17 1105 hrs</i> <i>2 Pgs</i> <i>45</i> <i>After Repair photo</i></p>			

LKK Auto Consultants hereby notify the Repairer of the following:

- No resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by the Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.