

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 1618L

DATE 9/12/2017 11:37

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (LH) ✓			\$ 1,388.00
	Front Fender (LH) ✓			\$ 619.00
	Front Door Mirror (LH) ✓			\$ 980.50
	SUB TOTAL			\$ 2,987.50
	LESS 20%			\$ 597.50
	DISCOUNTED TOTAL			\$ 2,390.00
	Front Door Comfort Logo (LH) ✗ ✓			\$ 75.00 Nett
	Labour Charge			400
	Panel Beating			\$ 450.00
	Spray Painting Charge			\$ 500.00 410
	Wiring Charge			\$ 50.00 20
	TOTAL LABOUR			\$ 1,000.00
	ESTIMATE TOTAL			\$ 3,465.00

Kalvin 11/12/17
 11/12/17 10:15 hrs
 2 Pys.
 PIP
 Before Paint p/h

Larry Ng

LKK Auto Insultants hence notify the Repairer

- To repair the damage
- To obtain a survey
- Part of the cost are subject to insurance
- Third party survey is on a "Without Prejudice" basis
- All legal proceedings are waived
- Subject to the terms and conditions of the insurance policy and the insurance company

Acknowledged: _____
 Signature: _____
 Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.