

Estimate To Repair : Toyota Vios 1.5E CVT
Vehicle No : SLL9957A
Chassis No : MHFB29F3202008036

Date : 27.11.2017

come in then call LKK rep: LKK Marcus 12-12-2017 @ 0925hrs.

Pages : 1 of 1

S/No	Quantity	Description	Unit price	Amount
		LABOUR & MISC. CHARGES		
1		To make good repair to n/s rear door, n/s rear fender and rear bumper	200	\$ 550.00
2		To putty and spray painting of n/s rear door, n/s rear fender and rear bumper	600	\$ 750.00
3		To repair n/s rear wheel rim and balancing		\$ 250.00
				\$ 1,550.00
		Grand Total		\$ 1,550.00

Not Attached
LKK
Take up the After repair
2/12 \$800
2 days
14/12/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216