

M/S AIG ASIA PACIFIC INS PTE LTD
CHARTIS BUILDING
78 SHENTON WAY #08-16
SINGAPORE 079120

ESTIMATE

DATE : 07/12/2017
ACC DATE : 06/12/2017
REF NO. : VFIX-TP20170379
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO :XD8124T ISUZU FXZ 77M

DESCRIPTION	AMOUNT S\$
1 1 FRONT BUMPER	2,088.80 ✓
2 1 HEADLAMP L	747.60 x
3 1 SIGNAL LAMP L	503.60 x
4 1 HEADLAMP RIM L	115.00
5 1 STEP BOARD LOWER	322.00 x
6 1 STEP BOARD LOWER GARNISH	358.00 ✓
	\$ 4,135.00
LESS 20%	\$ 827.00
	\$ 3,308.00

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove damaged body panel with all necessary components/attachments apply hot-works where necessary repair/reshape dented areas	400 800.00
2 To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	300 800.00
3 To conduct headlamp alignment	20 30.00
	\$ 1,630.00

GRAND TOTAL : \$ **4,938.00**

SINGAPORE DOLLARS : FOUR THOUSAND NINE HUNDRED & THIRTY
EIGHT ONLY

Vfix Auto Service Pte Ltd hereby notifies the Insureds hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____