

INS. CASE OWNER:

CC 6/CT1170 23581, Uka32

LKK:
IDAC:

Surveyor:

WAPINS

DOI:

ASSIGNMENT

12/12/17

Date / Time:

12/12/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

6BD 4700S

Name of Insured:

CHOR JWAY ENTERPRISE

Insured Tel No.:

HP:

D.O.A:

Nature of Accident:

Excess Sec II :SS

Is driver the owner? (YES / NO)

(YES / NO)

If NO, Driver Name / Age:

YAN YGOW HWEE

Driver Tel No.:

97621899

(V/L: YES / NO)

Claim No.:

SNM17007065/02/0/LKKS

Policy No.:

DM CUSN 308 2991700

Make / Model:

MISAN NV350

Place of Accident:

Tampines St 71

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLE 8153X



INSRS:

WSP:

Tel:

Liability:

RMKS:

LBA



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

12/12

2 min

02012018

2:42pm

23022018:

SLE 8153X - X; 6BD 4700S - X

Spoke to OTO (Mr Tan) - confirmed accident details and OTO moving out from minor with a stoppage. OTO will send any additional photo via email. Informed abt TP claim, aware of NCD rules and agree to settle. Send letter to OI.

File pass to COR: 2,450.00
 Refund to LOU: 5 x \$100.00 = 500.00
 LTA: 34.35

Total: 2,984.35 / G/L: 2,980.00

RECEIVED 23 FEB 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

15.12.2017

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

07022018

Confirm with:

Karen

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: 9d

Repair Cost:

SS 2,450.00

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

500.00 (\$100 x 5 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

34.35

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

Total:

SS

2,984.35

Global Sum SS: 2,980.00

FINAL PAYMENT

Date/Time:

07022018

Confirm with:

Karen

Email

Call

Payee 1:

SS

2,980.00

Name 1:

LBA Automotive Pte. Ltd.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400.00

COPY SENT
573/18




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI17023581/Uka3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 12-12-2017	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 4700S	Veh. Inspected	SLE 8153X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/12/2017	Inspection Date	12/12/2017
Survey held at	LBA AUTOMOTIVE PTE. LTD. 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

LBA AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

GBD47005

ESTIMATE

DATE : 11.12.2017
VEHICLE NO : SLE8153X
MAKE/MODEL : HONDA CIVIC
ACC DATE : 11.12.2017

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
<u>LIST PRICE</u>			
1	1 FRT HEADLAMP LH	912.70	912.70
2	1 FRT HEADLAMP LOWER BRACKET LH	29.10	29.10
3	1 FRT BUMPER	683.70	683.70
4	1 FRT BUMPER REINFORCEMENT	259.60	259.60
5	2 FRT BUMPER SIDE RETAINER RH/LH	16.20	32.40
6	1 RADIATOR SPARE TANK	43.80	43.80
7	1 AIR RESONATOR	189.70	189.70
8	1 FRT FENDER LH	450.80	450.80
9	1 FRT FENDER STAY BRACKET LH	19.20	19.20
10	1 FRT FENDER COWLING LH	94.80	94.80
		2420.4	2,715.80
		LESS 20%	543.16
		1936.32	2,172.64

<u>SPECIAL NETT ITEMS</u>			
1	1 (SET) FRT BUMPER CLIP	45.00	45.00
2	1 (SET) HADLAMP HID CONTROL UNIT	350.00	350.00
3	1 (SET) FRT FENDER COWLING CLIP	35.00	35.00
			430.00

<u>LABOUR CHARGES :</u>			
1	TO KNOCK OUT DENT AND REPLACE ACCIDEN PARTS	420	500.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	580	600.00
3	TO CHECK WIRING	20	30.00
4	TO TUFF KOTE	30	60.00
			1,190.00

not Ackd
h/s 32450/c
4 day.
12/12/17
taking photo. After repair

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 3,792.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	3222E

Vehicle Details

Vehicle No.	SLE8153X
Vehicle to be Exported	Yes
Intended De-registration Date	11 Dec 2017
Vehicle Make	HONDA
Vehicle Model	CIVIC 1.8L A
Primary Colour	Grey
Manufacturing Year	2006
Engine No.	R18A11039164
Chassis No.	JHMFD16206S211718
Maximum Power Output	103.0 kW (138 bhp)
Open Market Value	\$18,891.00
Original Registration Date	05 Sep 2006
First Registration Date	05 Sep 2006
Transfer Count	1
Actual ARF Paid	\$20,781.00

Intended PARF Rebate Details

PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	31 Aug 2021
COE Category	B - Car (1601cc & above)
COE Period(Years)	5
PQP Paid	\$27,232.00
COE Rebate Amount	\$20,262.00
Total Rebate Amount	\$20,262.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Dec 2017



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/CTI17023581/Uka3

Date: 15.12.2017

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLE 8153X


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/12/2017 at the premises of M/s LBA Automotive Pte. Ltd. - Kaki Bukit and have the following to report:-

Workshop Estimate Amount	: S\$	3,792.64
Revised Estimate Amount	: S\$	2,450.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Mei Kwan (LKKAUTO)

From: Jowyn Tay <jowyn.tay@sg.cntaiping.com>
Sent: Friday, 15 December, 2017 4:21 PM
To: Mei Kwan (LKKAUTO); Zaini (LKK Auto)
Cc: Hsiao Tong (LKKAUTO); Admin A; Jowyn Tay
Subject: RE: Direct Settlement - Accident Involving GBD4700S (OI : SNM17D07065/C02/0/LKKDS) AND SLE8153X (TP : LKK REF - CC6/CTI17023581/Uka3) on 11/12/2017
Attachments: SNM17D07065C02 20171215-TO INSD-APPT LKK.pdf; MJAS17163374-GBD4700S.pdf
Importance: High
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Zaini &/or Mei Kwan,

Please refer to the attachments.

Thank you.

Regards,

Jowyn Tay

Deputy Claims Executive

Motor Division

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6174

Fax: 6224 7175 / 6224 7478

Email: claimsdept@sg.cntaiping.com

jowyn.tay@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]

Sent: Friday, 15 December, 2017 9:49 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Jowyn Tay <jowyn.tay@sg.cntaiping.com>; Zaini (LKK Auto) <Zaini@lkkauto.com>; Hsiao Tong (LKKAUTO)



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.cntaiping.com

Co. Reg. No. 200208384E

Our Reference: **SNM17D07065/C02/0**

Date : **15 DECEMBER 2017**

via Ordinary & Registered Mail

**CHOR JUAY ENTERPRISE
BLK 733 TAMPINES STREET 71
#10-71 TAMPINES COURTVIEW
SINGAPORE 520733**

Dear Sir / Madam

**ACCIDENT INVOLVING GBD4700S AND SLE8153X ON 11 DECEMBER 2017
ALONG TAMPINES STREET 71**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SLE8153X**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : ZAINI

Ref : CC6/CTI17023581/Uka3

Contact No : 68412132

via Email : Zaini@lkkauto.com

CC : Agent - (AN0478A) - INSURE HUB PTE LTD

F01/LKKDS-2013

Zaini (LKK Auto)

From: LBA Automotive Pte. Ltd. <lbaautomotive@hotmail.com>
Sent: Tuesday, 6 February 2018 11:07 AM
To: Zaini (LKK Auto)
Cc: Hsiao Tong (LKKAuto)
Subject: RE: Your Ref: LBA1217-2362_ACCIDENT INVOLVING SLE 8153X & GBD 4700S ON 11/12/2017

Importance: High

Follow Up Flag: Follow up
Flag Status: Flagged

Dear Zaini,

We confirmed acceptance your offer of settlement \$ 2980/- all in.

Thanks & Best Regards

Ms Karen
LBA Automotive Pte Ltd
1 Kaki Bukit Ave 6
#02-47 Autobay
Singapore 417883
Tel: 6509 5521
Fax: 6509 5523

From: Zaini (LKK Auto) [mailto:Zaini@lkkauto.com]
Sent: Friday, 2 February, 2018 9:43 AM
To: LBA Automotive Pte. Ltd.
Cc: Hsiao Tong (LKKAuto)
Subject: RE: Your Ref: LBA1217-2362_ACCIDENT INVOLVING SLE 8153X & GBD 4700S ON 11/12/2017

WITHOUT PREJUDICE

Dear Karen,

We refer to your email below.

For a quick and amicable settlement, we revised our offer to settle global sum at S\$ 2,980.00 (all in)

Kindly confirm acceptance

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: LBA Automotive Pte. Ltd. [<mailto:lbaautomotive@hotmail.com>]

Sent: Tuesday, 30 January 2018 5:15 PM

To: Zaini (LKK Auto) <Zaini@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Your Ref: LBA1217-2362_ACCIDENT INVOLVING SLE 8153X & GBD 4700S ON 11/12/2017

Importance: High

Dear Zaini,

We would like to counter propose as below

COR	\$ 2450.00
LOU	\$ 500.00 (5 days) 1.8cc vehicle
LTA/EFILE	\$ 34.35

Please look into the matter and revert soon.

Thanks & Best Regards

Ms Karen

LBA Automotive Pte Ltd

1 Kaki Bukit Ave 6

#02-47 Autobay

Singapore 417883

Tel: 6509 5521

Fax: 6509 5523

From: Zaini (LKK Auto) [<mailto:Zaini@lkkauto.com>]

Sent: Wednesday, 24 January, 2018 9:12 AM

To: LBA Automotive Pte. Ltd.

Cc: Hsiao Tong (LKKAuto)

Subject: RE: Your Ref: LBA1217-2362_ACCIDENT INVOLVING SLE 8153X & GBD 4700S ON 11/12/2017

WITHOUT PREJUDICE

Dear Karen,

We refer to your email below.

For a quick and amicable settlement, we revised our offer to settle global sum at S\$ 2,880.00 (all in)

Kindly confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: LBA Automotive Pte. Ltd. [<mailto:lbaautomotive@hotmail.com>]
Sent: Monday, 22 January 2018 2:41 PM
To: Zaini (LKK Auto) <Zaini@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: Your Ref: LBA1217-2362_ACCIDENT INVOLVING SLE 8153X & GBD 4700S ON 11/12/2017
Importance: High

Dear Zaini,

We would like to counter propose as below.

COR	\$ 2450.00
LOU	\$ 500.00
LTA/EFIL	\$ 34.35

Our client vehicle is 1.8cc, please look into the matter again.

Thanks & Best Regards

Ms Karen
LBA Automotive Pte Ltd
1 Kaki Bukit Ave 6
#02-47 Autobay
Singapore 417883
Tel: 6509 5521
Fax: 6509 5523

From: Zaini (LKK Auto) [<mailto:Zaini@lkkauto.com>]
Sent: Monday, 22 January, 2018 9:35 AM
To: LBA Automotive Pte. Ltd.
Cc: Hsiao Tong (LKKAuto)
Subject: Your Ref: LBA1217-2362_ACCIDENT INVOLVING SLE 8153X & GBD 4700S ON 11/12/2017

WITHOUT PREJUDICE

Your Ref: LBA1217-2362
Our Ref: CC6/CTI17023581/Uka3

Dear Sirs,

ACCIDENT INVOLVING SLE 8153X & GBD 4700S ON 11/12/2017

We refer to the above matter

For a quick and amicable settlement, we offer to settle global sum at **S\$ 2,730.00 (all in)**

Kindly confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI17023581/Uka3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 27-02-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 4700S	Veh. Inspected	SLE 8153X
Policy No.	DMCVSN3082991700	Coverage (\$)	0.00
Claim No.	SNM17D07065C02	Excess (\$)	0.00
Assign From		Assign Date	12/12/2017

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC (A)	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JHMF16206S211718	Colour	GREY
Odometer	127140	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45R17	CONTINENTAL	6 mm
L/H Front Tyre	225/45R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/45R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/45R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/12/2017	Inspection Date	12/12/2017
Survey held at	LBA AUTOMOTIVE PTE. LTD. 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 8153X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT HEADLAMP LH	CRACKED	912.70	912.70
1	FRT HEADLAMP LOWER BRACKET LH	BENT	29.10	29.10
1	FRT BUMPER	TORN	683.70	638.00
1	FRT BUMPER REINFORCEMENT	DENTED	259.60	259.60
2	FRT BUMPER SIDE RETAINER RH/LH @ \$16.20	N/S BENT	32.40	16.20
1	RADIATOR SPARE TANK	NOT NECESSARY	43.80	-
1	AIR RESONATOR	NOT NECESSARY	189.70	-
1	FRT FENDER LH	BUCKLED	450.80	450.80
1	FRT FENDER STAY BRACKET LH	BENT	19.20	19.20
1	FRT FENDER COWLING LH	TORN	94.80	94.80
	LESS 20% DISCOUNT		-543.16	-484.08
			2,172.64	1,936.32
SPECIAL NETT ITEMS				
1	SET FRT BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	SET HEADLAMP HID CONTROL UNIT (SN)	NOT NECESSARY	350.00	-
1	SET FRT FENDER COWLING CLIP (SN)	NECESSARY	35.00	35.00
			430.00	80.00
LABOUR				
	TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS.		500.00	420.00
	TO SPRAY PAINTING ON ACCIDENT PORTION.		600.00	580.00
	TO CHECK WIRING.		30.00	20.00
	TO TUFF KOTE.		60.00	30.00
			1,190.00	1,050.00
GRAND TOTAL			3,792.64	3,066.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,450.00

Report Ref No. CC6/CT117023581/Uka3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.