

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719
Workshop: 24, Sungei Kadut Street 4 Singapore 729050
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712
Business Reg. No: 36463500B

M/s: AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-10
Singapore 068811

7 days.
The Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 12.12.2017

Motor Claim Dept

Vehicle number : XD 6245 R
Make/Model : MAN TGS 35.360
Date of accident : 05.08.2017
Claim Type : TP Claim

Sebastian
12/12/2017
- Lump Sum Repair.
- Photo After Paint.
900 36121
sebastianyeang@lkkauto.com.

Accident involving XD 6245 R & YN 7345 P along AYE on 05.08.2017.

Re: Estimate

1.	1 pc	Rear bumper (S/Nett) ✓ DT	\$	800.00 ✓
2.	2 pcs	Rear bumper bracket top (S/Nett) ✓ BT	\$	700.00 ✓
3.	2 pcs	Rear bumper bracket lower (S/Nett) ✓ BT	\$	680.00 ✓
4.	2 pcs	Rear lamp bracket (S/Nett) ✓ BT	\$	900.00 ✓
5.	2 pcs	Rear lamp (S/Nett) ✓ CRK	\$	580.00 ✓
6.	2 pcs	Rear lamp box (S/Nett) ✓ BT	\$	400.00 ✓
7.	1 pc	Rear no plate (S/Nett) X	\$	25.00
8.	1 pc	Rear no plate bracket (S/Nett) ✓ BT	\$	250.00 ✓
9.	2 pcs	Rear pipe u clip (S/Nett) ✓ BT	\$	360.00 ✓
			\$	4,695.00

To Towing Service (from LTA)	\$	300.00 ✓
To Wiring Service	\$	120.00 40
To Logo Writing Service	\$	300.00 200
To Replace & Repair Labour Charge	\$	1,500.00 1200
To Putty & Spray Painting	\$	1,000.00 800

Total \$ 7,915.00

Yours Faithfully,

李光華 摩哆燒焊

LEE KUAN HWA MOTOR SERVICE
39, Westwood Avenue, Singapore 648719
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712