

22/03/2002

ASS. REC. BY:

REF:

CS / ASM17028637 / T11b

Special Instruction:

Surveyor:

Taufik.

**ASSIGNMENT (Office)**

Smart claim

From (Person):

Winnik Ho

of

AXA

Date/Time: 13.12.2017 11.16am

Estimated Cost:

Bill to:

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No:

SLC 3550B

Insured:

at Workshop m/s

Charm's Customcraft

Tel:

6271 7054

of

Blk 1010 Bukit Merah Lane 3 #01-105

Policy No:

Claim No:

S7M00517

Sum Insured:

Excess:

\$600.00

Make of Veh:

(Client's Record)

D.O.A 11.12.2017

**CA / REV / REP. / REV 24 HRS**

H.O.D. Endorsement:

Date/Time:

13.12.2017 11.26am

Person Contacted:

Sharna

Vehicle **IN** / OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

SLC 3550B x

14/12-@ 10:44am revert via Smart claim.

14/12 @ 9:50am inform Sharon to authorise limit 7K. lump sum

~~Revert~~ Received email from workshop withdraw claim.  
 Submit preli report

Signature

Taufik

REF:

Ax17

# ASSIGNMENT

CoE: 2021 Aug.

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: **9600**  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **927K**  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

☒ CA / ☐ REV / ☐ REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: **Sharon** Vehicle: IN / OUT

Veh No: **SLC 3550B** Regn: **2006 Aug**  
 Type: ☒ M Car / ☐ M Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /  
 Truck / Trailer or  
 Make: **Toyota Mark X 2.5A** 2799  
 Colour: **8/ver.** A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA  
 Sp Reading: **(Signature)** T Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA  
 Eng/No: \_\_\_\_\_  
 C/No: **GRX1200047703**  
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt  
 Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or  
 Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or  
 Modi: ☐ Nil / ☒ SRim / ☐ STD A/Rim or  
 Tyre Size: F: **215/60R16** R: **1**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Hankook**  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: **6** mm R/Bal: **6** mm  
 L/Bal: **6** mm L/Bal: **6** mm  
 D.O.A. \_\_\_\_\_ D.O.I. **13/12/17**  
 Survey held at **Chavis Insurance BSM**  
 Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☒ N/S / ☒ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction **Repair limit 97K. Email to Sharon limit repair 97K.**  
**to Battery work**

RECEIVED 13/12/17

Date/Time File Pass to? ☒ Preli. Report  
**Old Typast** ☒ Final Report  
 Date/Time File Return to?

Days Of Repair: **10**  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ Site Insp \$  
☐ Interview \$  
☐ Tech. Insp \$  
☐ Weekend \$

Report Format: **OD**  
 Lump Sum / I.B.I. \$

Survey Fee:	<b>250</b>
Transporter	
S - PS	
Prices	
Others	
TOTAL	<b>250</b>



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/AXA17023637/T1tb

8 SHENTON WAY #24-01

AXA TOWERSINGAPORE 068811

Date : 13-12-2017



Code : AXA2

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLC 3550B
Policy No.	Coverage (\$)	0.00
Claim No. S7M00517	Excess (\$)	600.00
Assign From SMART CLAIM (WINNIE HO)	Assign Date	13/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	11/12/2017	Inspection Date	13/12/2017
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724		

## 5a. Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S7M005I7

Our Ref: CS/AXA17023637/T1tb

Date: 14/12/2017

The Motor Claims Department  
M/s AXA Insurance Singapore Pte Ltd

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO SLC 3550B**


We thank you for the instruction on 13/12/2017

Please be informed that we had conducted the inspection of the abovementioned vehicle on 13/12/2017 @ 12NOON at the premises of M/s CHARN'S CUSTOMCRAFT and have the following to report:-

Workshop Estimate Amount : S\$ 16,066.00  
Revised Estimate Amount : S\$ 8,480.00  
"Check" Items Amount : S\$ 5,901.00  
Total : S\$ 14,381.00  
Market Value : S\$ 27,000.00  
LTA Reimbursement Value : S\$ 19,926.00  
Nett Value : S\$ 7,074.00

Description of Damage:

The vehicle sustained damages at the Front n/s and rear portion.



Comments/ Present Status:

Damages Consistent

Repair cost economical

We have authorize repair on 14/12/2017 @ 950AM

Repairster agree to repair on Lump Sum

Days of repair: 3 Days

Yours Faithfully,

Taufikh  
Automotive Assessor

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Thursday, 14 December, 2017 10:47 AM  
**To:** 'Charn's Customcraft'; Taufikh (LKKAuto)  
**Subject:** RE: SLC 3550B REPAIR LIMIT

**Sensitivity:** Confidential

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLC 3550B (Excess \$600/-). NOT EXCEEDING \$7000 LUMP SUM**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Charn's Customcraft [mailto:[charns@singnet.com.sg](mailto:charns@singnet.com.sg)]

**Sent:** Thursday, 14 December, 2017 9:36 AM

**To:** Taufikh (LKKAuto) <[Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)>

**Cc:** Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)>

**Subject:** RE: SLC 3550B REPAIR LIMIT

**Importance:** High

**Sensitivity:** Confidential

Hi Taufikh

We would like to counter offer \$7k>

Kindly seek for approval.

Thanks & Regards,

Sharon Lee

Charn's Customcraft

Tel: 6272 5429 Fax: 6273 6676

Email: [charns@singnet.com.sg](mailto:charns@singnet.com.sg)

GST Reg. No: M90367863L

Company Reg No: 25151300M

---

**From:** Taufikh (LKK Auto) [mailto:[taufikh@lkkauto.com](mailto:taufikh@lkkauto.com)]

**Sent:** Thursday, 14 December, 2017 8:53 AM

**To:** 'Charn's Customcraft'

**Cc:** 'Denise Tay (LKKAuto)'

**Subject:** SLC 3550B REPAIR LIMIT

**Sensitivity:** Confidential

# Enquire PARF/COE Rebate for Registered Vehicle

11/12/17  
345 Fmths  
44mths

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	2146Z
Vehicle Details	
Vehicle No.	SLC3550B
Vehicle to be Exported	No
Intended De-registration Date	14 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	MARK X 2.5 A
Primary Colour	Silver
Manufacturing Year	2006
Engine No.	4GR0129905
Chassis No.	GRX1200047703
Maximum Power Output	158.0 kW (211 bhp)
Open Market Value	\$32,971.00
Original Registration Date	12 Aug 2006
First Registration Date	12 Aug 2006
Transfer Count	1
Actual ARF Paid	\$36,269.00
Intended PARF Rebate Details	
PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	11 Aug 2021
COE Category	E - Open Category
COE Period(Years)	5
PQP Paid	\$27,232.00
COE Rebate Amount	\$19,926.00
Total Rebate Amount	\$19,926.00

**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Dec 2017

OK

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	2146Z

### Vehicle Details

Vehicle No.	SLC3550B
Vehicle to be Exported	Yes
Intended De-registration Date	31 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	MARK X 2.5 A
Primary Colour	Silver
Manufacturing Year	2006
Engine No.	4GR0129905
Chassis No.	GRX1200047703
Maximum Power Output	158.0 kW (211 bhp)
Open Market Value	\$32,971.00
Original Registration Date	12 Aug 2006
First Registration Date	12 Aug 2006
Transfer Count	1
Actual ARF Paid	\$36,269.00

### Intended PARF Rebate Details

PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

### Intended COE Rebate Details

COE Expiry Date	11 Aug 2021
COE Category	E - Open Category
COE Period(Years)	5
PQP Paid	\$27,232.00
COE Rebate Amount	\$19,677.00
<b>Total Rebate Amount</b>	<b>\$19,677.00</b>

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Dec 2017

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

### ADDENDUM

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No : MCCC17163334 Vehicle Registration No: SLC 3550 B  
Name (as shown in NRIC) : Lim Hock Heng NRIC/FIN/Passport No : S17021467  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
Address : Blk 76A Redhill Rd #08-04 Singapore (151076)  
Contact (Tel) : \_\_\_\_\_ Mobile No. : 81638606  
Email Address : vmaxlim@gmail.com  
Date of Accident : 4/12/17 Time of Accident : 1825  
Place of Accident : Lentor Ave twds @ SLE  
Insurance Company : AXA Insurance Pte Ltd.

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To withdraw own damage claim. Repair @ own cost.



Policyholder / Driver's Signature  
Date:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:  
Date:



## Service Address

Blk 1010 Bukit Merah, , , 159724

## Primary Contact/Insured

LIM HOCK HENG

08-04, 76A REDHILL ROAD, 151076, Singapore, Singapore

vmaxlim@gmail.com

## Claim Handler

Winnie HO

6568804833

winnie.ho@axa.com.sg

## Additional Instructions

1) survey @ charn's customcraft 2) est- \$15,901 3) xs-\$600

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)




## Service Request Details

Claim

S7M005I7

Reference

None 

Loss Date

December 11, 2017

Request Date

December 13, 2017

Due Date

December 20, 2017

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SLC3550B

Make

TOYOTA

**SGCARMART.COM**  
 THE ONLY PLACE FOR SMART CAR BUYERS

All Car Mark

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES



**FOR DIRECT BUYERS & SELLER**  
100% FREE SETTLEMENT ON LOANS, INSURANCE & PAPERWORK

**SGCARMART CONNECT**  
BRIDGING BUYERS & SELLERS

**Post an Advertisement**

Sell it yourself! Advertise it at just

**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

**Brand New Toyota C-HR Hybrid 1.8A G @ \$118,888!**


Delivery By End Of December

2017! 1 Bid Guaranteed COE

Without Top Up! Call Now!

Apex Trading Pte Ltd StarAd







Browse by Category

Sort by Date

4 vehicles

Toyota Mark

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
<b>Search Selection</b>	Toyota Mark	Any	Any	> 10 year(s) old	Any	Any	
	Toyota Mark X (COE till 05/2021)		\$26,900	\$7,770 /yr	04-Aug-2006	2,499 cc	-
100% Accident Free, Low Depreciation Per Day Only \$19 Cheaper Than Rent A Car, Well Taken Care By Owner, All Wear And Repair Needed, High Loan Available, Trade In Welcome, Pleas...							
Posted: 13-Dec-2017 Tags: 2006 Toyota Mark, 2006 Toyota Mark, Toyota Mark, Toyota Mark, Toyota, Mark, Mark, Used Toyo							
	Toyota Mark X (COE till 06/2021)		\$29,988	\$8,480 /yr	28-Jun-2006	2,499 cc	-
Low Interest Rate Of 1.98%, Well Maintained, And Mint Condition. Spacious Interior! NO REPAIR NEEDED! Call Our Friendly i Obligation Test Drive At Your Door Step!							
Vroomcars Pte Ltd							
Posted: 07-Dec-2017 Tags: 2006 Toyota Mark, 2006 Toyota Mark, Toyota Mark, Toyota Mark, Toyota, Mark, Mark, Used Toyo							
	Toyota Mark X (COE till 10/2021)		\$33,000	\$8,580 /yr	19-Oct-2006	2,499 cc	111,181
Selling Lower Than Balance COE Plus Parf Value. Beautiful Upgraded Sports Rims And Special Designed Unique Tail Lamps. & Recent Parts Replacement Receipts. Please Call To Arrange ...							
Posted: 15-Nov-2017 Tags: 2006 Toyota Mark, 2006 Toyota Mark, Toyota Mark, Toyota Mark, Toyota, Mark, Mark, Used Toyo							
	Toyota Mark X (COE till 05/2026)		\$68,800	\$8,130 /yr	01-Jun-2006	2,499 cc	171,701
Beautiful Car Maintained In Excellent Condition By 1 Careful Owner, Cheapest Depreciation In The Market, Nice Interior All R Classic Luxury And Elegant With Premium Interior Superb...							
Posted: 12-Oct-2017 Tags: 2006 Toyota Mark, 2006 Toyota Mark, Toyota Mark, Toyota Mark, Toyota, Mark, Mark, Used Toyo							

Save this search criteria, to get email alerts whenever a match is found.

Compare

Make Model Price Depreciation Reg Date Eng Cap Mileage

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/12/2017 13:23
Date Of Accident	11/12/2017 18:25
Exact Location Of Accident	LENTOR AVE TWDS SLE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC3550B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM HOCK HENG
NRIC No	S1702146Z
Email Address	VMAXLIM@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81638606
Alternative Phone No	OFFICE-NOPHONE

### Vehicle Particulars

Manufacturer	TOYOTA
Model	MARK X-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA246428
Cover Note Number	

### Driver

Name of Driver	LIM HOCK HENG
NRIC No	S1702146Z
Date Of Birth	28/10/1965
Occupation	OUTDOOR
Date Of Driving Pass	06/05/1986
Driving Experience	31 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81638606
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	VMAXLIM@GMAIL.COM

Address	BLK 76A REDHILL ROAD #08-04
Postcode	151076
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### **General Information of the Accident**

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

#### **Other Information**

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### **Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### **Circumstances of Accident**

REFER TO SKETCH AND ATTACHED

#### **Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**SKETCH PLAN**

**IMPORTANT NOTICE**

VEHICLE NO: SLC3450 B  
ACCIDENT DATE: 11/12/17

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**NOTE: DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.**

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name  
NRIC/FIN No.:

CHARN'S CUSTOMER CRAFT

### SKETCH PLAN

210  
L  
18  
Nov 1921

Refer to the attached

I/We declare the foregoing particulars are true in every respect.

CHARN'S CUSTOMCRAFT



On 12/12/2017 at about 1825hrs, I was traveling along Lentor Ave towards SLE. It was raining heavily and road was slippery. I was approaching a bend, lost control and accidentally hit onto the left wall. My car spin and hit the RH wall thus, causing damages on the front and rear left hand side.




Lim Hock Heng  
S1702146Z  
SLC 3550 B  
81638606



Sketch Plan #4 Pg. 1

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S1702146Z



Name  
**LIM HOCK HENG**

Race  
**林 福 兴**  
**CHINESE**

Date of birth  
**28-10-1965**

Sex  
**M**

Country/Place of birth  
**SINGAPORE**

S1702146Z

REPUBLIC OF SINGAPORE DRIVING LICENCE



28 Oct 1965  
28 Sep 2016

002814595K

5653830

NRIC No. S1702146Z

Date of issue  
28-09-2016


Address  
APT BLK 75A REDHILL ROAD  
#08-04  
SINGAPORE 151076

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

Class	Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles with unladen weight <= 2500kg	EFFECTIVE DATE
Class 3		06 May 1986

NP 428A

Licence No: S1702146Z



# CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

GST Reg. No. M90367863L

AXA INSURANCE PTE LTD

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.
12/12/2017	MAIN	41833

OWN DAMAGE CLAIM			
ESTIMATE COST OF REPAIR FOR VEHICLE NO: <b>SLC3550B</b>			
Make/Model	DOA	Policy No	Chassis No.
<b>TOYOTA MARK X 2.5</b>	<b>11/12/2017@1825</b>	<b>GA246428</b>	<b>GRX1200047703 (2006)</b>


Qty	Unit	Description	Amount
1.00	pc	Front Bonnet <i>bt ✓</i>	500.00
8.00	pc	Front Bonnet Sponge Clips @ \$3 <i>net ✓</i>	24.00
9.00	pc	Front Bonnet Seal Clip @ \$3 <i>net ✓</i>	27.00
1.00	pc	Front Fender <i>ht ✓</i>	260.00
1.00	pc	Front Fender Inner Shield LH <i>de ✓</i>	150.00
8.00	pc	Front Fender Inner Shield Clips @ \$3 <i>net ✓</i>	24.00
2.00	pc	Front Fender Inner Shield Clips @ \$3 <i>net ✓</i>	6.00
1.00	pc	Front Bumper <i>de ✓</i>	250.00
1.00	pc	Front Bumper Retainer LH <i>net ✓</i>	25.00
1.00	pc	Front Bumper Retainer RH <i>net ✓</i>	25.00
1.00	pc	Front Bumper Sponge ?	70.00
1.00	pc	Front Bumper Reinforcement ?	165.00
6.00	pc	Front Bumper Clips @ \$3 <i>net ✓</i>	18.00
1.00	pc	Front Bumper Foglight Cover LH <i>net ✓</i>	50.00
1.00	pc	Front Headlamp (NORMAL) LH <i>one ✓</i>	540.00
1.00	pc	Front Support Panel Top Garnish ?	160.00
11.00	pc	Front Support Panel Top Garnish Clip @ \$3 ?	33.00
1.00	pc	Front Top Arm LH ?	250.00
1.00	pc	Front Shock Absorber LH ?	210.00
1.00	pc	Front Kunckle LH ?	250.00
1.00	pc	Front Kunckle Bearing LH ?	225.00
1.00	pc	Front Lower Arm LH ?	240.00
1.00	pc	Rear Door LH <i>RY ✓</i>	530.00
3.00	pc	Rear Door Speaker Rivets @ \$3 ?	9.00
8.00	pc	Rear Door Top Chrome Rivets @ \$3 ?	24.00
1.00	pc	Rear Fender LH <i>ht ✓</i>	450.00
1.00	pc	Rear Windscreen Moulding <i>net ✓</i>	60.00

CHARN'S CUSTOMCRAFT

Subtotal

GST 7%

Total



# CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

GST Reg. No. M90367863L

AXA INSURANCE PTE LTD

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.
12/12/2017	MAIN	41833

OWN DAMAGE CLAIM			
ESTIMATE COST OF REPAIR FOR VEHICLE NO: <b>SLC3550B</b>			
Make/Model	DOA	Policy No	Chassis No.
TOYOTA MARK X 2.5	11/12/2017@1825	GA246428	GRX1200047703 (2006)


Qty	Unit	Description	Amount
1.00	pc	Rocker Panel Garnish/side skirt LH <i>cd R</i>	390.00
1.00	pc	Rear Bumper <i>dl</i>	280.00
1.00	pc	Rear Bumper Retainer LH <i>ue</i>	40.00
2.00	pc	Petrol Tank Outer Cover Rivets @ \$3 <i>ue</i>	6.00
1.00	pc	Rear Shock Absorber LH ?	210.00
1.00	pc	Rear Kunckle LH ?	370.00
1.00	pc	Rear Kunckle Bearing LH ?	210.00
2.00	pc	Rear Top Arm ?	210.00
2.00	pc	Rear Lower Arm ?	300.00
1.00	pc	Rear Control Arm ?	150.00
1.00	pc	Sub-frame ?	1,375.00
1.00	pc	Exhaust Chrome LH ?	120.00
1.00	pc	Original Rim Front LH <i>cut</i>	1,105.00
1.00	pc	Original Rim Rear LH <i>dl</i>	1,105.00
		Subtotal - PARTS ONLY	10,446.00
1.00	pc	Tyre Front LH - S/NETT ? 80%/-	350.00
1.00	pc	Tyre Rear LH - S/NETT ? 80%/-	350.00
		Check wiring function	40.00 ✓
		Alignment	60.00 ✓
		Labour to remove and replace undercarriage front LH	180.00 120
		Labour to remove and replace undercarriage rear LH	180.00 120
		Labour to remove and reinstall rear gearbox to enable replace sub-frame.	250.00 ? 200
		Labour to remove and replace sub-frame	250.00 150 ?
		Press Bearing (front & rear)	120.00 100 ?

CHARN'S CUSTOMCRAFT

Subtotal

GST 7%

Total



# CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

GST Reg. No. M90367863L

AXA INSURANCE PTE LTD

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.
12/12/2017	MAIN	41833

OWN DAMAGE CLAIM			
ESTIMATE COST OF REPAIR FOR VEHICLE NO: <b>SLC3550B</b>			
Make/Model	DOA	Policy No	Chassis No.
TOYOTA MARK X 2.5	11/12/2017@1825	GA246428	GRX1200047703 (2006)

Qty	Unit	Description	Amount
		Labour to remove and replace front windscreen (unbroken)	180.00 /20
		Labour to remove and reinstall door glass rear LH (unbroken)	80.00 x
		Remove and install cushions, seats back rest, inner trim, garnish, roof lining and upholstery to facilitate repair.	180.00 /00.
		Remove necessary parts; jacking, panel beating, repair and straighten front inner panel, front support panel, front bonnet, front fender LH, front bumper, front door LH, rear door LH, rear fender LH, rear boot, rear fender, rear bumper and LH side skirt.	1,600.00 1400.
		Putty and respray the above-mentioned.	1,800.00 /600.

Note: The above is an estimate only. If other parts requested during the course of repair, we will inform you accordingly.

All new/O.E.M/used parts are subject to availability.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: CHARN'S CUSTOMCRAFT  
Date:

Tanpin 92495745  
Ex @ 600

Revert  
To check repair limit  
Resurvey before paint

13/12/17 @ 12pm.  
sur@lkkauto.com  
10 days.  
14/12/17

Subtotal	\$16,066.00
GST 7%	\$1,124.62
Total	\$17,190.62