

ASS. REC. BY:

REF: CS/FCI7023640/Uqd3nz Special Instruction:

Surveyor: Marcus ASSIGNMENT (Office)From (Person): CWS May Chua of FCI Date/Time: 5.50pm @ 12/12/17

Estimated Cost: _____ Bill to: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CSTo Inspect Vehicle No: SGY 2202G Insured: SHC 3670Kat Workshop m/s Imperium Automotive Tel: 97489940of 25 kaki Bukit Rd 4 # 01-49 SynergyPolicy No: P/15072701 MFSH Claim No: D17011454 MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 10/12/2017
(Client's Record)CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement: _____Date/Time: 10.18am @ 13/12/17 Person Contacted: Shawn Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction	Estimate
	SGY 2202G - NA/INC17023524/24	D.O.A: 10/12/2017
	SHC 3670K - NA/INC17023524/24	D.O.A: 10/12/2017
13/12/17 @ 6.49pm	revised to May Chua by email.	

SALES
Burglar (mercus)

REF:

Ful

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SGY22026
 at Workshop m/s: 1 myn
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 56
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGY22026 Yr Regn: 2 11
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or: CA
 Make: BMW 320i C.C. 1995
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 12/388 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: W3AP6560X0NM25661
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: _____ R: 25-5/35R18
 ES: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 mm Rear: 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 13/12/17
 Survey held at: _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
o/s Rear &
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction L7A 44372
3yrs 2mth. Sep 12 net 11628

13/12@6:32pm - revert preli advise. via email

3/1/18 conf. int L/S & 6150 with Shown.
(Red ID 1044385, 63%)

RECEIVED 3 JAN 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) 03/01 transfer ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

☐ S + RS (\$)

☐ Photos OSP

☐ Other 8/1/18

Report Format: TP

Lump Sum / L.B.I.: (\$ 6150)

TOTAL

6x15 90

170+90

50

50+50

56

466



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17023640/Uqd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3670K	Veh. Inspected	SGY 2202G
Policy No.		Coverage (\$)	0.00
Claim No.	D17011454MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	13/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/12/2017	Inspection Date	13/12/2017
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011454MFSH

Date: 13/12/2017

Our Ref: CS/FCI17023640/Uq

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGY 2202G

Please be informed that we had conducted the inspection of the abovementioned vehicle on 13/12/2017 at the premises of M/s IMPERIUM at and have the following to report:-

Workshop Estimate Amount	: S\$ <u>16,593.85</u>
Revised Estimate Amount	: S\$ <u>9,452.05</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
At o/s rear portion.



Repair days: 5

Yours faithfully

Marcus

Motor Surveyor

Survey Department Check List (Case Handler)

Reference No.: C8/PC117023640/UGD3
Policy Type: OD (TP) / TP RES / TL / EVA

SAY 2026

Case Handler

Typist

Admin (Nivitha): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Mohan): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓			
---	--	--	--

Check By:

[Signature] 03/01/18

Case Handler

Date

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	12-12-2017	Our Ref No. D17011454MFSH
Accident Date	10-12-2017	Claim Type. Third Party
Insured Vehicle	SHC3670K	Third Party Vehicle. SGY2202G
Survey Location	25 KAKI BUKIT ROAD 4 #01-49 SYNERGY@KB	
Contact Person.	SHAWN TAN	
Contact No.	97489940/ 97489940	Fax No. 63467213
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	IMPERIUM AUTOMOTIVE	Attention. NIL
Cc : TP Solicitor	JUSEQUITY LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231798)



PRI Documents



Close



PRI Header Details

Claim No	D17011454MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & JUSEQUIT
Workshop Name	IMPERIUM AUTOMOTIVE (Contact Person : SHAWN TAN)	Survey Location & Contact Details	25 KAKI BUKIT ROAD 4 #01-49 SYNERGY@KB Mobile: 97489940 , Phone: 97489940 , Fax: 6346721: EmailId: ALFREDJUSEQ@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3670K	TP Vehicle No	SGY2202G
PRI Recieved Date	12-12-2017 06:41:57 PM	Surveyor Appointed Date	12-12-2017 05:48:54 PM	Surveyor Accept Date	13-12-2017 11

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	13-12-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 13 December, 2017 6:49 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: 'MAYCHUA@FIRST-INSURANCE.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D17011454MFSH/1
Attachments: PRELI ADVISED SGY 2202G.pdf

Ignore previous report

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SGY 2202G**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 13 December, 2017 6:32 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011454MFSH/1

"Without prejudice"

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SGY 2202G**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 13 December, 2017 10:30 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011454MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011454MFSH

Date: 13/12/2017

Our Ref: CS/FCI17023640/Uq

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGY 2202G

Please be informed that we had conducted the inspection of the abovementioned vehicle on 13/12/2017 at the premises of M/s IMPERIUM at and have the following to report:-


Workshop Estimate Amount	: S\$ 16,593.85
Revised Estimate Amount	: S\$ 9,452.05
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages

At o/s rear portion

The undercarriage affected due to collision



Repair days: 4

Yours faithfully

Marcus

Motor Surveyor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	4468C
Vehicle Details	
Vehicle No.	SGY2202G
Vehicle to be Exported	No
Intended De-registration Date	13 Dec 2017
Vehicle Make	B.M.W.
Vehicle Model	320i AT ABS D/AB 2WD 4DR GAS/D SR
Primary Colour	Silver
Manufacturing Year	2010
Engine No.	A599I778N46B20BD
Chassis No.	WBAPG560XONM25661
Maximum Power Output	115.0 kW (154 bhp)
Open Market Value	\$39,296.00
Original Registration Date	24 Feb 2011
First Registration Date	24 Feb 2011
Transfer Count	3
Actual ARF Paid	\$39,296.00 19648
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	23 Feb 2021
PARF Rebate Amount	\$25,542.00
Intended COE Rebate Details	
COE Expiry Date	23 Feb 2021
COE Category	E - Open Category
COE Period(Years)	10
QP Paid	\$67,009.00
COE Rebate Amount	\$18,830.00
Total Rebate Amount	\$44,372.00

The information contained herein is correct as at 13 Dec 2017

OK

sgCARMART.COM
 THE ONLY PLACE FOR SMART CAR BUYERS

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES


FORUM

TOOLS & TIPS

All

Car Make or Model

Search



FREE HELP
FOR DIRECT BUYERS & SELLER
100% FREE SETTLEMENT ON LOANS, INSURANCE & PAPERWORK

sgCARMART CONNECT
BRIDGING BUYERS & SELLERS

Username / Email Add

password

Submit Qu

Connect

Sign Up New Account

Forgot Password

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad


Advertiser Login

Ways of Selling

2015 BMW 435i Grand Coupe At \$183800 Only



Super Low Mileage At 3700km
Only, Agent Service, XMas
Special Free 9h Coating
Global Carz Pte Ltd StarAd



HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

Browse by Category

Back (1 2) Next

Sort by Date Posted

20 results/page

27 vehicles

bmw 320

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 320		Any	Any	2011	Any	Any	Any	Available
	BMW 3 Series 320i Sunroof		\$57,800	\$12,980 /yr	27-Jan-2011	1,995 cc	90,334 km	Luxury	Available
1 Owner, Latest Arrival Luxury Sporty White BMW 320i Among Its Class. Service Regularly Without Fail, Accident Free Yet Non Smoker Unit. No Repair Needed We Deliver Our Promise. Suitable For All Ages,...									
Posted: 11-Dec-2017 Tags: 2011 BMW 320i, 2011 BMW 320i, BMW 320i, BMW 320i, BMW, 320i, 320i, Used BMW									
	BMW 3 Series 320i Convertible		\$75,800	\$15,630 /yr	10-Jun-2011	1,995 cc	-	Sports	Available
Very Well Maintained By Previous Owner. Sporty White On Beige Interior. In House Financing Available. Up To 85% Loan! Please Call Our Sales Advisor For Test Drive/Viewing Now!									
SKL Automobile Pte Ltd									
Posted: 11-Dec-2017 Tags: 2011 BMW 320i, 2011 BMW 320i, BMW 320i, BMW 320i, BMW, 320i, 320i, Used BMW									
	BMW 3 Series 320i Coupe		\$75,222	\$13,540 /yr	16-Dec-2011	1,995 cc	-	Sports	Available
High Spec PML Unit With Large I-Drive System, Comfort Access, Bluetooth Audio And Telephony, Navigation, Paddle Shifter, Set Of New Tyre, Major Service Done With Essential Wear And Tear Replaced. 1 Ca...									
Posted: 11-Dec-2017 Tags: 2011 BMW 320i, 2011 BMW 320i, BMW 320i, BMW 320i, BMW, 320i, 320i, Used BMW									
	BMW 3 Series 320i Sunroof		\$71,000	\$15,630 /yr	31-Mar-2011	1,995 cc	27,000 km	Luxury	Available
A Beautiful Black Beast With Black Interior Single Owner, Very Lowest Mileage In The Market. Always Parked Under Covered Car Park. Car In Great Condition. Regular Servicing And Inspection Done. Body G...									
Posted: 11-Dec-2017 Tags: 2011 BMW 320i, 2011 BMW 320i, BMW 320i, BMW 320i, BMW, 320i, 320i, Used BMW									
Car Buying Car Ownership Car Selling On The Move Car Aftermarket Lifestyle Buy Tyres Online! Latest Special Offers from Tyrepix!									
	BMW 3 Series 320i Sunroof		\$59,800	\$11,380 /yr	29-Jun-2011	1,995 cc	92,000 km	Luxury	Available
Most Competitive Pricing In Its Class, Brilliant Blue On Fastidious Dakota Interior, 1 Meticulous Owner Only, Fully Maintained By PML Since Day 1, Mint Conditions Inside Out, Original Paintwork, Low M...									
Posted: 11-Dec-2017 Tags: 2011 BMW 320i, 2011 BMW 320i, BMW 320i, BMW 320i, BMW, 320i, 320i, Used BMW									
	BMW 3 Series 320i M-Sport Sunroof		\$68,800	\$12,460 /yr	01-Nov-2011	1,995 cc	98,339 km	Luxury	Available
1 Year Free Servicing! \$7K Down Payment! STA Certified Accident Free Quality Pre Owned With Low Mileage And Agent Service History For Peace Of Mind. 100% Loan Approval With Our Flexible In House Finan...									
Cosmo Automobiles									
Posted: 11-Dec-2017 Tags: 2011 BMW 320i, 2011 BMW 320i, BMW 320i, BMW 320i, BMW, 320i, 320i, Used BMW									
	BMW 3 Series 320i Coupe Sunroof		\$58,300	\$13,130 /yr	31-Jan-2011	1,995 cc	105,000 km	Sports	Available
High/Flexible Loan Available! Lowest Depreciation In Town! Well Maintained By Fussy Previous Owner! Low Mileage Done! Original Paintwork Since Day 1. Call To View In Our Air Conditioned Showroom Now!									
GS Automobiles Pte Ltd									
Posted: 11-Dec-2017 Tags: 2011 BMW 320i, 2011 BMW 320i, BMW 320i, BMW 320i, BMW, 320i, 320i, Used BMW									
	BMW 3 Series 320i		\$57,500	\$11,500 /yr	15-Apr-2011	1,995 cc	103,300 km	Luxury	Available
Well Maintained Paintwork And Leather Seats. No Consignment Will Be Entertained.									

25 Kaki Buki Road 4 #01-49 Synergy @ KB Singapore 417800
Tel: 9748 9940 Fax: 6346 7213

Vehicle No: SGY 2202G

Model: BMW 320i

Not Authorized
nku
2/5 ~~9~~ 6150 1/2
5 day.
(3/1/1)
Telapb. Office -
Prices \$

QTY	List Price:	
1	Rear bumper	1245.12
2	Rear bumper side retainer- RH/LH @ 115.00	66.05
1	Rear windscreen moulding	175.02
1	Rear fender - RH	1435.62
1	Rear fender cowling - RH	
1	Rear shock absorber - RH	
1	Rear top arm - RH	1
1	Rear top control arm - RH	
1	Rear stay arm - RH	
1	Rear stabilizer bar link - RH	
1	Rear drive shaft - RH	
1	Rear knuckle arm - RH	912.15
1	Rear knuckle bearing	
1	Rear lower arm - RH	
1	Rear door - RH	
1	Rear door rubber - RH	
1	Rear door lock - RH	

Less 5%

10/10/11	1780.00	✓
05/10/11	230.00	✓
11/10/11	201.00	—
3.15.11	1805.00	✓
11	148.00	✗
11	355.00	✓
11	198.00	✗
11	188.00	✗
11	247.00	✗
11	92.00	✗
11	1406.00	✗
11/10/11	1056.00	✓
11	365.00	—
11/10/11	437.00	✓
11	1470.00	✗
11	195.00	✗
11	410.00	✗
	<u>10583.00</u>	
	(507.65)	
Subtotal	<u>10075.35</u>	

4990.56
4741.41

Special Nett Items:

1	Rear windscreen sponge tape
1	Rear windscreen sealant
1	Rear bumper clip
1	Rear sport rim - RH
1	Rear tyre - RH
1	Rear fender cowling clip

me	50.00	30
me	80.00	40
me	45.00	✓
20/34	1800.00	8505.2
8r	700.00	x
ur	45.00	x
Subtotal	2720.00	

Labour Charges:

Panel beating, cut, weld, remove and replacing above parts

To respray painting and etc

To checking wiring

Refix rear windscreen

Refix cushion and inner trim

Refix fuel tank

Replace rear undercarriage

4 wheel alignment

To respray undercoating

LKK Auto Consultants name
the Repairer of the following:
• To resurvey before after spray p
• To repair the damage after spray p

	1200.00	800
	1200.00	700
	80.00	20
	150.00	120
	150.00	60
	120.00	60
	700.00	120
	120.00	60
	100.00	50
Subtotal	3820.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 16593.85

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

GRAND TOTAL

Acknowledged by Repairer:
Signature: _____

7696.41
6157.11

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: IMPERIUM AUTOMOTIVE
VIN: SGY 2202 G
Date: 15.12.17 10:40



SGY 2202 G

BMW : 3 Series - E90/E91 (2005 - 2012) : Sedan / Touring (Wagon) 09/2008- : with AFS (Active Front Steering) : Series :
19" Wheel

Front : Left

Actual	Before	Specified Range
-0°35'	-0°38'	-0°48' 0°12'
6°07'	6°07'	
0°09'	0°04'	0°05' 0°09'
9°06'	9°10'	
8°32'	8°32'	
		-2°10' -1°10'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°38'	-0°37'	-0°48' 0°12'
6°07'	6°07'	
0°07'	0°08'	0°05' 0°09'
17°36'	17°35'	
16°58'	16°58'	
		-2°10' -1°10'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°03'	0°00'	-0°30' 0°30'
0°00'	0°00'	-0°30' 0°30'
-8°29'	-8°25'	
0°16'	0°12'	0°02' 0°26'

Rear : Left

Actual	Before	Specified Range
-1°30'	-1°30'	-1°55' -1°05'
0°10'	0°09'	0°07' 0°11'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°29'	-1°29'	-1°55' -1°05'
0°09'	0°09'	0°07' 0°11'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°01'	-0°01'	-0°30' 0°30'
0°19'	0°18'	0°06' 0°30'
0°00'	0°00'	-0°12' 0°12'

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: IMPERIUM AUTOMOTIVE
VIN: SGY 2202 G
Date: 12.12.17 14:33



SGY 2202 G

BMW : 3 Series - E90/E91 (2005 - 2012) : Sedan / Touring (Wagon) 09/2008- : with AFS (Active Front Steering) : Series : 19" Wheel

Front : Left

Actual	Before	Specified Range
-0°42'	-0°42'	-0°48' 0°12'
5°56'	5°56'	
0°06'	0°06'	0°05' 0°09'
19°41'	19°41'	
18°59'	18°59'	
		-2°10' -1°10'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°46'	-0°45'	-0°48' 0°12'
6°12'	6°12'	
0°09'	0°08'	0°05' 0°09'
13°40'	13°39'	
12°54'	12°54'	
		-2°10' -1°10'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°04'	0°03'	-0°30' 0°30'
-0°16'	-0°16'	-0°30' 0°30'
6°01'	6°02'	
0°14'	0°14'	0°02' 0°26'

Rear : Left

Actual	Before	Specified Range
-1°39'	-1°40'	-1°55' -1°05'
0°09'	0°09'	0°07' 0°11'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-2°30'	-2°30'	-1°55' -1°05'
1°03'	1°03'	0°07' 0°11'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°51'	0°50'	-0°30' 0°30'
1°12'	1°12'	0°06' 0°30'
-0°27'	-0°27'	-0°12' 0°12'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023640/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3670K	Veh. Inspected	SGY 2202G	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011454MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	12/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 320I (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WBAPG560X0NM25661	Colour	SILVER	
Odometer	121388	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/35 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	255/35 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	255/35 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	255/35 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/12/2017	Inspection Date	13/12/2017	
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 2202G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / TORN	1,780.00	1,245.12
2	REAR BUMPER SIDE RETAINER-RH/LH @\$115.00	O/S BENT	230.00	66.05
1	REAR WINDSCREEN MOULDING	NECESSARY	201.00	175.02
1	REAR FENDER-RH	BADLY DENTED	1,805.00	1,435.62
1	REAR FENDER COWLING-RH	NOT NECESSARY	148.00	-
1	REAR SHOCK ABSORBER-RH	BENT	355.00	355.00
1	REAR TOP ARM-RH	NOT NECESSARY	198.00	-
1	REAR TOP CONTROL ARM-RH	NOT NECESSARY	188.00	-
1	REAR STAY ARM-RH	NOT NECESSARY	247.00	-
1	REAR STABILIZER BAR LINK-RH	NOT NECESSARY	92.00	-
1	REAR DRIVE SHAFT-RH	NOT NECESSARY	1,406.00	-
1	REAR KNUCKLE ARM-RH	BENT / TWISTED	1,056.00	912.15
1	REAR KNUCKLE BEARING	NECESSARY	365.00	365.00
1	REAR LOWER ARM-RH	BENT / TWISTED	437.00	437.00
1	REAR DOOR-RH	TO REPAIR SEE LABOUR	1,470.00	-
1	REAR DOOR RUBBER-RH	NOT NECESSARY	195.00	-
1	REAR DOOR LOCK-RH	NOT NECESSARY	410.00	-
	LESS 5% DISCOUNT		-529.15	-249.55
			10,053.85	4,741.41
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SPONGE TAPE (SN)	NECESSARY	50.00	30.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	REAR SPORT RIM-RH (SN)	DENTED / BENT	1,800.00	850.00
1	REAR TYRE-RH (SN)	SERVICEABLE	700.00	-
1	REAR FENDER COWLING CLIP (SN)	NOT NECESSARY	45.00	-
			2,720.00	965.00

Report Ref No. CS/FC117023640/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR DOOR-RH.		1,200.00	800.00
	TO RESPRAY PAINTING AND ETC.		1,200.00	700.00
	TO CHECKING WIRING.		80.00	20.00
	REFIX REAR WINDSCREEN.		150.00	120.00
	REFIX CUSHION AND INNER TRIM.		150.00	60.00
	REFIX FUEL TANK.		120.00	60.00
	REPLACE REAR UNDERCARRIAGE.		700.00	120.00
	4 WHEEL ALIGNMENT.		120.00	60.00
	TO RESPRAY UNDERCOATING.		100.00	50.00
			3,820.00	1,990.00
	GRAND TOTAL		16,593.85	7,696.41
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,150.00

Report Ref No. CS/FCI17023640/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.