

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45119
Date Estimated : 11/12/2017
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Poh Min Yuan
66 Jalan Gumilang

- ACCOUNT - 303
First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 668905

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SFS6666T	G459829	21/07/2017	540iA	0
DESCRIPTION		ORIGINAL PRICE	DISC. %	NETT
# To replace rear silencer with exhaust flap include alignment and conducting checks for leak		451.00		451.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	2.75	2.00		5.50 nec ✓
# TRANSMISSION BRACKET *	55.80	1.00		55.80 de ✓
# CLAMPING BUSH *	131.95	1.00		131.95 br ✓
# RH TAILPIPE TRIM CHROME *	144.10	1.00		144.10 cut ✓
# REAR SILENCER W/EXHAUST FLAP *	2,211.30	1.00		2,211.30 br ✓
# REAR SILENCER LH HEAT INSULATION *	157.75	1.00		157.75 br ✓
# REAR SILENCER RH HEAT INSULATION *	157.75	1.00		157.75 br ✓
# UNDERBODY PANELLING REAR *	41.30	1.00		41.30 de ✓
# CONTROL UNIT SMART OPENER *	457.45	1.00		457.45 cva ✓

Total Labour : 451.00
Total Parts : 3,362.90
Total Labour & Parts : 3,813.90