

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
SIN MING AUTOCITY, SINGAPORE 575722.
Tel No. : 64536256/64563715 Fax No. : 64557754
E-Mail : kumchew1@singnet.com.sg
GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

LONPAC INSURANCE BHD
100, BEACH ROAD #19-00 SHAW TOWER
SINGAPORE 189702

Attention : Motor Claim Department
Contact : 62507388 Fax No. : 62963767

Estimate : ES004248

Date : 12/12/2017
Vehicle Num. : SKM 7672 R
Make/Model : LEXUS RX270
Chassis/Eng# :
Accident Date : 05/12/2017
Claim No. :
Reference : KC/TP7672/1712-02
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|-------|----------------------------------|--|--|
| 1. | 1 PC | REAR BUMPER | | |
| 2. | 2 PCS | REAR BUMPER RETAINER | | |
| 3. | 1 PC | REAR BUMPER REFLECTOR - RH | | |
| 4. | 1 PC | REAR BUMPER REINFORCEMENT | | |
| 5. | 1 PC | REAR BUMPER LOWER GARNISH - R/H | | |
| 6. | 1 PC | REAR BUMPER REVERSE SENSOR - R/H | | |

LIST ITEMS :

REAR BUMPER
REAR BUMPER RETAINER
REAR BUMPER REFLECTOR - RH
REAR BUMPER REINFORCEMENT
REAR BUMPER LOWER GARNISH - R/H
REAR BUMPER REVERSE SENSOR - R/H

List Total S\$:
10.00% Discount S\$:

LABOUR :

TO PULL, KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART.
TO SPRAY & PAINT ON ACCIDENT PORTION.
TO ANTI-RUST REAR AFFECTED AREAS.
TO CHECK WIRING FUNCTIONS.
TO DISMANTLE & FIX REVERSE SENSOR.

Labour Total S\$:

SingDollars : Three Thousand Nine Hundred Eighty-Four & Cents Seventy-Two Only

Total S\$: 3,984.72

KUM CHEW MOTOR WORKSHOP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

is subject to final approval from Insurance Company

Acknowledged by Repairer
Date:

chk from
106.72
853.93
213.44
494.30
496.18
519.88
421.96
2,999.69
299.97
2,699.72
250. 350.00
500 680.00
X 120.00
30 85.00
40 50.00
1,285.00

Not Authorised
PIP Repair
Before paint job
LKK Auto Mkt.
18/12/2017
3w/ days