

 $51\ UBI\ AVE\ 1,\#02-25\ PAYA\ UBI\ INDUSTRIAL\ PARK, SINGAPORE\ 408933\ TEL: (065)\ 62563561\ FAX: (065)\ 62564315$

Immediate Advice

To: AXA Insurance Pte Ltd Date: 19/12/2018

Survey Details:

Date of loss	10-Dec-17
Date of appointment	12-Dec-17
Date of survey	19-Dec-17
Location of survey	PEGASUS ENGINEERING & TRADING PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLQ 9437H
Make and Model	MAZDA 3 SEDAN 1.5 AT - 1496cc
Date of registration	27-Jul-17
Excess	
Market Value (est)	\$0.00
Parf Rebate (est)	\$0.00
Nett Loss (est)	\$0.00

Repair details:

Initial Estimate	\$	4,234.80
------------------	----	----------

Proposed/Revised repair cost:

Lump Sum(if applicable)	\$ -
Total	\$ 1,400.00
Labour	\$ 500.00
Check items (estimate)	\$ -
Parts	\$ 900.00

Number of days for repair	2 DAYS
---------------------------	--------



 $51\ UBI\ AVE\ 1,\#02-25\ PAYA\ UBI\ INDUSTRIAL\ PARK, SINGAPORE\ 408933\ TEL: (065)\ 62563561\ FAX: (065)\ 62564315$

Remarks:

We have not authorized repairs. It was reported that Insured had lost contorl and rear-ended TP vehicle. An email was sent out to the Insured to notify TP claim, NCD and XS. No feedback till date. TP LOD IN. For mandate approval. - TP vehicle is a Grab vehicle. Claiming for LOI. LOU = Grab Rental Rate @ \$66.95 daily + LOI @ \$50 daily.

Mandate:

Liability(TP)	100%]
Proposed Repair Cost	\$ 1,498.00	w/gst
Loss of Use	\$ 220.00	\$110 x 2 days
Loss of Rental	\$ -	no. of days
Loss of Income	\$ -	no. of days
GIA search fees	\$ -	
Others	\$ -	
Proposed Total	\$ 1,718.00	