

Estimate

13/12/2017

AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
AXA TOWER #27-01
SINGAPORE 068811

Page # :- 1

Veh # :- SJK2279Z

Veh Model :- MERCEDES-BENZ C180K

Estimate# :- CK416784

Claim # :- 78 / CK130217

ACC. Date :- 06/12/17

Terms :- C.O.D Days

Remarks :- MFA 13 OCT 2008 (7808)

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Attention :- XA009

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT BUMPER CHROME MOULDING	2 PC	110.00	220.00 <i>new</i>
2.	FRONT BUMPER - REPAIR	1 PC		
3.	FRONT BUMPER SIDE RETAINER RH - CHECK	1 PC		
4.	HEADLAMP RH- CHECK	1 PC		
LIST TOTAL S\$				220.00
10% DISCOUNT S\$				-22.00
				198.00
LABOUR :				
TO INSPECT FRONT LIGHTING MECHANISM				40.00 ✓
TO REPAIR ON FRONT BUMPER. TO REMOVE & REFIX AFFECTED ATTACHMENT. REALIGN CONNECTION				180 280.00
TO SPRAY PAINT ON REPAIRED AREA				200 280.00
LABOUR TOTAL S\$				600.00

E. & O.E

NON-TAX AMOUNT S
AMOUNT S\$ 798.00
GST @ 7 % 55.86
AMOUNT DUE S\$ 853.86

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

KKR Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
49 90010068
2-3 days
P/P
19/12/17 @ 1145
Reay after repair