

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

AIG

Name : Rajurayan Singh S/O Suruj Singh

Accident Date : 2-Sep-17

Vehicle No : FBE 1030 G

Vehicle Model : Honda CL200

Estimated Repair Costs

Qty	Description	Amount S(\$)
	List Items	
1	Front fender	\$ 47 70.00 ✓
2	Fork inner tubes	\$ 2 350.00 x
2	Fork outer tubes	\$ 2 360.00 x
1	Fork under bracket	\$ 2 185.00 x
1	Front brake disc	\$ 17 185.00 x
1	Front rim shaft	\$ 17 42.00 x
1	Front rim bearing	\$ 17 38.00 x
1	Handle bar	\$ 2 125.00 ✓
1	Handle bar balancer	\$ 2 28.00 ✓
1	Side mirror -R/H	\$ 2 50.00 ✓
1	Brake lever	\$ 2 28.00 ✓
1	Side cowling -R/H	\$ 2 230.00 ✓
1	Headlamp	\$ 17 198.00 x
1	Side board -R/H	\$ 2 58.00 ✓
1	Front footrest -R/H	\$ 2 45.00 ✓
1	Front footrest bracket -R/H	\$ 2 60.00 ✓
1	Brake pedal	\$ 2 42.00 ✓
1	Rear footrest -R/H	\$ 17 45.00 x
1	Exhaust assy	\$ 2 485.00 x
1	Exhaust protector	\$ 2 55.00 ✓
1	Rear signal -R/H	\$ 17 48.00 x
		\$ 2,727.00
Less 10%		\$ 272.70
791		\$ 2,454.30

Special Neft Items

1	Number plate (1 set)	\$ 17 28.00 x
1	Rear box	\$ 47 180.00 ✓
1	Rear box bracket	\$ 2 100.00 ✓
2	Fork oils	\$ 2 30.00 ✓
2	Fork oil seals	\$ 2 56.00 ✓
1	Steering cone (1 set)	\$ 2 90.00 ✓
		\$ 484.00

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Rajurayan Singh S/O Suruj Singh

Accident Date : 2-Sep-17

Vehicle No : FBE 1030 G

Vehicle Model : Honda CL200

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service.	\$ 12 50.00 x
2	To check wiring and reset headlamp focusing.	\$ 11 80.00 x
3	To provide labour.	\$ 220 380.00
		<u>\$ 510.00</u>

Grand Total \$ 3,448.30

Dollars: Three Thousand Four Hundred Forty-Eight And Thirty Cents Only.


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: