



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

**Our Ref: CV1/OCB17023720/R1Cc**

**Date: 19 December 2017**

**M/s Overseas-Chinese Banking  
Corporation Limited**  
Auto Loan Centre  
63 CHULIA ST #07-00  
OCBC CENTRE EAST  
Singapore 049514

**VALUATION REPORT: VEHICLE REGN. NO SDZ 3009Y**

**1. Inspection**

Inspected vehicle SDZ 3009Y on 14/12/2017 at 511 Bukit Batok Street 23, 2<sup>nd</sup> Floor,  
Vicom Inspection Centre.

**2. Vehicle Information**

Vehicle Regn No.	: SDZ 3009Y (LOT 1)
Make & Model	: B.M.W. 740LI A
Engine No.	: 11527549N54B30A
Engine Capacity	: 2979cc
Chassis No.	: WBAKB420X0CY83379
Year of Manufacture	: 2010
Original Regn.Date	: 13/12/2010
No. of Transfer	: 0
PARF Benefit (\$)	: -
Quota Premium	: \$45,501.00
COE Expiry Date	: 12/12/2020
Road Tax Expiry Date	: 12/06/2017
Speedometer Reading	: 161551km

**3. Valuation**

Valuation as at December 2017

Market Value	: S\$ 76,000/-
Forced Sales Value	: S\$ 68,000/-

4. Photographs of vehicle SDZ 3009Y taken during the inspection are attached with this report.

HLC

Ho Leong Chuan  
AUTOMOTIVE ASSESSOR

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.