LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

From: LKK Auto Consultants Pte Ltd

To: AXA Insurance Pte Ltd

8 Shenton Way #24-01 51 Ubi Ave 1 #01-25 AXA Tower Paya Ubi Industrial Park Singapore 068811 Singapore 408933

Attn: Flossie Ang Date: 21 Dec 2017

Preliminary Advice

Insured Vehicle No : FBE6003C

TP Vehicle No : SLL5904D Accident Date : 16/11/2017

Make : MERCEDES-BENZ CLA180 Assignment Date : 13/12/2017

Date of Inspection : 20/12/2017 Est. Duration of Repair : 3 days

Inspection At : Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)

188 Pandan Loop Singapore 128378

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ... rear O/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,382.55
Revised Amount	:S\$	3,961.51
Check Items (Estimated)	:S\$	118.22
Total	:S\$	4,079.73

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() The vehicle is unconformed to be repaired, you are advised to livite tender for the wice

(X) Other comments: We have not authorized repairs.