

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146 email: ben@allswellmotor.com.sg

(3rd party claim against AXA Insured skV4T38H)

Repair Estimate

Vehicle No. : SU 6055Y
 Make & Model : BMW 520I
 Chassis No. : _____
 Date of survey : _____

Submitted by : BEN
 Year Manufacture : 2007
 Engine No. : _____

S/No	Part Description	Qty	Unit Price (SGD)	Price (SGD)	Disposition by Surveyor
01	Panel beating & putty and sand paper (Right Rear Fender)	01	\$220	200	
02	Respray damage part and polish (Right Rear Fender)	01	\$360	200	
			* \$400 / One Day Repair		
			Total = \$560 =		
			Excluding 1 day (loss of use)		

Ben
 3/4/2018

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.