



SMRT AUTOMOTIVE SERVICES PTE LTD
60 Woodlands Industrial Park E4, SINGAPORE

To: _____

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sebastian. 14/11/2017.
- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint
90036121
sebastianyeang@lkkauto.com.

Vehicle No: GBE6947D
Model: NISSAN NV200
Date: 14/12/2017

Quotation

S/No.	Description	Qty	Price
1	REPLACE BOOTLID (LH) LH Rear Door ✓ DT	1	\$ 1,380.00
2	REPLACE BOOTLID HINGE (set) X	1	\$ 220.00
3	REPLACE REAR BUMPER ?	1	\$ 775.00
4	REPLACE REAR BUMPER RETAINER (LH) ?	1	\$ 110.00
5	REPLACE REAR BUMPER REFLECTOR (set) ?	1	\$ 132.00
6	REPLACE REAR BUMPER SPONGE ?	1	\$ 105.00
7	REPLACE REAR END PANEL X	1	\$ 540.00
8	REPLACE REAR TAIL LAMP (LH) ✓ CRK	1	\$ 325.00
9	REPLACE REAR BOOTLID OUTSIDE HANDLE X	1	\$ 280.00
10	REPLACE BOOTLID LOCK X	1	\$ 380.00
11	REPLACE STICKER 70KM AND STICKER WHITE/REH ✓ NEC	1	\$ 25.00
12	REPLACE NUMBER PLATE WITH HOLDER X	1	\$ 50.00
13	REPLACE BOOTLID EMBLE ✓ NEC	1	\$ 85.00
14	REPLACE REVERSE SENSOR (set) ?	1	\$ 320.00
15	REPLACE REAR RECORDING CAMERA (set) X	1	\$ 450.00
16	LABOUR CHARGE TO REMOVE & REFIX NEW ITEM PARTS, REAR WINDSCREEN, CHECKING WATER LEAKING AND CHECKING TAIL LAMP, REVERSE & REAR CAMERA WIRING	NA	\$ 1,500.00 500
17	LABOUR CHARGE TO SPARY PAINTING	NA	\$ 1,000.00 400
Currently no stock, need overseas indent. Estimated 4 to 6 weeks and 07 working days upon quotation approval.		Total Charges:	\$ 7,677.00
		GST	\$ 537.39
		Amount Payable:	\$ 8,214.39

Brijesh

SMRT Automotive Pte Ltd