

ASS. REC. BY:

REF: CS/MSG17023772/T1rd37

Special Instruction:

Surveyor:
Maximen

Taufik

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSIG

Date/Time:

14/12/17 @ 3:17pm

Estimated Cost:

Bill to:

OD / EV / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLA 4644T

Insured:

SLH 5332A

at Workshop m/s:

Mora Automotive

Tel:

62723892

of

No. 22 Jln Kilang #03-01, 159419

Policy No.:

A28851390Avw

Claim No.:

540479

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9/12/2017

CA / REV / REP. / REV 24 HRS

Cup

18/12/17 @

After Lunch (1pm)

H.O.D. Endorsement:

Date/Time:

3:42pm @ 14/12/17

Person Contacted:

Nifha

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLA 4644T - X

SLH 5332A - X

24/1/18

Sent poli thru maximen

Confirm

\$5093.20 @ 6 days (Red: \$1464.24, 221.)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2017		14 Dec 2017 15:17 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GAO SHAN, ID: S7377426H		
Main Claimant:	YEO KER SHIN, ID: S8834801Z		
Vehicle Reg. No.:	SLA4644T	Date of Loss:	09/12/2017 16:00 - :59
Claim Type:	TP / 540479	Policy/Cover Note No.:	A28851390AVW (Comprehensive) Coverage: 09/11/2017 - 08/11/2018
Vehicle Reg. No. (Insured):	SLH5332A	Policy No. (Claimant):	
		Excess:	
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) No. 22 Jalan Kilang, #03-01, Mova Building, 159419 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/12/2017]		
Driver/Custodian (Insured):	LIU YANFANG (), NRIC: S7081629F, Tel: +6583280143		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17023772/T1rd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 14-12-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLH 5332A	Veh. Inspected	SLA 4644T	
Policy No.	A28851390AVW	Coverage (\$)	0.00	
Claim No.	540479	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAN)	Assign Date	14/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/12/2017	Inspection Date		
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Happy Car

www.facebook.com/happycar8

OFFICIAL RECEIPT

No.: HC17-009

Date: 8/7/2017

茲收到
Received from

Yeo Ker Shin (SLA4644T)

支付大銀
the sum of Dollars

Four Hundred and Fifty Only

系还
in payment of

9H Ceramic Coating Package

\$ 450

Cash / Cheque No.:

Yeo Ker Shin
HAPPY CAR

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 24 Jan 2018

Preliminary Advice

Insured Vehicle No	: SLH5332A	Accident Date	: 09/12/2017
TP Vehicle No	: SLA4644T	Assignment Date	: 14/12/2017
Make	: HONDA VEZEL	Est. Duration of Repair	: 6.00
Date of Inspection	: 18/12/2017		
Inspection At	: SIN SENG HONG SPRAY PAINTING & SERVICE (HQ) BLK 3022A UBI ROAD 1 #01-53 SINGAPORE 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,201.28
Revised Amount	:S\$	4,586.24
Check Items (Estimated)	:S\$	576.00
Total	:S\$	5,162.24

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	11/12/2017 09:47
Date Of Accident	08/12/2017 16:30
Exact Location Of Accident	OUTSIDE TO ANCHORPOINT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLA4644T
Insured/Policyholder	
Name Of Registered Owner	YEO KER SHIN
NRIC No	S8834801Z
Email Address	KSYEO1@E.NTU.EDU.SG
Mobile Phone No	(LOCAL) +65-97343377
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL 1.5X A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5077849663-01
Cover Note Number	
Driver	
Name of Driver	YEO KER SHIN
NRIC No	S8834801Z
Date Of Birth	18/09/1988
Occupation	INDOOR
Date Of Driving Pass	15/08/2007
Driving Experience	10 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97343377
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	KSYEO1@E.NTU.EDU.SG

Address
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLH5332A
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver LIU YAN FANG
NRIC/Passport Number S7081629F
Contact Number 83280143
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF INJURED PERSON 1

Name YEO KER SHIN
Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by: Reporting Centre Personnel

Sketch Plan



Sketch Plan Pg. 2

[illegible]

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre
Personnel

I, Liu Yan Fang, caused the accident. ~~as~~ I'm
willing to take the responsibility for the damage
of the car. My contact no. +65 83280143

Liu Yan Fang

Liu yanfang
S7081629F

Estimate

12/12/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Attention :- XA013

Page # :- 1

Veh # :- SLA4644T

Veh Model :- HONDA VEZEL

Estimate# :- CK416782

Claim # :-

ACC. Date :- 08/12/17

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT FENDER WHEEL AVC PROTECTOR LH	1 PC	185.00 <i>cut</i>	185.00 ✓
2.	FRONT DOOR LH	1 PC	1,195.60 <i>bt</i>	1,195.60 ✓
3.	FRONT DOOR CHECKER LH	1 PC	75.00 <i>nn x</i>	75.00 ✓
4.	FRONT DOOR WINDOW REGULATOR LH	1 PC	495.00 <i>bt</i>	495.00 ✓
5.	REAR DOOR LH	1 PC	1,025.60 <i>bt</i>	1,025.60 ✓
6.	REAR DOOR STONE GUARD STICKER LH	1 PC	38.70 <i>cut</i>	38.70 ✓
7.	REAR DOOR CENTRE RUBBER LH	1 PC	68.50 <i>cut</i>	68.50 ✓
8.	REAR FENDER PROTECTOR LH	1 PC	145.00 <i>cut</i>	145.00 ✓
9.	SIDE SKIRT LH	1 PC	395.00 <i>cut</i>	395.00 ✓
10.	SIDE SKIRT CLIPS	11 PC	3.90 <i>re</i>	42.90 ✓
11.	REAR WHEEL RIM LH	580 1 PC	400 886.50 <i>cut</i>	886.50 ✓
12.	REAR WHEEL HUB LH	1 PC	375.10 <i>nn x</i>	375.10 ✓
13.	RERA SHOCK ABSORBER LH	1 PC	386.20 <i>nn x</i>	386.20 ✓
14.	FRONT FENDER LH - REPAIR	1 PC		
15.	ROCKER PANEL LH - REPAIR	1 PC		
LIST TOTAL S\$				5,314.10
20% DISCOUNT S\$				-1,062.82
				4,251.28
LABOUR :				
TO REPAIR FRONT FENDER LH & ROCKER PANEL LH. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS & REALIGN ALL AFFECTED AREAS				400 500.00
TO SPRAY PAINT FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, & ROCKER PANEL LH				750. 950.00
TO REMOVE & REFIX DOOR MECHANISM, CHECK & TEST POWER WINDOW & CENTRE LOCKING SYSTEM				120. 160.00
TO RUST PROOF AFFECTED AREAS				50 80.00
TO REMOVE AND REFIX REAR UNDERCARRIAGE SUSPENSION LH				150. 180.00 X ^m
TO CONDUCT WHEEL ALIGNMENT				✓ 80.00
LABOUR TOTAL S\$				1,950.00

Estimate

12/12/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Attention :- **XA013**

Page # :- 1 130215

Veh # :- SLA4644T

Veh Model :- HONDA VEZEL

Estimate# :- CK416782

Claim # :-

ACC. Date :- 08/12/17

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalin Kilang,
Singapore 159419
Tel : **(65) 6476 3333**
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : **(65) 6272 3892**
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S 6557.44

AMOUNT S\$ 6,201.28

GST @ 7 % 434.09

AMOUNT DUE S\$ 6,635.37

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanjilkh 97495749
WP
12/12/17 @ 1700
Resurvey before paint
Sur @ (Kkauto.com
5-6 days.

Main Office:
Move Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5691
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904039G
GST Reg. M2-0088664-2

SUPPLEMENTARY

MSIG INSURANCE (S) PTE LTD
16, RAFFLES QUAY
#21-01 HONG LEONG BUILDING
SINGAPORE 048581

Page : 1
Veh No : SLA4644T
Model : HONDA VEZEL
Claim No : CK416782
Acc Date : 8-Dec-17
Incharge : JIAYU

No	Description	Qty	U.Price	Amt \$
LIST ITEMS:				
1	FRONT DOOR BLACK STICKER LH	1	\$ 42.60	\$42.60 <i>rel</i>
2	REAR DOOR BLACK STICKER LH	1	\$ 42.60	\$42.60 <i>rel</i>
	LIST TOTAL S\$			\$85.20
	20% DISCOUNT			\$17.04
				<u>\$68.16</u>
SPECIAL NET ITEMS:				
1	CERAMIC COATING FOR FENDERS & DOOR LH SIDE			\$288.00 <i>rel</i>
	SPECIAL NET TOTAL S\$			<u>\$288.00</u>

NON-TAX AMOUNTS	\$356.16
GST @ 7%	\$24.93
AMOUNT DUE	<u>\$381.09</u>

Customer's Signature/Co. Stamp

MOVA AUTOMOTIVE PTE LTD

Janice Lee (LKKAUTO)

From: Jia Yu <jiaYu@movas.com.sg>
Sent: Thursday, May 10, 2018 11:34 AM
To: Taufikh (LKKAUTO)
Cc: SUR; CS A Team; Admin A
Subject: FW: SLA4644T FINALIZATION
Attachments: DSCF5206.jpg; DSCF5207.jpg; DSCF5208.jpg; DSCF5209.jpg; DSCF5210.jpg; DSCF5211.jpg; DSCF5212.jpg; DSCF5213.jpg; DSCF5214.jpg; IMG_8121.JPG; IMG_8122.JPG; IMG_8123.JPG; IMG_8124.JPG; IMG_8126.JPG; IMG_8127.JPG; IMG_8128.JPG; IMG_8131.JPG; IMG_8132.JPG; HAPPY CAR COATING (AFTER REPAIR).pdf; SLA4644T COATING INVOICE (HAPPY CAR).pdf; SLA4644T FINALISE.pdf

Importance: High

From: Jia Yu [mailto:jiaYu@movas.com.sg]
Sent: Tuesday, 17 April 2018 2:51 PM
To: 'Taufikh (LKK Auto)'
Cc: 'cs-a@lkkauto.com'; 'admin-a@lkkauto.com'; 'sur@lkkauto.com'
Subject: FW: SLA4644T FINALIZATION

Hi All,

Need your help to finalise this case as soon as possible.
Thank You.

Best Regards,
Jia Yu
MOVA Automotive Pte Ltd

From: Jia Yu [mailto:jiaYu@movas.com.sg]
Sent: Saturday, 24 February 2018 10:01 AM
To: 'Taufikh (LKK Auto)'
Cc: 'sur@lkkauto.com'; 'cs-a@lkkauto.com'; 'admin-a@lkkauto.com'
Subject: SLA4644T FINALIZATION

Hi Taufikh,

Above attached with before paint, check items and after repair photos for SLA4644T.
Attached with the invoice provided by owner for the coating of the spray paint areas after repair.
Please advice whether we can finalise the cost of repair at \$5338.40 with 6 repair days ?
Thank You.

Best Regards,
Jia Yu
MOVA Automotive Pte Ltd

Main Office:
Mova Building
No. 22, Jalan Klang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/04
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

12/12/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Attention :- XA013

Page # :- 1.

Veh # :- SLA4644T

Veh Model :- HONDA VEZEL

Estimate# :- CK416782

Claim # :-

ACC. Date :- 08/12/17

Terms :- C.O.D Days

Remarks :-

CK130215

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT FENDER WHEEL AVC PROTECTOR LH	1 PC	185.00	185.00
2.	FRONT DOOR LH	1 PC	1,195.60	1,195.60
3.	FRONT DOOR CHECKER LH	1 PC	75.00	75.00
4.	FRONT DOOR WINDOW REGULATOR LH	1 PC	495.00	495.00
5.	REAR DOOR LH	1 PC	1,025.80	1,025.80
6.	REAR DOOR STONE GUARD STICKER LH	1 PC	38.70	38.70
7.	REAR DOOR CENTRE RUBBER LH	1 PC	88.50	88.50
8.	REAR FENDER PROTECTOR LH	1 PC	145.00	145.00
9.	SIDE SKIRT LH	1 PC	395.00	395.00
10.	SIDE SKIRT CLIPS	11 PC	3.90	42.90
11.	REAR WHEEL RIM LH	1 PC	886.50	886.50
12.	REAR WHEEL HUB LH	1 PC	375.10	375.10
13.	REAR SHOCK ABSORBER LH	1 PC	386.20	386.20
14.	FRONT FENDER LH - REPAIR	1 PC		
15.	ROCKER PANEL LH - REPAIR	1 PC		
LIST TOTAL S\$				5,314.10
20% DISCOUNT S\$				-1,062.82
				4,251.28

LABOUR :

TO REPAIR FRONT FENDER LH & ROCKER PANEL LH.
TO REMOVE & REPLACE ALL ACCIDENT DAMAGED
PARTS & REALIGN ALL AFFECTED AREAS

TO SPRAY PAINT FRONT FENDER LH, FRONT DOOR
LH, REAR DOOR LH, & ROCKER PANEL LH

TO REMOVE & REFIX DOOR MECHANISM, CHECK &
TEST POWER WINDOW & CENTRE LOCKING SYSTEM

TO RUST PROOF AFFECTED AREAS

TO REMOVE AND REFIX REAR UNDERCARRIAGE
SUSPENSION LH

TO CONDUCT WHEEL ALIGNMENT

LABOUR TOTAL S\$

400 500.00
750.
950.00
120.
160.00
50
80.00
150.
180.00
80.00
1,950.00

Attn: Ah Khen

Estimate

12/12/2017

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Attention :- XA013

Page # :- 1 130215
Veh # :- SLA4644T
Veh Model :- HONDA VEZEL
Estimate# :- CK416782
Claim # :-
ACC. Date :- 08/12/17
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/24
Singapore 159722

Tel : (65) 6272 3892
Fax : (65) 8270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

6,201.28

GST @ 7 %

434.09

Signature

AMOUNT DUE S\$

6,635.37

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

PARTS (LIST):

\$4563.00 - 20%

= \$3650.40

Special Net : \$288.00

LABOUR: \$1400.00

Total: \$5338.40 *

6 days.

Tan Jiah 97495749

WP

12/12/17 @ 1700

Resuming before paint

Sur @ (Kuantan.com

5-6 days.

Happy Car

UEN: 53358123X

www.facebook.com/happycarB

OFFICIAL RECEIPT

No.: HC18-005

Date: 3/2/2018

茲收到 Received from Yeo Ker Shin (White Vezel - SLA4644T)

支付大銀 the sum of Dollars Two Hundred and Eighty Eight Only —

系还 In payment of 9H Ceramic Ginty (Left Side Only)

\$ 288

Cash / Cheque No:

Yeff HAPPY
CAR

Happy Car

www.facebook.com/happycar8

OFFICIAL RECEIPT

No.: HC17-009

Date: 8/7/2017

Besform

茲收到
Received from Yeo Ker Shin (SLA4644T)

支付大銀
the sum of Dollars Four Hundred and Fifty Only

系在
in payment of 9H Ceramic Coating Package

\$ 450

☒ Cash ☐ Cheque No.:

Yeo Ker
HAPPY
CAR



日美汽車私人有限公司 JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450618 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2550

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct 6417 9191 / 6745 9429



Dept Direct 6365 9610

Dept Direct 6365 9611

Dept Direct 6417 9192



Dept Direct 6417 9194

Dept Direct 6417 9195

Dept Direct 6417 9196

Dept Direct 6417 9197

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

MOVA AUTOMOTIVE PTE LTD
15 FAN YOONG RD

SINGAPORE
TEL: 62623377 FAX: 62643151
ATTN: JIAYU

TAX INVOICE : AR201712-10410
DATE : 19/12/2017
CUSTOMER ID : MOV001
VEH REG. NO. : SLA4644T
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 2
CURR : SGD

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1. H74157-T7M-H01 RU1	WHEEL ARCH FR LH	PA PL1-L1-11S	1		
2. H67050-T7Y-T10ZZ HRV-RU1	FR DOOR LH	PA PL1-F1-12A	1		
3. H75895-T7A-003	TAPE, RR LH	PA PL1-C1-08Z	1		
4. H71850-T7A-003 RU1	SILL SKIRT LH	PA PL1-M1-020	1		
5. H91505-TM8-003 GM2	CLIPS BUMPER (H91505-TM8-000)	PA PL1-M1-09N	11		
6. H74450-T7M-H01 RU1	WHEEL ARCH RR LH	PA PL1-B1-08A	1		
7. H42700-T8C-T91 RU1	SPORT RIM BNKEI 16X7J	PA PL1-C1-09B	1		350.00

1140
19/12/2017

CONTINUE NEXT PAGE

[P] 19/12/2017 9:18:10AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[B] 19/12/2017 9:10:09AM

Janice Lee (LKKAUTO)

From: Jia Yu <jiaYu@mova.com.sg>
Sent: Monday, July 23, 2018 1:33 PM
To: Janice Lee (LKKAUTO)
Cc: SUR; Taufikh (LKKAUTO)
Subject: RE: SLA4644T FINALIZATION *LKK REF: CS/MSG17023772/T1rd3

Hi Janice,

Okay. Amount and days confirmed.
Thank you.

Best Regards,

Jiayu

Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Janice Lee (LKKAUTO) [mailto:JaniceLee@lkkauto.com]
Sent: Monday, 23 July 2018 11:27 AM
To: SUR; Taufikh (LKKAUTO); 'Jia Yu'
Subject: RE: SLA4644T FINALIZATION *LKK REF: CS/MSG17023772/T1rd3

Hi Jia Yu,

Kindly confirm \$5093.20 @ 6 days

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAUTO)
Sent: Friday, July 20, 2018 5:05 PM
To: SUR <sur@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; 'Jia Yu' <jiaYu@mova.com.sg>
Subject: RE: SLA4644T FINALIZATION *LKK REF: CS/MSG17023772/T1rd3

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2017		14 Dec 2017 15:17 Edit Adj Rpt	S\$5,093.20 Edit Estimates	S\$5,093.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	GAO SHAN , ID: S7377426H								
Main Claimant:	YEO KER SHIN , ID: S8834801Z								
Vehicle Reg. No.:	SLA4644T	Date of Loss:	09/12/2017 16:00 - :59 [21 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 540479	Policy/Cover Note No.:	A28851390AVW (Comprehensive) Coverage: 09/11/2017 - 08/11/2018						
Vehicle Reg. No. (Insured):	SLH5332A	Policy No. (Claimant):							
		Excess:							
Repairer:	Sin Seng Hong Spray Painting & Service (HQ) BLK 3022A UBI ROAD 1 #01-53, 408716 Ubi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 13/01/2018]								
Driver/Custodian (Insured):	LIU YANFANG (), NRIC: S7081629F, Tel: +6583280143								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLA4644T (540479)

[SLH5332A]

TP

YEO KER SHIN

Dec 9 2017 4:00PM

[GAO SHAN]

Sin Seng Hong Spray Painting & Service

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
1	13/12/17 09:58	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement From: SC - Reg. No: SLH5332A, Claimant: GAO SHAN	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/01/18 12:58	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder		Thumbnail	Print
1	20/07/18 17:15	LKK Auto Consultants Pte Ltd (HQ) General View	 Load JPG	☒
2	20/07/18 17:15	General View	 Load JPG	☒
3	20/07/18 17:15	General View	 Load JPG	☒
4	20/07/18 17:15	General View	 Load JPG	☒
5	20/07/18 17:15	General View	 Load JPG	☒
6	20/07/18 17:15	General View	 Load JPG	☒
7	20/07/18 17:15	General View	 Load JPG	☒
8	20/07/18 17:15	General View	 Load JPG	☒
9	20/07/18 17:15	General View	 Load JPG	☒
10	20/07/18 17:15	General View	 Load JPG	☒
11	20/07/18 17:15	General View	 Load JPG	☒
12	20/07/18 17:15	General View	 Load JPG	☒
13	20/07/18 17:15	General View	 Load JPG	☒
14	20/07/18 17:15	General View	 Load JPG	☒
15	20/07/18 17:15	General View	 Load JPG	☒
16	20/07/18 17:15	General View	 Load JPG	☒
17	20/07/18 17:15	General View	 Load JPG	☒
18	20/07/18 17:15	General View	 Load JPG	☒
19	20/07/18 17:15	General View	 Load JPG	☒
20	20/07/18 17:15	General View	 Load JPG	☒
21	20/07/18 17:15	General View	 Load JPG	☒
22	20/07/18 17:15	General View	 Load JPG	☒
23	20/07/18 17:15	General View	 Load JPG	☒
24	20/07/18 17:15	General View	 Load JPG	☒
25	20/07/18 17:15	General View	 Load JPG	☒
26	20/07/18 17:15	General View	 Load JPG	☒
27	20/07/18 17:15	General View	 Load JPG	☒
28	20/07/18 17:15	General View	 Load JPG	☒
29	20/07/18 17:15	General View	 Load JPG	☒
30	20/07/18 17:16	Reinspection Photo	 Load JPG	☒
31	20/07/18 17:16	Reinspection Photo	 Load JPG	☒
32	20/07/18 17:16	Reinspection Photo	 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	20/07/18 17:16	Reinspection Photo	Load JPG	☒
34	20/07/18 17:16	Reinspection Photo	Load JPG	☒
35	20/07/18 17:16	Reinspection Photo	Load JPG	☒
36	20/07/18 17:16	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/12/17 09:59	TP GIA Rep -SLA4644T From: SC - Reg. No: SLH5332A, Claimant: GAO SHAN	Load PDF	
2	18/12/17 09:41	EMAIL to TP reject their list of SJE	Load PDF	
3	18/12/17 09:42	PRI	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/07/18 09:33	SUPPLEMENTARY PART	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023772/RD3Q2

Date: 26/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28851390AVW
 Claimant Vehicle No: SLA4644T Insured Vehicle No: SLH5332A
 Date of Loss: 09/12/2017 Nature of Claim: TP Claim No: 540479

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA4644T**
 Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4025017
 Reg. Date: 01/03/2016 (Man. Year: 2015) Chassis No: RU11105020
 Colour: White Odometer: 45228 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,607.44	3,693.20	914.24	19.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	1,400.00	550.00	28.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,557.44	5,093.20	1,464.24	22.33
+ GST 7.00/7.00% (S\$)	459.02	356.52	102.50	22.33
Nett Amount (S\$)	7,016.46	5,449.72	1,566.74	22.33

INSPECTION

Date of Assignment: 14/12/2017
 Date Inspected: 18/12/2017 Inspected At: NO.22 JLN KILANG #03-01,
 SINGAPORE 159419
 Repairer: MOVA AUTOMOTIVE PTE LTD
 Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2018)
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA4644T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT FENDER WHEEL AVC PROTECTOR LH	Cut	185.00 FL	*185.00 FL
2	1	*FRONT DOOR LH	Bent	1,195.60 FL	*1,195.60 FL
3	1	*FRONT DOOR CHECKER LH	Not Necessary	75.00 FL	*- FL
4	1	*FRONT DOOR WINDOW REGULATOR LH	Bent	495.00 FL	*495.00 FL
5	1	*REAR DOOR LH	Bent	1,025.60 FL	*1,025.60 FL
6	1	*REAR DOOR STONE GUARD STICKER LH	Cut	38.70 FL	*38.70 FL
7	1	*REAR DOOR CENTRE RUBBER LH	Cut	68.50 FL	*68.50 FL
8	1	*REAR FENDER PROTECTOR LH	Cut	145.00 FL	*145.00 FL
9	1	*SIDE SKIRT LH	Cut	395.00 FL	*395.00 FL
10	11	*SIDE SKIRT CLIPS	Necessary	42.90 FL	*42.90 FL
11	1	*REAR WHEEL RIM LH	Cut	886.50 FL	*580.00 FL
12	1	*REAR WHEEL HUB LH	Not Necessary	375.10 FL	*- FL
13	1	*REAR SHOCK ABSORBER LH	Not Necessary	386.20 FL	*- FL
14	1	*FRONT FENDER LH (NPA)	Repair	0.00 FL	*- FL
15	1	*ROCKER FENDER LH (NPA)	Repair	0.00 FL	*- FL
16	1	*FRONT DOOR BLACK STICKER LH	Necessary	42.60 FL	*42.60 FL
17	1	*REAR DOOR BLACK STICKER LH	Necessary	42.60 FL	*42.60 FL
18	1	*CERAMIC COATING FOR FENDERS & DOOR LH SIDE	Necessary	288.00 FS	*288.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,687.30	4,544.50
- List Item Discount on L Items 20.00/20.00% (S\$)	1,079.86	851.30
Total Parts (S\$)	4,607.44	3,693.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR FRONT FENDER LH & ROCKER PANEL LH,TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS & REALIGN ALL AFFECTED AREAS	New	500.00	400.00
2	TO SPRAY PAINT FRONT FENDER ,LH FRONT DOOR LH ,REAR DOOR LH,ROCKER PANEL LH	New	950.00	750.00
3	TO REMOVE & REFIX DOOR MECHANISM ,CHECK & TEST POWER WINDOW & CENTRE LOCKING SYSTEM	New	160.00	120.00
4	TO RUST PROOF AFFECTED AREAS	New	80.00	50.00
5	TO REMOVE AND REFIX REAR UNDERCARRIAGE SUSPENSION LH	New	180.00	0.00
6	TO CONDUCT WHEEL ALIGNMENT	New	80.00	80.00
Gross Labour Cost (\$\$)			1,950.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >