



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



Thatcham escribe

Reg. No: 52983356E GST Reg. No. 20-0405911-H

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17023786/K1vbn2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 28-12-2017
Code: INC4	



### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBA 5869Z	<b>Veh. Inspected</b>	SHD 4138U
<b>Policy No.</b>	5084994253-01	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/0973733-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	14/12/2017

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HYUNDAI SONATA	<b>c.c</b>	1991
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2012
<b>Chassis No.</b>	KMHET41VMCA824479	<b>Colour</b>	BLUE
<b>Odometer</b>	152646	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/60 R16	WEST LAKE	7 mm
<b>L/H Front Tyre</b>	215/60 R16	WEST LAKE	7 mm
<b>R/H Rear Tyre</b>	215/60 R16	WEST LAKE	7 mm
<b>L/H Rear Tyre</b>	215/60 R16	WEST LAKE	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	13/12/2017	<b>Inspection Date</b>	14/12/2017
<b>Survey held at</b>	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**