

Mei Kwan (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Friday, 26 January, 2018 2:10 PM
To: 'Janet Tan'
Cc: Zaini (LKK Auto); Hsiao Tong (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving GBG7100M (OI : EQI - DM17HO02820/JT) AND SJS8001B (TP : LKK REF - CC6/EQI17023826/Aka3) on 10/12/2017
Attachments: TP ESTIMATE - MARKED.pdf; Preliminary Advice.pdf; LKK RESURVEY PHOTO-1.pdf; LKK RESURVEY PHOTO-2.pdf; LKK SURVEY PHOTO.pdf
Categories: HMK

WITHOUT PREJUDICE

Your ref: DM17HO02820/JT
LKK ref: CC6/EQI17023826/Aka3

Dear Janet,

We refer to your below email and the contents were duly noted.

Enclosed revert of vehicle: SJS 8001B

Date of survey: 14.12.2017

Enclosed for your perusal is:

- TP estimate (marked)
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

We have not authorized repairs.

Kindly take note that the case handler in-charge is Zaini and he can be contacted at DID: 6841 2132.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]
Sent: Thursday, 25 January, 2018 3:43 PM
To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Cc: Zaini (LKK Auto) <Zaini@lkkauto.com>
Subject: FW: Direct Settlement - Accident Involving GBG7100M (OI : EQI - DM17HO02820/JT) AND SJS8001B (TP : LKK REF - CC6/EQI17023826/Aka3) on 10/12/2017

Dear Mei Kwan/Zaini

OI report as attached. In the absence of evidence and or final police investigation result, liability down on third party.

Regards,

Janet Tan

Senior Executive | Claims




EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]

Sent: Thursday, January 25, 2018 1:23 PM

To: Janet Tan <janet.tan@eqinsurance.com.sg>

Cc: Zaini (LKK Auto) <Zaini@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBG7100M (OI : EQI - TBA) AND SJS8001B (TP : LKK REF - CC6/EQI17023826/Aka3) on 10/12/2017

Dear Janet,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Friday, 19 January, 2018 1:49 PM

To: Janet Tan <janet.tan@eqinsurance.com.sg>

Cc: Zaini (LKK Auto) <Zaini@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBG7100M (OI : EQI - TBA) AND SJS8001B (TP : LKK REF - CC6/EQI17023826/Aka3) on 10/12/2017

Dear Janet,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Friday, 15 December, 2017 2:15 PM

To: Janet Tan <janet.tan@eqinsurance.com.sg>

Cc: Zaini (LKK Auto) <Zaini@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving GBG7100M (OI : EQI - TBA) AND SJS8001B (TP : LKK REF - CC6/EQI17023826/Aka3) on 10/12/2017

WITHOUT PREJUDICE

Your ref: TBA

LKK ref: CC6/EQI17023826/Aka3

Dear Janet,

We refer to the above matter.

This is a TP direct settlement case.

We have inspected TP vehicle SJS 8001B at M/s Flying High Spray Painting - Kaki Bukit.

Please be informed that the estimated cost of repair is not ready yet.

We will revert to you on preliminary advice in due course.

Enclosed for your perusal is:

- TP GIA report

Kindly take note that the case handler in-charge is Zaini and he can be contacted at DID: 6841 2132.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)