

TP EQ
Zaini

SJS8001B

Honda CRV

JHLRE28309C200298

Rear Bumper	Rehd	578.30	✓
Rear RH Bumper	Rehd	197	✓
Rear Bumper clips.	m	30	✓
Rear Bumper Side Holder.	m	25.70	✓
Rear RH Mudflap.	Rehd	118.60	✓
Rear RH Fender	Dented	92.6	✓
Rear RH Fender Arc Garish	Rehd	210.10.	✓
Rear RH Fender Arc Garish Clips.	m	25.	✓
Rear RH Wheel Rim	lt	800(SN) 550(SN)	
Rear RH Tyre.	lt	280(SN) 200(SN)	
Rear RH Lower Arm	Bent	854.60.	✓
Rear RH Knuckle Arm		410.60.	✓
Rear RH Shock Absorber		198.80	✓
Rear RH Wheel Hub & Bearing	Rehd	224.80.	✓
Rear RH Stay Arm	Bent	94.10.	✓
Rear Cross Member.	Bent	1050.	✓
Rear ^{RH} Fender Glass Moulding.	N/A	56.70	✓
Rear RH Fender Glass Sealant.		30(SN)	✓

SJS8001B.

Rees RH Fender Inner Trim

Rees RH Fender Inner Trim Clips

Taillamp. RH

338.30 +

50 +

437.70 x

4300.3

3600.24

S.N. 780

SSS 8001B.

Panel Beating	1000	600
Spray Painting.	600	300
Wiring	50	30
To undersend	150	40
To remove reverse sensor	100	50
To remove rear fender glass	100	50
To remove upholstery.	150	40
To remove rear undercarriage	400	320
To perform wheel alignment.	150	80
Towing Fees.	60.	✓
	1570	

total: 5950.24
w/s: 4750.
08 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: