

15/5/2010

INS. CASE OWNER:

CC 3 / QBE1702 3826, F2W3n2

LKK:

IDAC:

Surveyor: kalunDOI: 14/11/18Date / Time: 14/11/18Registered in Merimen: -

Pre-assign / CCU / FTE

Insured Vehicle No.: 4BB 82780Name of Insured: GRUNDPOS (S) P/L

Insured Tel No.: \_\_\_\_\_ HP: \_\_\_\_\_

Excess Sec II :S\$ \_\_\_\_\_ D.O.A.: 14/11/18

Is driver the owner? (YES / NO) Nature of Accident: \_\_\_\_\_

If NO, Driver Name / Age: RAVASUBRAMANIAN KARTHIK

Driver Tel No.: \_\_\_\_\_ (V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

VC0109938-V0009275 - MVA - R0003MITSUBISHIXILIN AVE CROSS CHAMUSOUTH AVE 1

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHD 11895INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:PremierINSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

14/3/18  
VIC

SHD 11895 - 4 4BB 82780 - 6

FINALISED.

TP LOW IN BTH CHAMU.

RECEIVED 13 SEP 2018

CALL OLD. NO RESPONSE. CALL OLD CO.

AUTOMATED. FILE REVIEWED. OLD REPAIR ENDED

TP. SEND LETTER TO OI TO NOTIFY

TP CLAIM.

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to Of: 04/04/18 - VIC

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)	<input type="checkbox"/>	<input type="checkbox"/>
After call ltr to OI:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Release Voucher:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Car Rental Invoice:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Towing Invoice	<input type="checkbox"/>	<input type="checkbox"/>
LTA / GIA:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Medical Bill:	<input type="checkbox"/>	<input type="checkbox"/>
PIR:	<input type="checkbox"/>	<input type="checkbox"/>
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
LOD	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Payment Breakdown Form:	<input type="checkbox"/>	<input type="checkbox"/>
Post-Repair Photos:	<input type="checkbox"/>	<input type="checkbox"/>
Others:	<input type="checkbox"/>	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 15/11/18 Sent By: PM

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: P/P SS 820.00 (2 days) Reduction: 77 % Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Confirm by:

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 Email ☐ Call ☐Repair Cost: (w/GET) SS 663.40Loss of Rental (LOR): SS 164.91 (1.5 days) x 109.94Loss of Use (LOU): SS 60.00 (\$ 40 x 1.5 days)Loss of Income (LOI): SS - (\$ x days)LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]GIA/LTA Search SS 2.00Medical: SS -Disbursement: SS - (e.g. Tow/ Independent)Legal Cost SS -Total: SS 890.31 Global Sum S\$: 890.00FINAL PAYMENT Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email ☐ Call ☐Payee 1: SS 890.00 Name 1: PREMIER AUTOMOTIVE SERVICES PTE LTDPayee 2: (Strike if N.A.) SS - Name 2: -Payee 3: (Strike if N.A.) SS - Name 3: -COPY SENT  
14/11/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format: 400.00

3) Survey fee: 400.00

25

## ASSIGNMENT

From \_\_\_\_\_ Date \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop mis \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured \_\_\_\_\_ Excess \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition.)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Sal. or Market Value:	_____	
IDAC Accident Rpt.:	_____	Consistent? : Yes or No
GIA / FR Seen:	_____	Consistent? : Yes or No
Est. Repairs:	_____ days	Res.: Yes or No
Lum Sum:	_____ %	3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Van No: SAD 1189 D V-Reg: Feb 2017  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / T/Tru Prime Mover: 0  
 Truck / Trailer or:  
 Make: Hyundai Z30 cc: 1582  
 Colour: silver A/C: 0 Ins: 0 Std: NI / NA:  
 Sp. Reading: 104481 T. Radio: Ins: 0 Std: NI / NA:  
 Eng. No:  
 O/No: TMAP2814VHJH 125083  
 Gen. Condi: Good / 0 / Poor / Burnt  
 Steering: In: 0 / Jammed / Leaked / Burnt or:  
 Brake: In: 0 / Jammed / Leaked / Burnt or:  
 Modi: Nil / S/Rim / STD 0 / Sim or:  
 Tyre Size: F: 195/65R15  
 R: ✓  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or: Maxxis  

Front		Rear	
R.Bal.	<u>7</u> mm	R.Bal.	<u>7</u> mm
L.Bal.	<u>7</u> mm	L.Bal.	<u>7</u> mm
D.O.A.	<u>14/12/17</u>	D.O.A.	<u>14/12/17</u>

 Survey held at: Premier  
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or:  
Rear  
 The U/C / Chassis frame / Body Structure affected due to collision:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/12/17	Cancel P/P \$620 / 2 P/L (REV: \$ 2,178.35 / 73%)

QBE

DataTime File Path(s)

☐ : Prelim. Report  
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

**Transmittance**

Date/Time: File Return: 27

Add Fee:

	$\frac{1}{2}$	$\frac{1}{3}$	$\frac{1}{4}$	$\frac{1}{5}$
	$\frac{1}{3}$	$\frac{1}{4}$	$\frac{1}{5}$	$\frac{1}{6}$
	$\frac{1}{4}$	$\frac{1}{5}$	$\frac{1}{6}$	$\frac{1}{7}$
	$\frac{1}{5}$	$\frac{1}{6}$	$\frac{1}{7}$	$\frac{1}{8}$

Report Format :

Lump Sum / I.B.I.: \$




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/QBE17023836/K1hb3	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 15-12-2017	
		Code : QBE	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBB 8278D	Veh. Inspected	SHD 1189S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	15/12/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	14/12/2017	Inspection Date	16/12/2017
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBLAVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC3/QBE17023836/K1hb3

Date: 15.12.2017

The Motor Claims Department  
M/s QBE INSURANCE (INTERNATIONAL) LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**


**SHD1189S**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14.12.2017 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	2,798.35
Revised Estimate Amount	: S\$	620.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:  
The vehicle sustained damages at the  
Rear Portion



Comments/Present Status:  
Damages Consistent  
Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG  
Licensed Appraiser

## Shu Pei (LKKAuto)


---

**From:** Jenny Toh <jenny.toh@qbe.com>  
**Sent:** Tuesday, 13 March 2018 3:05 PM  
**To:** Shu Pei (LKKAuto); Syaheeda Nacah Binte Mohamed Othman  
**Subject:** RE: Direct Settlement - Accident Involving GBB8278D (OI : QBE - TBA) AND SHD1189S (TP : LKK REF - CC3/QBE17023836/K1hb3) on 14.12.2017  
**Attachments:** GBB8279D.pdf

Dear Shu Pei

The vehicle should read as GBB8278D not GBB8279D, informed workshop to do the amendment.

Jenny Toh  
Senior Assistant, Claims  
QBE Emerging Markets - Singapore  
  
QBE Insurance (Singapore) Pte Ltd  
Phone: +65 6477 1225  
Email [jenny.toh@qbe.com](mailto:jenny.toh@qbe.com)  
Visit us on the web at [www.qbe.com.sg](http://www.qbe.com.sg)



**From:** Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]  
**Sent:** Monday, 12 March, 2018 11:48 AM  
**To:** Jenny Toh <jenny.toh@qbe.com>; Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>  
**Subject:** RE: Direct Settlement - Accident Involving GBB8278D (OI : QBE - TBA) AND SHD1189S (TP : LKK REF - CC3/QBE17023836/K1hb3) on 14.12.2017

### WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Shu Pei (LKKAuto)

**Sent:** Wednesday, 17 January 2018 6:12 PM

**To:** Jenny Toh <[jenny.toh@qbe.com](mailto:jenny.toh@qbe.com)>

**Cc:** Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>; Syaheeda Nacah Binte Mohamed Othman <[syaheeda.othman@qbe.com](mailto:syaheeda.othman@qbe.com)>

**Subject:** RE: Direct Settlement - Accident Involving GBB8278D (OI : QBE - TBA) AND SHD1189S (TP : LKK REF - CC3/QBE17023836/K1hb3) on 14.12.2017

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Syaheeda Nacah Binte Mohamed Othman [<mailto:syaheeda.othman@qbe.com>]

**Sent:** Tuesday, 19 December 2017 9:29 AM

**To:** Jenny Toh <[jenny.toh@qbe.com](mailto:jenny.toh@qbe.com)>

**Cc:** Shu Pei (LKKAuto) <[shupeil@lkkauto.com](mailto:shupeil@lkkauto.com)>; Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>

**Subject:** FW: Direct Settlement - Accident Involving GBB8278D (OI : QBE - TBA) AND SHD1189S (TP : LKK REF - CC3/QBE17023836/K1hb3) on 14.12.2017

Hi Jenny,

Please assist.

Thanks,

Syaheeda Othman

Senior Executive, Claims

QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd

DID: +6477 1130 Fax: +6533 3270

Email: [syaheeda.othman@qbe.com](mailto:syaheeda.othman@qbe.com)

Visit us on the web at [www.qbe.com.sg](http://www.qbe.com.sg)

**From:** Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

**Sent:** Friday, 15 December, 2017 5:48 PM

To: Jenny Toh <jenny.toh@qbe.com>; Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>  
Cc: Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAUTO)  
<AsherSng@lkkauto.com>

Subject: Direct Settlement - Accident Involving GBB8278D (OI : QBE - TBA) AND SHD1189S (TP : LKK REF - CC3/QBE17023836/K1hb3) on 14.12.2017

## WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHD 1189S at M/s Premier Automotive Services Pte Ltd - Changi.

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary Advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----  
IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

-----  
IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.



Text size + -

**Enquire Vehicle Registration Details****Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H  
Owner ID Type: Company  
Owner Name: PREMIER TAXIS PTE. LTD.  
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443  
Mailing Address: -  
Birth Date: -

**Vehicle Particulars**

Vehicle No.: SHD1189S  
Previous Vehicle No.: -  
Effective Date of Ownership: 28 Feb 2017  
Original Regn Date: 28 Feb 2017  
Registration Date: 28 Feb 2017  
Year of Manufacture: 2016  
Vehicle Type: Public Transport Taxi (Motor Car)  
Vehicle Scheme: Taxi (Company)  
Vehicle Attachment 1: Air-Con (Taxi)  
Vehicle Attachment 2: -  
Vehicle Attachment 3: -  
Vehicle Make: HYUNDAI  
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT  
Primary Colour: Silver  
Secondary Colour: -  
Passenger Capacity: 4  
Chassis No.: TMAD281UVHJ125043  
Engine No.: D4FBGZ115762  
Engine Capacity/Power Rating: 1582 cc / -  
Maximum Power Output: 100.0 kW (134 bhp)  
Propellant: Diesel  
Max Unladen Weight: 1496 kg  
Maximum Laden Weight: 1940 kg  
Open Market Value: \$20,951.00  
PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 27 Feb 2025  
Minimum PARF Benefit: \$8,299.00  
No. of Transfers: 0  
IU Label No.: 1050704311  
COE No.: 2017022801003695N  
COE Expiry Date: 27 Feb 2025  
COE Category: A - Car (up to 1600cc & 97kW (130bhp))  
COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))



# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

14-Dec-17

## ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1189 D

1 pc	Rear bumper <i>X repair</i>	\$	447.00
1 pc	Rear bumper sponge <i>X</i>	\$	79.20
1 pc	Rear bumper reinforcement <i>X</i>	\$	815.64
1 pc	Rear bumper reinforcement centre <i>X</i>	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20 <i>X</i>	\$	104.40
		\$	1,525.44
	Less 20%	\$	305.09
		\$	1,220.35

### S/NETT

1 set	Rear bumper clips <i>X</i>	\$	48.00
1 set	Reverse sensor <i>X</i>	\$	<del>280.00</del> 200
	Sundry	\$	<del>50.00</del> 20
	To dismantle and replace reverse sensor and test system	\$	<del>80.00</del> 20
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of end panel, etc.	\$	<del>550.00</del> 200
	To putty and spray painting on the rear bumper, end panel <i>X</i>	\$	<del>450.00</del> 180
	To apply rustproofing on the repaired and replaced panels	\$	<del>120.00</del> <i>X</i>
	<b>Total</b>	\$	<u>2,798.35</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

*Kalvin LKK*  
*14/12/17 1605hrs*  
*2 Days*  
*PIP*  
*After Repair photo*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

14-Dec-17

## ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1189 D

1 pc	Rear bumper <i>X repair</i>	\$	447.00
1 pc	Rear bumper sponge <i>X see</i>	\$	79.20
1 pc	Rear bumper reinforcement <i>X see</i>	\$	815.64
1 pc	Rear bumper reinforcement centre <i>X see</i>	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20 <i>X see</i>	\$	104.40
		\$	1,525.44
	Less 20%	\$	305.09
		\$	1,220.35

### S/NETT

1 set	Rear bumper clips <i>X</i> <i>should</i>	\$	48.00
1 set	Reverse sensor <i>X</i>	\$	<del>280.00</del> 200
	Sundry <i>NEC</i>	\$	<del>50.00</del> 20
	To dismantle and replace reverse sensor and test system	\$	<del>80.00</del> 20
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of end panel, etc.	\$	<del>550.00</del> 200
	To putty and spray painting on the rear bumper, end panel <i>X</i>	\$	<del>450.00</del> 180
	To apply rustproofing on the repaired and replaced panels	\$	<del>120.00</del> <i>X</i> 40
	<b>Total</b>	\$	<b>2,798.35</b>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

*Kalvin LK/16*

*14/12/17 1605 hrs*

*2 Days*

*PIP*

*After Repair photo*

*29/12/17*

*confirmed P/P \$620 / 2 Days*

K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary parts must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

## Vic (LKKAUTO)

---

**From:** Gary Shi <gary.shi@premiertaxi.com>  
**Sent:** Tuesday, 11 September, 2018 5:13 PM  
**To:** Vic (LKKAUTO)  
**Cc:** Admin A  
**Subject:** RE: LOD / Accident involving SHD1189S & GBB8278D on 14.12.17 (QBE case) LKK REF CC3/QBE17023836/K1hb3  
**Attachments:** SHD1189S - DV.pdf

WITHOUT PREJUDICE

Dear Vic,

On a without prejudice basis and without admission of liability whatsoever on our client's part and driver of SHD1189S, our client agreed to direct settle the above claims at \$890.00

We enclosed hereby Discharge voucher & ATA for your kind attention, original copies will pass to Mr Calvin.

Kindly let us have your settlement sum of S\$890.00 in our favour – Premier Automotive Services Pte Ltd within 14days from the date hereof.


Please be informed that this settlement excludes any bodily injuries arising out of the above said accident and pertains to property damage only.

Regards

Gary Shi  
Senior Executive, Claims  
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443  
**Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511**  
Visit us at: [www.premiertaxi.com.sg](http://www.premiertaxi.com.sg)

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

---

**From:** Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]  
**Sent:** Tuesday, 11 September, 2018 4:51 PM  
**To:** Gary Shi  
**Cc:** Admin A; Vic (LKKAUTO)  
**Subject:** RE: LOD / Accident involving SHD1189S & GBB8278D on 14.12.17 (QBE case) LKK REF CC3/QBE17023836/K1hb3

Without Prejudice

Dear Gary,

We refer further to our below email.

Purely for an amicable settlement on a without prejudice basis and without admission of any liability to our Insured's part, we have our principal's mandate and we propose a global sum of **\$890.00** (all in) to settle your client's claim.

If agreeable, kindly chop and sign the attached **DV and ATA** then forward back to us a scan copy for payment processing.

Thank you.

*"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."*


Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Vic (LKKAuto)

**Sent:** Tuesday, 21 August, 2018 1:06 PM

**To:** 'Gary Shi'

**Cc:** Admin A; Vic (LKKAuto)

**Subject:** RE: LOD / Accident involving SHD1189S & GBB8278D on 14.12.17 (QBE case) LKK REF CC3/QBE17023836/K1hb3

Without Prejudice

Dear Gary,

We refer to your below email.

Please be informed that till date, we are yet to receive mandate approval from our principal.

We will continue to follow up on the matter.

Thank you.




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/QBE17023836/K1hb3n2		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 17-09-2018		
		Code : QBE		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBB 8278D	Veh. Inspected	SHD 1189S	
Policy No.	8-V0008225-MVA-R0003	Coverage (\$)	0.00	
Claim No.	VC010993	Excess (\$)	0.00	
Assign From		Assign Date	14/12/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI I30	c.c	1582	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	TMAD281UVHJ125043	Colour	SILVER	
Odometer	104481	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MAXXIS	7 mm	
L/H Front Tyre	195/65 R15	MAXXIS	7 mm	
R/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
L/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/12/2017	Inspection Date	14/12/2017	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1189S**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	447.00	-
1	REAR BUMPER SPONGE	SERVICEABLE	79.20	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	815.64	-
1	REAR BUMPER REINFORCEMENT CENTRE	SERVICEABLE	79.20	-
2	REAR BUMPER N/S & O/S SIDE BRACKET @\$52.20	SERVICEABLE	104.40	-
	LESS 20% DISCOUNT		-305.09	-
			1,220.35	-
	<b>SPECIAL NETT ITEMS</b>			
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			378.00	220.00
	<b>LABOUR</b>			
	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM.		80.00	20.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE OF END PANEL,ETC.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		550.00	200.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER,END PANEL.		450.00	180.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,200.00	400.00
	<b>GRAND TOTAL</b>		<b>2,798.35</b>	<b>620.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>620.00</b>

Report Ref No. CC3/QBE17023836/K1hb3n2

**KALVIN ANG WEI KUN**

Automotive Assessor / Investigator

**HO LEONG CHUAN**

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
 No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.