

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7639B

MAKE :

MODEL : HYUNDAI SONATA

Tokio Marine-CL(S) TS

Tyre : Westlake

DATE 15/12/2017

LKK - kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper X Repair			\$ 578.40	
	Rear Bumper Clip X			\$ 22.00	
	Rear Bumper Protector (LH) X Repair			\$ 38.00	
	Tail Lamp (LH) —			\$ 344.00	
	SUB TOTAL			\$ 982.40	
	LESS 20%			\$ 196.48	
	DISCOUNTED TOTAL			\$ 785.92	
	Rear Bumper Rubber Mat —			\$ 50.00	Nett
	Rear Bumper Advertisement Logo —			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) —		\$ 100.00	\$ 200.00	Nett
				\$ 300.00	
	Labour Charge				
	Panel Beating			\$ 350.00 200	
	Spray Painting Charge			\$ 200.00 180	
	Wiring Charge			\$ 50.00 20	
	Remove/Refix Reverse Sensor			\$ 120.00 X	
	TOTAL LABOUR			\$ 720.00	
	ESTIMATE TOTAL			\$ 1,805.92	
Kalvin LKK 15/12/17 1540hrs 2 Days 45 After Repair photo					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before spray painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					