
The state of the s	R 7WLT CC4/EQ11702 2919	2 May LKK
INS. CASE OWNE	ASSIGNMENT (	\ /
· R.	Tantikh DOL ASSIGNMENT	7 18/14/17
Surveyor:		Date / Time:
	1.4 6986	Registered in Merimen:
Pre-assign / CC		
Insured Vehicle	io. : GBF 73727 Claim No	0. 3
Name of Insured	Policy N	10.
Li- U	(I)	AVI X
Insured Tel No.	HP: Make / N	
Excess Sec II :S	D.O.A: LY (121) Place of	Accident :
Is driver the own	7-11 MANAGEMENT NO 11-14 MANAGEMENT NO 11-11-11-11-11-11-11-11-11-11-11-11-11-	
If NO, Driver No	ume / Age : OI GIA I	REPORT: YES / NO ; TP GIA REPORT: YES / NO
Driver Te	No.: (V/L: YES / NO ) Insured I	Liability: % Final? Yes/No
SUT AND	9U .	
100 01 11.11		
INSRS:	INSRS: INSRS	
WSP:	WSP: WSP:	WSP: Tel:
Tel;	Tel: Liability: Liability: Liability:	FI D 2277422
Liability: TC	RMKS RMKS	W 10
HMKS:	RMKS.	1
Date/Time	THE SAME OF THE SA	STAGE DATE/PIC
MINIA	101 177 54 - 4 CBC 1812 4 - X	STAGE DATE/PIC Non-Reporting ltr (1st):
111		Non-Reporting ltr (2nd):
(M)	tropassy will be nithdrawing its and port	Non-Reporting ltr (Final):
	when will be assisting engaged velover excess I pass of use " - tan chong	Notification ltr (if non-pickup):
	excess & page of use. " - " tan chong.	Call OI: After call lir to OI:
	V	Documentation Check List: Handler Typist
satulis	Fr. 30/2 L. Clay Dr. La claye ( )	Notification Itr (if non-pickup)
11/2/36	Fice pass to shu per to close (up)	After call itr to Of:
-		Authorisation To Acc
		Release Voucher
	1	Final Repair Bill:
		Car Rental Invoice:
		Towing Invoice
		LTA / GIA :
		Medical Bill:
		PIR:
		Mandate/Reject Instruction:
		LOD
	F. Date/Time: Min/acc Sent By: Www	Payment Breakdown Form:
LIMINARY ADVIC	E Date/Time: W N Sent By: W	Post-Repair Photos:
4	5 9 Mark	Others:
ALIZATION	Date/Time: Confirm with:	Confirm by:
intr Cost:	55 (days) Reduction: %	
AL SETTLEMENT	Date/Time: Confirm with	f NO or B 28, Ass. Liu:
Liability:	% (Agreed / Assessed) BOLA S/N No.:	II NO of B 24, Ass. Liu:
cir Cost.	SS Anna	Company Active
s of Rental (LOR):	SS ( days) SS (S x days)	1.1.152
of Use (LOU): of Income (LOI):	SS (5 x days) SS (S x days)	W W W
it only LOU on	The second secon	10(
	SS TREE STATE OF THE SALE OF T	
J. T.A. Samerh	SS	1) Claim status: Normal/Reject/Private Settle
		2) Report Format: TV
-lical:	SS (e.g. Tow/ Independent )	
-lical:	SS (e.g. Tow/ Independent ) SS	3) Survey fee: \$ 150.00
rsement:		3) Survey fee: \$ 160.00
rsement:	\$5	
rsement UCost UE AL PAYMENT	S5 S\$ Global Sum S\$:	3) Survey fee: \$ 160.00
A.TA Search	S5 S\$ Global Sum S\$: Date/Time: Confirm with:	3) Survey fee: \$ 160.00

Prime Taxi Office 5, Benoi Place Singapore 629926 Tel: 6898 2000 Fax: 6862 2628 PRIME CAR RENTAL
& TAXI SERVICES PTE LTD



Co. Cert. No: 19-9606293-Z Gst Reg. No: 19-9606293-Z

Email primetaxi@alognet.com so Website : www.primetaxi.com so

Our Ref: SHD2664E

Your Ref: Please advise

7102.11.2017 sted

oT

: Whom It May Concern

From : Prime Car Rental & Taxi Services Pte Ltd

# <u>OUINNSTON</u> RE: LETTER OF CERTIFICATION FOR KHOON SOON TIONG

This letter serves to confirm that Mr. Khoo Soon Tiong Quinnston, Nric Number S7124522E is a Taxi Master for Prime Car Rental & Taxi Services Pte Ltd hiring the Vehicle Registration Number SHD2664E for Singapore Dollar Eighty Two and Cents Ninety (\$82.90) Only.

Should clarification require I can be contacted at 94524182.

Thank you with Best Regards

1

Yours Sincerely

Wr Chan Kong Loong Workshop Manager

Server Paul REF. EQ.	1	
V	ASSIGNMENT	
From Data 18/12	117 Ven No. SLJ93384 Yr Regr	2016 Dec.
Estimated Cost	Type: M.Cas/ M.Cycle / Bus / Van / Lorry / Taxl / F	
OD (TP)WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or	
To Inspect Vehicle No: SJJ 9338	y Make Nissan Dashgan	cc 1197.
at Workshop m/s TC Autoclinic		nsured / Std / NI / NA.
25 Leng Kee Road	Sp. Reading 2691 TiRadio:	nsured / Std / NI / NA
Insured.	Eng-No:	0 - 224 0
Policy No.	CINO: SJNFEAJ	114172555
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt	
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or	
(Client's Record)	Brake Inorder   Jammed / Leaked / Burnt or	
Make of Veh:	Modi: Nil (S/B/m / STD A/Rim or	
· ·	Tyre Size F: 215/64(1)	
(Policy Condition)	R: W/n	5.
Remark: The veh had commenced its	N/S O/S BS / DUN / EXNOVA /GY PS / LIZA / MIC / OHT	SU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or	•
Bal, or Market Value	Ergnt / Rear	
IDAC Accident Rport. Consistent? : Yes or N	No R/Bal. O mm R/Bal.	6
GIA / PR Seen: Consistent? : Yes or M	No LiBal. 6 mm LiBal.	L mm
Est Repairs: 5 days Res.: Yes or	No D.O.A. D.O.I.	18/12/12@ (64)
Lum Sum; % 3 Val.: Yes or	No Survey held at TC	7 6
CA / REV / REP. / 24 HRS Cups	Des. of Damages : Frt. / Rear / O/S / N/S / U/C	/ Rooftop or
Veh	hicle: IN/OUT Put N/S	
Dete: Person Contacted	The U/C / Chassis frame / Body Structure	affected due to collision.
Date / Time Action / Instruction		
Submit	4	
PIP # A111.52 ( Rec	of # 435.44 5771 - excluded of	neck Homs
	# 100.5	1
•		
Data-Time. File Pass 107 : Prelli. Report	Days Of Repair:	
; Final Report	Resurvey No. of Trip: Survey	
Date:Time, File Raturn to 7	Trinspor	
2	Add Fee:   Site Insp (5 ) _ E = 3	3_3
2	Interview IS Proces	
Report Format :	Tech Invs (\$ ) Ones	
Lump Sum / I.B.I: (\$	Waskend (5	
	5074	

Can advise us on the liability and arrange for survey.
Thanks
Auto Wheels Motorworks Pte Ltd Louis Ong 91928963
On Fri, 8 Sep 2017 at 10:27, louisongautowheels@yahoo.com
<li><louisongautowheels@yahoo.com> wrote:</louisongautowheels@yahoo.com></li>
Hi
We would like to do a Direct Settlement with you if our liability is 100%.  Can advise us on the liability and arrange for survey.
Thanks
Auto Wheels Motorworks Pte Ltd
No 1 Bukit Batok Crescent
WCEGA PLAZA #02-40 Louis Ong 91928963
IMPORTANT NOTICE: The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ I	NSURANCE COM	PANY LTD	Ref :	CC4/EQI17023	919/T1pb3		
#17-	XXWELL ROAD 00 TOWER BLOC COMPLEXSING			18-12-2017			
			Code:	The same of the sa			
1.			Veh. Inspected SLJ 9338Y				
	Insured Veh.	GBF 2322Z	121-130000		0.00		
	Policy No.			age (\$)	0.00		
	Claim No.		Exces		18/12/2017		
	Assign From			n Date	10/12/2011		
2.		Vehicle Part	_	Condition	0		
	Make & Model	702220	c.c		0		
	Engine No.	HIDDEN	Year of Reg.				
	Chassis No.		Colour				
	Odometer	•	Steering				
	Brakes		Modification				
	General			Harris I i			
3.			tions of	Tyres			
		Size	Make		Balance		
	R/H Front Tyre				mm		
	L/H Front Tyre			14	mm		
	R/H Rear Tyre				mm		
	L/H Rear Tyre			75	mm		
4.		Descrip	tion of Da	amages			
5.		Gener	ral Inform	nation			
	Accident Date	14/12/2017	Inspe	ction Date	18/12/2017		
	Survey held at	TC AUTOCLINIC PTE LTD		1			
	1000 - 10	25 LENG KEE RD SINGAPORE 159097					
5a.			Remarks	k .			

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref:

To Be Advised

Our ref:

CC4/EQI17023919/T1pb3

Date:

19.12.2017

The Motor Claims Department M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

# PRELIMINARY ADVICE OF VEHICLE NO.

SLJ9338Y

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18.12.2017 at the premises of M/s TC AutoClinic Pte Ltd and have the following to report:-

Workshop Estimate Amount	: SS	8,426.96
Revised Estimate Amount	: SS	4,111.52
"Check" Items Amount	: S\$	1,120.88
Market Value	: S\$	
LTA Reimbursement Value	: S\$	7
Nett Value	: S\$	

Description of Damage:

The vehicle sustained damages at the

Front N/S Portion

rearraide front

Comments/Present Status:

Damages Consistent

Estimated normal period for repairs:

5-6

days

Yours faithfully,

MOHD. TAUFIKH

Licensed Appraiser

	1.00
Was there any video captured by Car Camera?	ON
Are accident photos available for attachment?	YES
Attachment(s)	
I WAS DRIVING ALONG SENTOSA CASINO DRIV IMPACT AT THE RIGHT SIDE OF MY TAXI, A VEH ONTO THE RIGHT PORTION OF MY TAXI.	
Circumstances of Accident	
Yes, against whom?	
Was notice of intended Prosecution given?	ON
If Yes. Please state which Police Station	
Was the accident reported to the police?	ON
Details of Police Action	
Number of Passengers (Including Driver)	2
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	ON
Was any other material or property damaged?	AES
Was any body injured in the Accident?	ON
Was any foreign vehicle involved in this accident?	ON
Other Information	
Road Surface	DRY
Weather Conditions	CLEAR
Type Of Accident	SIDE SMIBE
General Information of the Accident	
insurance Company of Driver's Own Vehicle	:
Vehicle	
Vehicle Registration Number of Driver's Own	
If No. Relationship of the Driver with the Insured	OTHER - RELIEF
Was driver an employee of the Insured's Company	ON
Poetcode	
Address	
2 *	

SSENGER ON BOARD, SUDDENLY I FELT AN

E OUT FROM CARPARK DRIVEWAY AND COLLIDED

ON Was there any audio recorded?

Vehicle Registration Number SKZZZ48U DETAILS OF OTHER VEHICLE PROPERTY 1

Phone Number этым Details of Witness No. Of Passenger (Including Driver) Vature Of Damage

Email Address

Insurance Company Name

Details Of Properties

NNKNOMN

Contact Number

Address

Postcode

NRIC/Passport Number

Name of Driver

Vehicle Make/Model/Colour

TC AUTOCLINIC PTE LTD 25 LENG KEE ROAD SINGAPORE 159097

ESTIMATE

: ACCIDENT/BODY REPAIRS

WORKSHOP

: LENG KEE

CONTACT NO

: 67038511

REFERENCE

: 234/1C/TCAC/CCR/2017

DATE

: 14-DEC-2017

EQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD

#17-00 TOWER BLOCK

MND COMPLEX S(069110)

TEL : 62239433

FAX : 62234190

ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME

: MISS CHAN LI-MEL, KAREN

ADDRESS

: 477 RIVER VALLEY ROAD

#03-02

5(248362)

TELEPHONE NO : 91278832

TYPE OF CLAIM : THIRD PARTY CLAIM

POLICY NO

: 2100495035-00000

VEHICLE NO

: SLJ9338Y

MODEL COBE

: FRLARBZJ11UEA--A--

MODEL/YEAR

: NISSAN QASHQAI 1.2

ENGINE NO

: HRA2309715A

CHASSIS NO

: SJNFEAJ1101723337

MILEAGE

: 3691 KM

DATE IN

: 14/12/2017

LIABILITY

0.00

EXCESS CLAUSE :

0.00

ESTIMATE BY

: SHAWN CHUA CHU RONG

ACCIDENT DATE : 14/12/2017

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed.
- . Supplementary item(s) must be resummed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

18/12/17 C/645 Resum before part 5-6 days. Sur C/Mandocom.

After government

#### ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REEN NO SLJ9338Y

S/NO	JOB CODE	NATURE OF JOB		SURVEYOR'S RECOMMENDATION
1	CONI	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	/
2	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	/
3		PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	240.00	120.
4	SEALT	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	200.00	/
5	WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	X
6	22/001	RENEW FRONT BUMPER, LEFT HEADLAMP, HODO, LEFT FENDER, TRIM, LEFT FOG LAMP & COVER ETC PANELS & REPAIR.		1170.
7	22/002	RESPRAY FRONT BUMPER, HODD, LEFT FENDER, LEFT DOOR ETC	1500.00	750.
8	22/003	QC, RETUNE & CONSULT CHECK		
9	ZZ/004	WASH & VACUUM, POLISH & WAX, SHINE ALL TYRES	130.00	×
		TOTAL LABOUR CHARGES	4938.00	

7 . 1

### MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SL19338Y

	DAMAGED	PART	SA	PR	ICES
--	---------	------	----	----	------

s/No	PARTS DESCRIPTION	PARTS NUMBER	NETT		S/NETT	
1	H000	F5100+4EAAA	951.40 6	2%		
2	LEFT FENDER TRIM	63811-4EADA	483.00 ?			
3	LEFT FENDER PROTECTOR	53843-4EADA	87.50 d	e-		
4	FRONT LEFT FENDER	F3101-4EAMB	622.70 6	-		
5	ENERGY ABSORBER	62090-4EA18	195.70 ?			
5	LOWER ARMATURE	62030-4EJ1A	337.70 7			
7	LEFT ENERGY ABSORBER	62090-4EADC	62.20 ?			
8	LEFT BUMPER BRACKET	62223-4EA0A	20.90 🗚	*		
9	FRONT BUMPER	62022-4EA0H	614.60 d	4/		
10	TOW HOCK COVER	622AG-4EAGA	19.30 ✓	My		
11	LEFT FOG LAMP COVER	62257-4EA0C	74.70 C	X-		
12	LEFT FOG LAMP	25150-89928			258.00	?
13	LEFT HEADLAMP	25060-4EA0A	559.00 C	t-		12.
	SUB TOTAL		4038.70	0.00	258.00	
	LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S	/NETT00%)	B07.74		0.00	
	GRAND TOTAL		3230.96	0.00	258.00	
	OVERALL TOTAL		3488.96		********	

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

	, m - E

TO AUTOCLINIC PTE LTD 25 LENG KEE ROAD SINGAPORE 159097

#### SUMMARY OF ESTIMATE FOR VEHICLE REEN NO SLIPBING

TOTAL LABOUR CHARGES 4938.00 TOTAL SPARE PARTS CHARGES 3488.95

\*\*\*\*

-----

GRAND TOTAL

8425.96 \*

\* All charges do2 not include 65%.

#### SURVEYOR'S PARTICULARS

NAME

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

0.00

REMARKS

21

PLS NOTE: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

# Nivitha (LKK Auto)

From:

Shu Pei (LKKAuto) <shupei@lkkauto.com>

Sent:

Friday, 15 December, 2017 2:20 PM

To:

assignments

Subject:

FW: Accident Involving SLJ9338Y & GBF2322Z On 14/12/17

Attachments:

SLI9338Y GIA Report.pdf; Front Accident Footage Between SLI9338Y & GBF2332Z

(online-video-cutter....mp4; Estimate Before Survey.pdf

2.25pm @15/12/2017 Vehicle In Person @ shawn Amonge on 18/12/17

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: <u>shupei@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]

Sent: Friday, 15 December, 2017 2:17 PM

To: Shawn Chua / TCAC <shawnchua@tanchong.com>; Admin A <admin-a@lkkauto.com>

Cc: Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>

Subject: RE: Accident Involving SLI9338Y & GBF2322Z On 14/12/17

# Without Prejudice Save As To Costs

Dear Shawn.

Our insured has yet to report.

Aside to Catherine,

Please arrange to attend to the PRS. We shall follow up with insured and revert on liability soonest possible.

Regards,


#### Janet Tan

Senior Executive | Claims



**EQ Insurance Company Limited** 

5 Maxwell Road #17-00 Tower Block MND Complex Singapore D69110 did 65 6496 9032 | tel 65 6223 9433 est 032 | fax 65 6223 4190 www.eginsurance.com.sg



you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

		Total .

From: Shawn Chua / TCAC [mailto:shawnchua@tanchong.com]

Sent: Friday, December 15, 2017 2:07 PM

To: Bazlin Ahmad <bazlin.ahmad@eginsurance.com.sg>

Cc: Janet Tan < janet.tan@eqinsurance.com.sg>; Elaine Cheong < elaine.cheong@eqinsurance.com.sg>

Subject: Re: Accident Involving SLJ9338Y & GBF2322Z On 14/12/17

Good afternoon.

Can I appoint LKK Auto Consultants Pte Ltd as the motor surveyor?

On Fri, Dec 15, 2017 at 1:29 PM, Bazlin Ahmad <a href="mailto:bazlin.ahmad@eqinsurance.com.sg">bazlin.ahmad@eqinsurance.com.sg</a> wrote:

#### Without Prejudice

Dear Sir,

We refer to your Notice of Accident of even date.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please <u>revert within 2 working days</u> if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

AJAX Inspection Services     Pte Ltd	Automobile Inspection     Services Pte Ltd
Tel: 6255 0808	Tel: 6286 0155
Fax: 6849 9155	Fax: 6284 1539
Contact person : Joey/Joseh	Contact Person: Sophia
3) LBS Automotive	4) Priority Services
Appraisal Pte Ltd  L.B.S. Auto Consultants Pte	Tel: 62934822
Ltd	Fax: 62963283
Tel: 6281 6690 / 62832866	
Fax: 6281 8748	Contact Person: Sharon Kho
Contact Person: Amy/ Grace	
5) RT Appraisal Pte Ltd	6) LKK Auto Consultants Pte Ltd
Tel: 67486076	
Fax: 67480361	Tel: 6256-3561
Contact Person: Ricky Teng	Fax: 6741-4108



# 7) Kelvin Automotive Appraising Services

Tel: 81825263

Fax: 67461148

Contact Person: Kelvin

# 8) Automotive Appraiser & Surveying Services

Tel: 96623655

Fax: 67655662

Contact Person: Mr Chee

# 9) JP Knights Pte Ltd

Tel: 63450068

Fax: 63445328

Contact Person: Edna Lee

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Thank You.

Regards,

#### Lynn Ahmad

Executive | Claims



**EQ Insurance Company Limited** 

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190 www.eqinsurance.com.sg





			1.5

"Avileged/Confidential information may be contained in this message	If you are not the intended recipient, please notify the sender immediately and delete all copies
---	---

From: Shawn Chua / TCAC [mailto:shawnchua@tanchong.com]

Sent: Friday, December 15, 2017 11:30 AM

To: Janet Tan; Bazlin Ahmad; Elaine Cheong; Kelvin Heng / TC AUTO CLINIC

Subject: Accident Involving SLJ9338Y & GBF2322Z On 14/12/17

Dear Sir/Madam.

Our customer holds your insured driver, GBF2322Z liable for the accident on 14/12/17 and would like to claim against your insured driver. We hereby inquire whether you would like to have a direct settlement with our customer, SLJ9338Y.

If you minded to reach an amicable direct settlement with our customer, please let us have your substantive reply strictly by 14/12/17. Otherwise our customer will proceed in a manner that he deems fit.

Please arrange for an accident survey as my claimant had left her vehicle at TC AutoClinic Pte Ltd 25 Leng Kee Rd S159097.

Attached herewith the GIA Report and estimate of repair cost for SLJ9338Y.

Regards,

Shawn Chua

Service Executive

TC AutoClinic Pte Ltd

25 Leng Kee Road

Singapore 159097

DID: ±65 67038515

HP: +65 96450023

Fax: +65 64795019



# Regards,

Shawn Chua Service Executive TC AutoClinic Pte Ltd 25 Leng Kee Road Singapore 159097 DID: +65 67038515 HP: +65 96450023

Fax: +65 64795019



		100

# Shu Pei (LKKAuto)

From:

Shawn Chua / TCAC <shawnchua@tanchong.com>

Sent:

Tuesday, 26 December, 2017 6:20 PM

To:

Janet Tan

Cc:

Admin A; Bazlin Ahmad

Subject:

Re: Accident Involving SLJ9338Y & GBF2322Z On 14/12/17

EQ Insured: GBF2322Z Our Claimant: SLJ9338Y

Good evening.

SLJ9338Y will be withdrawing its 3rd party claim against your insured, GBF2322Z.

We will be assisting SLJ9338Y to recover her excess & loss of use etc later on.

On Fri, Dec 15, 2017 at 2:16 PM, Janet Tan < janet.tan@eqinsurance.com.sg > wrote:

### Without Prejudice

#### Save As To Costs

Dear Shawn,

Our insured has yet to report.

Aside to Catherine,

Please arrange to attend to the PRS. We shall follow up with insured and revert on liability soonest possible.

Regards,

Janet Tan

Senior Executive | Claims



**EQ Insurance Company Limited** 

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 059110 did 65 6496 9032 | 1el 65 6223 9433 ext 032 | fax 65 6223 4190

			¥







Provinged/Confidential information may be contained in this message. If you are not the intended recipient, piease notify the sender immediately and delete all copies of it.

From: Shawn Chua / TCAC [mailto:shawnchua@tanchong.com]

Sent: Friday, December 15, 2017 2:07 PM

To: Bazlin Ahmad <bazlin.ahmad@eginsurance.com.sg>

Cc: Janet Tan < ianet.tan@eqinsurance.com.sg >; Elaine Cheong < elaine.cheong@eqinsurance.com.sg >

Subject: Re: Accident Involving SLJ9338Y & GBF2322Z On 14/12/17

Good afternoon.

Can I appoint LKK Auto Consultants Pte Ltd as the motor surveyor?

On Fri, Dec 15, 2017 at 1:29 PM, Bazlin Ahmad < bazlin.ahmad@eqinsurance.com.sg > wrote:

#### Without Prejudice

Dear Sir,

We refer to your Notice of Accident of even date.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please <u>revert within 2 working days</u> if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

# 1) AJAX Inspection Services Pte Ltd

Tel: 6255 0808

# 2) Automobile Inspection Services Pte Ltd

Tel: 6286 0155

Fax: 6849 9155	Fax: 6284 1539
Contact person : Joey/Joseh	Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd  L.B.S. Auto Consultants Pte Ltd  Tel: 6281 6690 / 62832866	4) Priority Services  Tel: 62934822  Fax: 62963283  Contact Person: Sharon Kho
Fax: 6281 8748  Contact Person: Amy/ Grace	6) LKK Auto Consultants Pte
5) RT Appraisal Pte Ltd  Tel: 67486076  Fax: 67480361	6) LKK Auto Consultants Pte Ltd  Tel: 6256-3561  Fax: 6741-4108
7) Kelvin Automotive Appraising Services	8) Automotive Appraiser & Surveying Services
Tel: 81825263	Tel: 96623655
Fax: 67461148	Fax: 67655662
Contact Person: Kelvin	Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	<b>†</b> +
Contact Person: Edna Lee	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

			2

Thank You.

Regards,

#### Lynn Ahmad

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Soad #17-00 Tower Block MND Complex Singapore 069110 did 55 6496 9851 | tel 65 6225 9453 ext 851 | fax 65 6223 4190 www.edimurance.com.56



Provinged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copie.

you've got a friend

From: Shawn Chua / TCAC [mailto:shawnchua@tanchong.com]

Sent: Friday, December 15, 2017 11:30 AM

To: Janet Tan; Bazlin Ahmad; Elaine Cheong; Kelvin Heng / TC AUTO CLINIC

Subject: Accident Involving SLJ9338Y & GBF2322Z On 14/12/17

Dear Sir/Madam,

Our customer holds your insured driver, GBF2322Z liable for the accident on 14/12/17 and would like to claim against your insured driver. We hereby inquire whether you would like to have a direct settlement with our customer, SLJ9338Y.

If you minded to reach an amicable direct settlement with our customer, please let us have your substantive reply strictly by 14/12/17. Otherwise our customer will proceed in a manner that he deems fit.

Please arrange for an accident survey as my claimant had left her vehicle at TC AutoClinic Pte Ltd 25 Leng Kee Rd S159097.

		es Sast

Attached herewith the GIA Report and estimate of repair cost for SLJ9338Y.

Regards,

Shawn Chua

Service Executive

TC AutoClinic Pte Ltd

25 Leng Kee Road

Singapore 159097

DID: +65 67038515

HP: +65 96450023

Fax: +65 64795019



Regards,

Shawn Chua

Service Executive

TC AutoClinic Pte Ltd

25 Leng Kee Road

Singapore 159097

				.*

DID: +65 67038515

HP: +65 96450023

Fax: +65 64795019



# Regards,

Shawn Chua Service Executive TC AutoClinic Pte Ltd 25 Leng Kee Road Singapore 159097 DID: +65 67038515 HP: +65 96450023 Fax: +65 64795019

×

			181	

# Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Wednesday, 27 December, 2017 11:11 AM

To:

'janet.tan@eqinsurance.com.sg'

Cc:

Admin A; 'bazlin.ahmad@eqinsurance.com.sg'

Subject:

RE: Accident Involving SLJ9338Y & GBF2322Z On 14/12/17 \*LKK

REF:CC4/EQI17023919/T1pb3

Your Ref: GBF2322Z

LKK REF:CC4/EQ117023919/T1pb3

Hi Janet.

Further to the below email from third party repairer.

We will proceed to close file and submit our wp report to your good office.

Thank you.

"Wishes you a Merry Christmas & Happy New Year 2018"

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <a href="mailto:chewht@lkkauto.com">chewht@lkkauto.com</a> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shawn Chua / TCAC [mailto:shawnchua@tanchong.com]

Sent: Tuesday, 26 December, 2017 6:20 PM
To: Janet Tan < janet.tan@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>

Subject: Re: Accident Involving SLJ9338Y & GBF2322Z On 14/12/17

EQ Insured: GBF2322Z Our Claimant: SLJ9338Y

Good evening.

SLJ9338Y will be withdrawing its 3rd party claim against your insured, GBF2322Z.

We will be assisting SLJ9338Y to recover her excess & loss of use etc later on.

On Fri, Dec 15, 2017 at 2:16 PM, Janet Tan < janet.tan@eqinsurance.com.sg > wrote:

# Without Prejudice

### Save As To Costs

Dear Shawn,		
Our insured has yet to report.		
Aside to Catherine,		
Please arrange to attend to the PRS. We shall follow up wi	th insured and revert on liabilit	y soonest possible.
Regards,		
Janet Tan Senior Executive   Claims		
EQ Insurance Company Limited  5 Minawell Road J117-00 Tower Block MHD Complex Singapore 069110 did 65 6496 9032   tel 65 6223 9433 ext 032   fax 65 6223 4190		
www.eqinanaoce.com.sg	9.	
A Momber of Citystate  Privileged/Confidential information may be contained in this message. If you are n	of the intended recipient, please postile the	you've got a friend
From: Shawn Chua / TCAC [mailto:shawnchua@tanchong.co Sent: Friday, December 15, 2017 2:07 PM To: Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg> Cc: Janet Tan &lt;<a href="mailto:janet.tan@eqinsurance.com.sg">janet.tan@eqinsurance.com.sg</a>&gt;; Elaine Cheo Subject: Re: Accident Involving SLJ9338Y &amp; GBF2322Z On 14</bazlin.ahmad@eqinsurance.com.sg>	om] ong <elaine.cheong@eginsuran< th=""><th></th></elaine.cheong@eginsuran<>	
Good afternoon.		

Can I appoint LKK Auto Consultants Pte Ltd as the motor surveyor?

On Fri, Dec 15, 2017 at 1:29 PM, Bazlin Ahmad < bazlin.ahmad@eqinsurance.com.sg > wrote:

# Without Prejudice

Dear Sir,

We refer to your Notice of Accident of even date.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please <u>revert within 2 working days</u> if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

l) AJAX Inspection Services Pte Ltd	2) Automobile Inspection Services Pte Ltd		
Tel: 6255 0808	Tel: 6286 0155		
Fax: 6849 9155	Fax: 6284 1539		
Contact person : Joey/Joseh	Contact Person: Sophia		
LBS Automotive     Appraisal Pte Ltd	4) Priority Services Tel: 62934822		
L.B.S. Auto Consultants Pte Ltd	Fax: 62963283  Contact Person: Sharon Kho		
Tel: 6281 6690 / 62832866 Fax: 6281 8748			
Contact Person: Amy/ Grace	San authorite Pte		
5) RT Appraisal Pte Ltd	LKK Auto Consultants Pte     Ltd		
Tel: 67486076 Fax: 67480361	Tel: 6256-3561		
Contact Person: Ricky Teng	Fax: 6741-4108		
7) Kelvin Automotive Appraising Services	Automotive Appraiser & Surveying Services		
Tel: 81825263	Tel: 96623655		
Fax: 67461148	Fax: 67655662		
Contact Person: Kelvin	Contact Person: Mr Chee		

# 9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328 Contact Person: Edna Lee

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Thank You.

Regards,

#### Lynn Ahmad

Executive | Claims



**EQ Insurance Company Limited** 

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9831 | tel 65 6223 9433 ext 881 | fax 65 6223 4190 www.eginsurance.com.se



you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copie

From: Shawn Chua / TCAC [mailto:shawnchua@tanchong.com]

Sent: Friday, December 15, 2017 11:30 AM

To: Janet Tan; Bazlin Ahmad; Elaine Cheong; Kelvin Heng / TC AUTO CLINIC

Subject: Accident Involving SLJ9338Y & GBF2322Z On 14/12/17

Dear Sir/Madam,

Our customer holds your insured driver, GBF2322Z liable for the accident on 14/12/17 and would like to claim against your insured driver. We hereby inquire whether you would like to have a direct settlement with our customer, SLJ9338Y.

If you minded to reach an amicable direct settlement with our customer, please let us have your substantive reply strictly by 14/12/17. Otherwise our customer will proceed in a manner that he deems fit.

Please arrange for an accident survey as my claimant had left her vehicle at TC AutoClinic Pte Ltd 25 Leng Kee Rd S159097.

Attached herewith the GIA Report and estimate of repair cost for SLJ9338Y.

Regards,

Shawn Chua

Service Executive

TC AutoClinic Pte Ltd

25 Leng Kee Road

Singapore 159097

DID: +65 67038515

HP: +65 96450023

Fax: +65 64795019



	5%	

Regards,

Shawn Chua

Service Executive

TC AutoClinic Pte Ltd

25 Leng Kee Road

Singapore 159097

DID: +65 67038515

HP: +65 96450023

Fax: +65 64795019



Regards,

Shawn Chua Service Executive TC AutoClinic Pte Ltd 25 Leng Kee Road Singapore 159097 DID: +65 67038515 HP: +65 96450023

HP: +65 96450023 Fax: +65 64795019





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En A	Automobile
--	------------

EQ INSURANCE COMPANY LTD

ESTIMATED NORMAL PERIOD FOR REPAIR:

Ref: CC4/EQI17023919/T1pb3q2

5 MAXWELL ROAD

6 Working Days

	Date: 08-01-2018 Code: EQI	
Policy Particul	ars :- THIRD PARTY CLAI	M
GBF 2322Z	Veh. Inspected	SLJ 9338Y
	Coverage (\$)	0.00
	Excess (\$)	0.00
JANET	Assign Date	18/12/2017
Vehicle P	articulars & Condition	
NISSAN QASHQAI	c.c	1197
HIDDEN	Year of Reg.	2016
SJNFEAJ11U1723337	Colour	SILVER
3691	Steering	IN ORDER
IN ORDER	Modification	SPORTS RIM
GOOD		
Cor	nditions of Tyres	rt 567- F
Size	Make	Balance
215/60 R17	GOODYEAR	6 mm
215/60 R17	GOODYEAR	6 mm
215/60 R17	GOODYEAR	6 mm
215/60 R17	GOODYEAR	6 mm
Descr	ription of Damages	
	FRONT N/S PORTION.	
Ger	neral Information	
14/12/2017	Inspection Date	18/12/2017
TC AUTOCLINIC PTE LTD		
25 LENG KEE RD SINGAPORE 159097		
	Remarks	
ON WAS CONDUCTED ON A ICE TO YOUR INSTRUCTION	"WITHOUT PREJUDICE" BAS S, WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.
Estim	nate Days of Repair	
	JANET  Vehicle P  NISSAN QASHQAI  HIDDEN  SJNFEAJ11U1723337  3691  IN ORDER  GOOD  Cor  Size  215/60 R17  215/60 R17  215/60 R17  215/60 R17  Descr  USTAINED DAMAGES AT THE  DETAILS.  Ger  14/12/2017  TC AUTOCLINIC PTE LTD  25 LENG KEE RD  SINGAPORE 159097  ION WAS CONDUCTED ON ANCE TO YOUR INSTRUCTION	Policy Particulars :- THIRD PARTY CLAI  GBF 2322Z



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 9338Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HOOD (N)	TO REPAIR SEE LABOUR	961.40	8
1	LEFT FENDER TRIM (N)	* CHECK	483.00	
1	LEFT FENDER PROTECTOR (N)	DEFORMED	87.50	87.50
1	FRONT LEFT FENDER (N)	BENT	622.70	622.70
1	ENERGY ABSORBER (N)	* CHECK	195.70	
1	LOWER ARMATURE (N)	* CHECK	337.70	
1	LEFT ENERGY ABSORBER (N)	* CHECK	62.20	
1	LEFT BUMPER BRACKET (N)	NECESSARY	20.90	20.90
1	FRONT BUMPER (N)	DEFORMED	614.60	614.60
1	TOW HOOK COVER (N)	NOT NECESSARY	19.30	
1	LEFT FOG LAMP COVER (N)	CUT	74.70	74.70
1	LEFT HEADLAMP (N)	CUT	559.00	559.00
	LESS 20% DISCOUNT		-807.74	-395.88
			3,230.96	1,583.52
	SPECIAL NETT ITEMS			
1	LEFT FOG LAMP (SN)	· CHECK	258.00	
			258.00	
	LABOUR			
	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT.		240.00	240.00
	FOCUS & ADJUST H/LAMP , RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION.		48.00	48.00
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.		240.00	120.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA		200.00	200.00
	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/SHORT CIRCUIT , REPAIR WHEN NECESSARY.	NOT NECESSARY	240.00	
	RENEW FRONT BUMPER ,LEFT HEADLAMP ,HOOD ,LEFT FENDER ,TRIM ,LEFT FOG LAMP & COVER ETC PANELS & REPAIR INCLUSIVE OF THE REPAIR OF HOOD.		2,340.00	1,170.00

Report Ref No. CC4/EQI17023919/T1pb3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	RESPRAY FRONT BUMPER, HOOD, LEFT FENDER, LEFT DOOR ETC. WASH & VACUUM, POLISH & WAX, SHINE ALL TYRES.	NOT NECESSARY	1,500.00	III SOVEN
		NOT HESESSIAIT	4,938.00	
	GRAND TOTAL		8,426.96	4,111.52

RECOMMENDED COST OF REPAIRS	4,111.52
(REPAIR COST NOT CONCLUDE)	
(EXCLUDE CHECK ITEMS S\$1,120.88 NETT)	

Report Ref No. CC4/EQI17023919/T1pb3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.