

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WA006 / AXA INSURANCE
 Chassis No: JHMF4520AS200126
 License No: SCK3459Y
 Mileage: 100291
 Engine No: R16A15000188

Document No: SVO17079144
 Printed By: FSCHUI
 Order Date: 19. December 2017
 Order Time: 6:02:04 PM
 Service Advisor: STEVEN CHUI FOOK SENG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO:P1362432 OWNER:HENG SIEW HWEE ACC DATE:13/12/2017 SURVEYED BY:MARCUS (LKK) DATE:19/12/2017 AUTHORIZED ON :19/12/2017 REF NO : CAS201712182331008						
54206	EXTERNAL LABOUR SALES - INS. EXCESS	-1	250.00		-250.00	-17.50	-267.50
	SUM EXCESS:				-250.00	-17.50	-267.50
73371-SNA-A01	GLASS L FR CORNER	1	152.80	35	99.32	6.95	106.27
73375-SNA-003	GARNISHL.FR.	1	39.50	35	25.67	1.80	27.47
73334-SFA-000	CLIPFR.CORNER	2	2.90	35	3.77	0.26	4.03
73332-SNA-A00	RUBBER A W/SHIELD DAM	1	4.90	35	3.18	0.22	3.40
60261-SNB-000ZZ	PANEL L FR FENDER	1	450.80	35	293.02	20.51	313.53
74151-SNA-A00	FENDERL.FR.INNER	1	99.30	35	64.54	4.52	69.06
74207-SNA-A01	GARNISHL.FR.FENDER	1	28.00	35	18.20	1.27	19.47
74155-SNA-A00	ENCLOSUREL FR FENDER	1	17.80	35	11.57	0.81	12.38
04711-SNB-E50ZZ	FACEFR.BUMPER	1	638.00	35	414.70	29.03	443.73
71190-SNB-000	BEAML FR BUMPER	1	30.50	35	19.82	1.39	21.21
71198-SNB-003	SPACERL FR BUMPER SIDE	1	12.80	35	8.32	0.58	8.90
91505-S9A-003	CLIP ABUMPER	10	3.90	35	25.35	1.77	27.12
51602-SNA-S02	ABSORBERL.FR.SHOCK.	1	489.30	35	318.04	22.26	340.30
33151-SNB-T51	HEADLIGHT UNITL.	1	790.40	35	513.76	35.96	549.72
34301-SNW-003	LAMP UNIT	1	17.30	35	11.24	0.79	12.03
44300-SNA-952	BEARING FR HUB	1	111.10	35	72.21	5.05	77.26
51360-SNA-903	ARML FR LOWER	1	222.40	35	144.56	10.12	154.68
51216-SNA-010	KNUCKLE L FR	1	247.10	35	160.81	11.24	171.85
51230-SNA-A03	JOINTL.FR.LOWER BALL	1	101.70	35	66.10	4.63	70.73
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
53610-SNB-J01	END RACK	1	76.30	35	49.59	3.47	53.06
53560-SNA-A02	END COMPTIE ROD	1	79.10	35	51.41	3.60	55.01
53449-S84-A01	BANDBELLOW	1	6.20	35	4.03	0.28	4.31
	SUM PARTS:				2,439.01	170.71	2,609.72
BOSUN	0626	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML01I	EXT-YJ	1	60.00		60.00	4.20	64.20
	INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)						
BOBC		1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BP06R	EXT-YBH	1	1,125.00		1,125.00	78.75	1,203.75
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)						
BOMISC1	EXT-YJ	1	1,750.00		1,750.00	122.50	1,872.50
	TO RENEW LHF FENDER & DOOR,BONNET, BUMPERRHF FENDE						